

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
18 SIN MING LANE #01-08 MIDVIEW CITY  
SINGAPORE 573960

Contact : 66550005-GRAB 88159245

TP 1st Cap  
Khanchan

## ESTIMATE

Repair Code : CLM16017

Date in : 31/01/2020

Vehicle Num. : SLE965Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104554426/1ZRX585870

### Parts and Labour Assesment

| Description of part                         | Qty | Unit Price | Amount       |
|---------------------------------------------|-----|------------|--------------|
| AIRCON CONDENSER <i>Replaced</i>            | 1   | 1289.00    | ✓ 1,289.00   |
| FRONT BONNET <i>Repair</i>                  | 1   | 1140.40    | ✗ 1,140.40   |
| FRONT BONNET HINGES L/R <i>New</i>          | 2   | 135.10     | ✗ 270.20     |
| FRONT BONNET MECHANISM LOCK <i>Replaced</i> | 1   | 271.85     | 135 ✓ 271.85 |
| FRONT BONNET TOP RUBBER MOULDING <i>New</i> | 1   | 40.00      | ✗ 40.00      |
| FRONT BRACE PANEL <i>Best</i>               | 1   | 182.10     | ✓ 182.10     |
| FRONT BUMPER <i>Replaced</i>                | 1   | 581.45     | ✓ 581.45     |
| FRONT BUMPER LOWER GRILLE <i>Replaced</i>   | 1   | 191.40     | ✓ 191.40     |
| FRONT BUMPER REINFORCEMENT <i>Best</i>      | 1   | 374.45     | ✓ 374.45     |
| FRONT BUMPER SIDE RETAINER L/R <i>New</i>   | 2   | 132.10     | ✓ 264.20     |
| FRONT BUMPER SPONGE <i>Replaced</i>         | 1   | 186.10     | ✓ 186.10     |
| FRONT GRILLE <i>Replaced</i>                | 1   | 595.90     | ✓ 595.90     |
| FRONT GRILLE 'LOGO' EMBLEM <i>New</i>       | 1   | 65.45      | ✓ 65.45      |
| FRONT GRILLE TOP GARNISH <i>Replaced</i>    | 1   | 92.00      | ✓ 92.00      |
| FRONT GRILLE TOP RUBBER MOULDING <i>New</i> | 1   | 181.90     | ✗ 181.90     |
| FRONT HEADLAMP L/R <i>Replaced</i>          | 2   | 850.00     | ✓ 1,700.00   |
| FRONT HEADLAMP LOWER BRACKET L/R <i>New</i> | 2   | 132.10     | ✗ 264.20     |
| FRONT SUPPORT PANEL <i>Repair</i>           | 1   | 2121.40    | ✗ 2,121.40   |

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005-GRAB 88159245

## ESTIMATE

Repair Code : CLM16017

Date in : 31/01/2020

Vehicle Num. : SLE965Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104554426/1ZRX585870

|                                                             |   |        |   |        |
|-------------------------------------------------------------|---|--------|---|--------|
| RADIATOR TOP BRACKET <i>could</i>                           | 1 | 174.40 | ✓ | 174.40 |
| REAR BOO TLID REFLECTOR L/R <i>new</i>                      | 2 | 374.45 | + | 748.90 |
| REAR BOOTLID <i>Buckled</i>                                 | 1 | 781.10 | ✓ | 781.10 |
| REAR BOOTLID 'ALTIS' EMBLEM                                 | 1 | 54.10  | ✓ | 54.10  |
| REAR BOOTLID 'COROLLA' EMBLEM <i>new</i>                    | 1 | 50.20  | ✓ | 50.20  |
| REAR BOOTLID 'LOGO' EMBLEM                                  | 1 | 58.50  | ✓ | 58.50  |
| REAR BOOTLID HINGES L/R <i>new</i>                          | 2 | 79.60  | + | 159.20 |
| REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i> | 2 | 17.00  | + | 34.00  |
| REAR BOOTLID INNER TRIM BOARD <i>new</i>                    | 1 | 181.85 | + | 181.85 |
| REAR BOOTLID LOCK STRIKER <i>new</i>                        | 1 | 85.00  | + | 85.00  |
| REAR BOOTLID MECHANISM LOCK <i>Damaged</i>                  | 1 | 379.20 | ✓ | 379.20 |
| REAR BOOTLID WEATHER STRIP <i>at</i>                        | 1 | 271.45 | ✓ | 271.45 |
| REAR BUMPER <i>delid</i>                                    | 1 | 581.90 | ✓ | 581.90 |
| REAR BUMPER REFLECTOR L/R <i>could</i>                      | 2 | 141.45 | ✓ | 282.90 |
| REAR BUMPER REINFORCEMENT <i>Dent Bent</i>                  | 1 | 398.70 | ✓ | 398.70 |
| REAR BUMPER REINFORCEMENT BRACKET L/R <i>Bent</i>           | 2 | 165.00 | ✓ | 330.00 |
| REAR BUMPER REVERSE SENSOR <i>Damaged</i>                   | 2 | 265.30 | ✓ | 530.60 |
| REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>                | 2 | 121.10 | + | 242.20 |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
18 SIN MING LANE #01-08 MIDVIEW CITY  
SINGAPORE 573960

Contact : 66550005-GRAB 88159245

## ESTIMATE

Repair Code : CLM16017

Date in : 31/01/2020

Vehicle Num. : SLE965Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104554426/1ZRX585870

|                                            |   |         |     |           |
|--------------------------------------------|---|---------|-----|-----------|
| REAR BUMPER REVERSE SENSOR WIRE HARNESS    | 1 | 715.20  | x   | 715.20    |
| REAR BUMPER SIDE RETAINER L/R              | 2 | 65.00   | ✓   | 130.00    |
| REAR END PANEL                             | 1 | 781.90  | ✓   | 781.90    |
| REAR END PANEL INNER TOP GARNISH           | 1 | 185.99  | ✓   | 185.99    |
| REAR EXHAUST GASKET                        | 1 | 63.20   | x   | 63.20     |
| REAR EXHAUST RUBBER MOUNTING               | 2 | 63.90   | x   | 127.80    |
| REAR EXHAUST SILENCER BOX                  | 1 | 1255.00 | x   | 1,255.00  |
| REAR FENDER INNER TRIM L/R                 | 2 | 338.00  | 338 | 676.00    |
| REAR FLOOR PANEL TOP BOARD COVER           | 1 | 485.10  | ✓   | 485.10    |
| REAR TAILLAMP INNER BACK RUBBER GASKET L/R | 2 | 25.50   | ✓   | 51.00     |
| REAR TAILLAMP L/R                          | 2 | 391.90  | ✓   | 783.80    |
| REAR TAILLAMP LOWER BRACKET L/R            | 2 | 88.70   | ✓   | 177.40    |
| Subtotal before discount                   |   |         |     | 20,588.59 |
| Percentage discount 25%                    |   |         |     | 5,147.15  |
| Sub-total 1                                |   |         |     | 15,441.44 |
| FRONT BUMPER CLIPS - SET                   | 1 | 80.00   | 30  | 80.00     |
| FRONT BUMPER NUMBER PLATE                  | 1 | 25.00   | ✓   | 25.00     |
| FRONT BUMPER NUMBER PLATE HOLDER           | 1 | 50.00   | 30  | 50.00     |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
18 SIN MING LANE #01-08 MIDVIEW CITY  
SINGAPORE 573960

Contact : 66550005-GRAB 88159245

## ESTIMATE

Repair Code : CLM16017

Date in : 31/01/2020

Vehicle Num. : SLE965Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104554426/1ZRX585870

|                                                         |              |        |           |                   |
|---------------------------------------------------------|--------------|--------|-----------|-------------------|
| FRONT GRILLE CLIPS - SET <i>Ne</i>                      | 1            | 40.00  | <i>20</i> | <del>40.00</del>  |
| REAR BOOTLID INNER TRIM BOARD CLIPS - SET <i>Not ne</i> | 1            | 50.00  | <i>+</i>  | 50.00             |
| REAR BUMPER CLIPS - SET <i>Ne</i>                       | 1            | 80.00  | <i>30</i> | <del>80.00</del>  |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Ne</i>  | 1            | 30.00  | <i>10</i> | <del>30.00</del>  |
| REAR FENDER INNER TRIM CLIPS L/R - SET <i>Ne</i>        | <i>215</i> 2 | 50.00  | <i>30</i> | <del>100.00</del> |
| REAR FLOOR PANEL INSULATOR MAT <i>Ne</i>                | 1            | 300.00 | <i>+</i>  | 300.00            |
| REAR TAILLAMP CLIPS L/R - SET <i>Ne</i>                 | 2            | 20.00  | <i>✓</i>  | 40.00             |
| Subtotal before discount                                |              |        |           | 795.00            |
| Percentage discount 0%                                  |              |        |           | 0.00              |
| <b>Sub-total 2</b>                                      |              |        |           | 795.00            |
| <b>Parts-total</b>                                      |              |        |           | <b>16,236.44</b>  |

## LABOUR

|                                                                                                                |                                |
|----------------------------------------------------------------------------------------------------------------|--------------------------------|
| To remove, change air con parts, vacuums, refill air con gas.                                                  | <i>60</i> <del>120.00</del>    |
| To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)       | <i>80</i> <del>80.00</del>     |
| To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.                 | <i>80</i> <del>100.00</del>    |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)          | <i>60</i> <del>140.00</del>    |
| To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper. | <i>800</i> <del>1,400.00</del> |
| To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.            | <i>600</i> <del>1,200.00</del> |
| To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.      | <i>+</i> 100.00                |

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
18 SIN MING LANE #01-08 MIDVIEW CITY  
SINGAPORE 573960

Contact : 66550005-GRAB 88159245

## ESTIMATE

Repair Code : CLM16017

Date in : 31/01/2020

Vehicle Num. : SLE965Y

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104554426/1ZRX585870

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

Labour Total

5,740.00

Parts & Labour Total

21,976.44

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 5

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Lj  
A/S 05/02/20  
10 days.  
total: 12729.71  
A/S: 10.1K ✓