

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

16-03-20

Date of Accident : 08-01-2020

OUR REF : SKJ 1561H/T/20

TAW SANG

Blk 23 Jalan Membina

#30-82

Singapore 163023

LKK - Mercedes

Date In/Out: 10-02-2020 to 13-02-2020

Not Authorised
Date
2/5 @ 1600
3 days

VEHICLE NO : SKJ 1561H

VEHICLE MODEL : MERCEDES BENZ c180

CHASSIS NO : WDD2040312A801644

LIST ITEM

Tail Lamp LH

Side Mirror LH

Side Mirror Cover With Signal Light

Rear Door Chrome Moulding LH

1/c one 605.00 X
Grand/Day 1,150.00 ✓
8u 406.00 X
nu 86.00 ✓
2,247.00
Less Discount 10%: 224.70
2,022.30

LABOUR CHARGE

To respray affected areas (Rear bumper, rear LH fender, rear LH door, LH side mirror & rear sport rim)

To renew damaged parts, straighten & repair and aligned all parts

To check & adjust computer wheel alignment

600 1,200.00
300 400.00
11 X 120.00
3,742.30
GST 7% : 261.96
AMOUNT DUE : 4,004.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1
SKJ 1561H/T/20

P-1236
102
111240
900.00
2012.40
1609