

VEHICLE NO. SMQ 6926X TOYOTA ALTIS

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<b>PARTS (LIST ITEMS)</b>			
1	LHS Rear Door	REPAIR	2 0.00	X
1	LHS Rear Door Protector		22 232.00	✓
1	LHS Rear fender		2 982.00	X
1	LHS Rear fender inner shield		17 238.00	X
1	LHS Rear taillamp		17 745.00	X
1	Rear bumper	485.10	cut 1120.00	—
2	Rear bumper retainer (long) @75.00		17 150.00	X
2	Rear bumper retainer (short) @68.00		17 136.00	X
2	Rear bumper reflectors @72.00		17 144.00	X
1	LHS Side skirting		cut/trim 780.00	—
1	LHS Rear shock absorber		17 592.00	X
1	LHS Rear wheel bearing		Doyle 248.00	✓
			5367.00	
		less 25%	1341.75	25%
			4025.25	
	<b>SPECIAL NETT ITEM</b>			
1set	Rear bumper clips		22 40.00	✓ S.W
1	Rear LHS fender Sealant		17 100.00	X
1	Rear LHS sport rim		cut/set 980.00	4005.2
1	LHS Rear fender inner shield clips		17 60.00	X
1	Rear windscreen inner sealant		17 120.00	X
	<b>Total Parts</b>		5325.25	

Not Authorized  
LHR  
2/5 # 2650 / 2  
4 days  
Theophile Attwiler

P-1745.10  
25%  
P-1308.82  
S.W-440.00  
L-1600.00  
3348.82  
22  
2679.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

50-2900

## VEHICLE NO. SMQ 6926X TOYOTA ALTIS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1400.00	- 520
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired LHS Rear door)	900.00	- 800
3	To remove and refix rear windscreen	140.00	- 11X
4	To remove and replace LHS Rear undercarriage parts (suspension system)	250.00	- 120
6	To conduct full computerised wheel alignment test	120.00	- 80
7	To <i>Disassemble &amp; refix cushion upholstery</i>	180.00	- 80
	Labour Total :	2990.00	
	TOTAL (PARTS & LABOUR):	8315.25	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts