

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20002038/KPS3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005529

Claimant
Vehicle No : SLF7177D **Insured Vehicle No :** SGG1701J

Date of Loss: 24/01/2020 Nature of Claim: TP Claim No: 1202000003794

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF7177D	Engine No:	65492080122669
Make & Model:	MERCEDES-BENZ E200, 2.0 D SE (A)	Chassis No:	WDD2130132A268758
Reg. Date:	31/10/2017 (Man. Year: 2017)	Odometer:	132202 km
Colour:	Metallic Black		
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,455.00	1,914.50	2,540.50	57.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	910.00	810.00	47.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,175.00	2,824.50	3,350.50	54.26
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	6,175.00	2,250.00	3,925.00	63.56
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/02/2020

Date Inspected: 24/02/2020 Inspected At:

Multilateral Services (HQ)
160 SIN MING DRIVE #06-01, SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jul 2020)
Parts:	143	MERCEDES-BENZ E200 2.0 D SE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF7177D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented / Warped	2,485.00 FL	*1,755.00 FL
2	1		*FRONT RH DOOR LOCK	Repair	980.00 FL	*- FL
3	1		*FRONT RH DOOR WINDOW CHROME MOULDING	Serviceable	520.00 FL	*- FL
4	1		*FRONT RH DOOR INNER RUBBER (50%)	Necessary	346.50 FS	*150.50 FS
5	1		*FRONT RH DOOR LOWER CHROME	Dented	580.00 FL	*205.00 FL
6	1		*REAR RH DOOR (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,911.50	2,110.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	456.50	196.00
Total Parts (\$\$)	4,455.00	1,914.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES ,TO DO CUTTING ,WELDING ,REPLACE REPAIR ACCIDENT AFFECTED AREA	New	600.00	250.00
2	TO TRANSFER DOOR PARTS TO ANOTHER DOOR	New	100.00	60.00
3	TO DO COMPUTER SETTING FOR DOOR AFTER REPAIR	New	150.00	100.00
4	TO CHECK WIRING SYSTEM ON ACCIDENT AREA	New	120.00	20.00
5	ANTI RUST (NPA)	New	0.00	0.00
6	TO SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	600.00	480.00
7	REMOVE,REFIX ,REPLACE GARNISH ,SIDE TRIM ,TRIM BOARD ,CAR SEAT UPHOLSTERY ETC	New	150.00	0.00
Gross Labour Cost (\$\$)			1,720.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >