

DOI: 6/2/20

SOM02FDR

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 05.02.20

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SFL3700J
 MODEL : SUZUKI VITARA
 DATE OF ACCIDENT : 04.02.20
 TIME OF ACCIDENT : 16:15HRS

JSAJTE 54V00200334

Ceilia.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	ENGINE MOUNTING	2	\$ 283.70	\$ 567.40	+
2	GEAR BOX MOUNTING	1	\$ 168.40	\$ 168.40	+
3	CENTER PROPELLER SHAFT	1	\$ 1,298.60	\$ 1,298.60	+
4	TAILGATE Dented	1	\$ 989.80	\$ 989.80	✓
5	TAILGATE HINGE New	2	\$ 65.00	\$ 130.00	+
6	TAILGATE GLASS WITH MOULDING Shattered	1	\$ 1,210.50	\$ 1,210.50	✓
7	TAIL GATE INNER TRIM Cribled	1	\$ 498.65	\$ 498.65	✓
8	TAILGATE TOP TRIM New	1	\$ 185.50	\$ 185.50	+
9	TAILGATE SIDE TRIM Cut	2	\$ 76.80	\$ 153.60	✓
10	TAILGATE WEATHER STRIP Cut	1	\$ 198.45	\$ 198.45	✓
11	TAILGATE LOCK Brand	1	\$ 175.65	\$ 175.65	✓
12	TAILGATE WIREHARNES New	1	\$ 287.60	\$ 287.60	+
13	TAILGATE EMBLEM 'SUZUKI'	1	\$ 120.50	\$ 120.50	✓
14	TAILGATE EMBLEM 'GRAND VITARA'	1	\$ 40.25	\$ 40.25	✓
15	TAIL GATE WIPER MOTOR New	1	\$ 422.00	\$ 422.00	+
16	SPARE TYRE COVER Dented	1	\$ 597.45	\$ 597.45	✓
17	SPARE TYRE COVER BASE Cribled	1	\$ 583.65	\$ 583.65	✓
18	SPARE TYRE BRACKET New	1	\$ 196.50	\$ 196.50	+
19	REAR BUMPER Dented	1	\$ 682.45	\$ 682.45	✓
20	REAR BUMPER REFLECTOR New	2	\$ 26.30	\$ 52.60	+
21	REAR BUMPER SIDE RETAINER New	2	\$ 46.50	\$ 93.00	✓
22	REAR NUMBER PLATE LAMP BRACKET New	1	\$ 94.35	\$ 94.35	+
23	REAR NUMBER PLATE LAMP New	2	\$ 47.20	\$ 94.40	+
24	TAIL LAMP Cribled	2	\$ 248.00	\$ 496.00	✓
25	TAIL LAMP LOWER BRACKET New	2	\$ 48.50	\$ 97.00	+
26	REAR FENDER INNER COWLING New	2	\$ 112.30	\$ 224.60	+
27	REAR FENDER INNER TRIM (TOP) New	2	\$ 488.50	\$ 977.00	+
28	REAR FENDER INNER TRIM (LOWER) Cribled	2	\$ 764.45	\$ 1,528.90	+
29	REAR END PANEL (OUTER) Dented	1	\$ 409.95	\$ 409.95	✓

560.

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SFL3700J
 MODEL : SUZUKI VITARA
 DATE OF ACCIDENT : 04.02.20
 TIME OF ACCIDENT : 16:15HRS

30	REAR END PANEL (INNER) <i>Revised</i>	1	\$ 342.75	\$ 342.75	+
31	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 169.55	\$ 169.55	✓
32	REAR FLOOR PANEL TOP COVER <i>Del'd</i>	1	\$ 394.65	\$ 394.65	✓

7374.10
6267.98

TOTAL PRICE \$ 13,481.70
 LESS 15% \$ 2,022.26
 SUB TOTAL PRICE \$ 11,459.45

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	TAIL GATE SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	+
4	TAIL GATE WINDSCREEN SEAL <i>20</i>	1	\$ 60.00	\$ 60.00	30
5	TAIL GATE WINDSCREEN SEALANT <i>10</i>	1	\$ 80.00	\$ 80.00	30
6	TAIL GATE WINDSCREEN SOLAR FILM	1	\$ 550.00	\$ 550.00	200
7	TAIL GATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	30
8	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	10
9	REAR FENDER INNER COWLING CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
10	REAR FENDER INNER TRIM (LOWER) CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	✓
11	REAR END PANEL SEALANT (OUTER) <i>New</i>	1	\$ 80.00	\$ 80.00	60
12	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	+
13	AUTO TRANSMISSION (2ND HAND) <i>3rd</i>	1	\$ 5,500.00	\$ 5,500.00	+
14	AUTO TRANSMISSION OIL <i>New</i>	1	\$ 280.00	\$ 280.00	+
15	REVERSE SENSOR <i>Del'd</i>	1	\$ 220.00	\$ 220.00	200

640

TOTAL \$ 7,310.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	80
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	80
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 80.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 280.00	60

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SFL3700J
 MODEL : SUZUKI VITARA
 DATE OF ACCIDENT : 04.02.20
 TIME OF ACCIDENT : 16:15HRS

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
12	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$ 350.00	100
13	REMOVE AND REFIX CENTER SHAFT PROPELLER	\$ 350.00	X
14	REMOVE AND REFIX AUTO TRANMISSION	\$ 350.00	X
15	REMOVE AND REFIX ENGINE MOUNTING AND GEAR BOX MOUNTING	\$ 650.00	X
16	FOUR WHEEL ALIGNMNET	\$ 120.00	X
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$6,300.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,769.45
 TOTAL LABOUR COST : \$ 6,300.00
 TOTAL REPAIR COST : \$ 25,069.45

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY

ABBY

SERVICE ADVISOR
 ABBY (HP: 9856 4815)

LRK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian
 L/R 06/02/20.
 07

total: 9007.98

L/S: AK

(Nett Value)

2100