

# LEONG AUTO PTE LTD

160, Sin Ming Drive, Sin Ming Autocity, #02-13, Singapore 575722  
 Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg  
 Business Registration No. 201312846W  
 GST Registration No. 201312846W

*Not Authorized  
 1 Day @?  
 Recovery After Paint 3 days*

## ESTIMATE

Date: 4/2/2020  
 DOA: 2/2/2020

Vehicle No: SML2443A  
 Make & Model: Audi A5 2.0 A

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Rear Boot Lid	\$ 2,236.30	X
7	1	Rear Boot Lid Lock Mechanism	\$ 117.20	X
8	1	Rear Boot Lid Lock Catch	\$ 97.20	X
9	1	Rear Boot Lid WeatherStrip	\$ 178.70	X
12	1	Rear End Panel (Outer)	\$ 850.00	?
13	1	Rear End Panel Top Garnish	\$ 135.90	X
14	2	Rear Fender Inner Trim	\$ 1,243.90	X
15	2	Tail Lamp	\$ 1,926.00	X
16	2	Tail Lamp Side Retainer	\$ 83.50	X
17	2	Fender Inner Shield	\$ 299.60	X
18	1	Rear Bumper Assy	\$ 1,468.60	✓
19	2	Rear Bumper Retainer	\$ 180.60	4
21	1	Rear Bumper Reinforcement	\$ 494.90	?
23	2	Rear Bumper Reinforcement Bracket	\$ 452.20	?
25	1	Rear Bumper Inner Garnish	\$ 264.30	?
27	1	Rear Bumper Tow Cover	\$ 148.50	X
29	4	Rear Bumper Parking Sensor	\$ 959.80	X
31	4	Rear Bumper Parking Sensor Holder	\$ 216.00	?
33	1	Rear Bumper Parking Sensor Wiring	\$ 473.50	X
35	2	Rear Exhaust Bracket	\$ 120.90	?
37	2	Rear Exhaust Mounting	\$ 127.90	?
			<b>\$ 12,075.50</b>	
Less 10%			<b>\$ 1,207.55</b>	
			<b>\$ 10,867.95</b>	
<u>Special Nett Items</u>				
1		Sundries	\$ 50.00	X
2	1	Rear Boot Lid Logo	\$ 180.00	X
3	1	Rear End Lower Panel (Inner) Sealant	\$ 120.00	?
4	1	Rear End Top Panel (Inner) Sealant	\$ 120.00	X
5	1	Rear End Panel (Outer) Sealant	\$ 120.00	X
6	1 set	Rear End Panel Top Garnish Clips	\$ 80.00	X
7	2 set	Rear Fender Inner Trim Clips	\$ 120.00	X
8	2	Rear Tail Lamp Tinting	\$ 300.00	X
9	2 set	Tail Lamp Clips	\$ 50.00	X
10	2 set	Fender Inner Shield Clips	\$ 60.00	X
11	1 set	Rear Bumper Assy Clips	\$ 50.00	✓
12	1 set	Rear Bumper Lower Garnish Clips	\$ 60.00	X
13	1	Rear Bumper Lower Diffuser Lip	\$ 1,800.00	✓
14	1 set	Rear Bumper Lower Diffuser Lip Clips	\$ 80.00	—
15	1	Rear Bumper Lower Diffuser Lip Sealant	\$ 120.00	4052
16	1 set	Rear Exhaust Assy	\$ 4,800.00	?
17	1 set	Rear No. Plate with Garnish	\$ 80.00	X

			\$ 8,190.00	
		<b>Total parts</b>	\$ 19,057.95	
S/N	Labour Description		Amount	Amount
1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.		\$ 1,600.00	7
2	To putty and spray painting rear portion.		\$ 1,200.00	500
3	To check rear lighting and wiring.		\$ 50.00	15/
4	To remove and install rear boot lid lock mechanism.		\$ ~ 150.00	X
5	To remove and install inner garnish and trim to facilitate the repair.	~	\$ - 380.00	X
6	To apply anti rust proofing to rear affected area.	~	\$ 250.00	X
7	To remove and install rear parking sensor.		\$ 150.00	60/
8	To conduct computer diagnostic test		\$ 180.00	?
9	To remove and install exhaust muffler and rear exhaust centre pipe		\$ 180.00	80/
10	To remove & refit boot lid componenet to replace boot lid, check & re-adjust the close gap and alignment and water seepage	~	\$ 120.00	X
	Total labour :		\$ 4,260.00	
	Total parts :		\$ 19,057.95	
	Total labour :		\$ 4,260.00	
	Total repair cost : (Before GST)		\$ 23,317.95	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: