

Total parts

\$	8,190.00
\$	19,057.95

S/N	Labour Description	Amount	Amount
	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.	\$ 1,600.00	400l
1	rear damaged parts.	\$ 1,200.00	500l
2	To putty and spray painting rear portion.	\$ 50.00	15l
3	To check rear lighting and wiring.	\$ ~ 150.00	X
4	To remove and install rear boot lid lock mechanism.	\$ ~ 380.00	X
5	To remove and install inner garnish and trim to facilitate the repair.	\$ 250.00	X
6	To apply anti rust proofing to rear affected area.	\$ 150.00	60l
7	To remove and install rear parking sensor.	\$ 180.00	R
8	To conduct computer diagnostic test	\$ ~ 180.00	80l
9	To remove and install exhaust muffler and rear exhaust centre pipe	\$ 180.00	
10	To remove & refit boot lid component to replace boot lid, check & re-adjust the close gap and alignment and water seepage	\$ 120.00	X
	Total labour :	\$ 4,260.00	

Total parts :
Total labour :
Total repair cost : (before GST)

\$	19,057.95
\$	4,260.00
\$	23,317.95

LKK Auto Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirm on Third party survey is on a "Without Prejudice" basis
- No repair/modification is allowed
- All repair work must be inspected and approved by the relevant insurance company
- Approval to final approval from insurance company