

源摩哆廠

GUAN MOTOR WORKS

Business Regn No 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SCL361J

No.	Qty	List Items	
1	1	Front bumper	\$ A 2,158.00 —
2	1	Front bumper LH side retainer	\$ D.I 78.00 —
3	1	LH headlamp	\$ CRA 3,789.00 ✓ 2972
4	1	Front LH fender	\$ BT 1,975.00 ✓ 1875
5	1	Front LH sports rim	\$ BT 3,122.00 ✓ 1981.30
6	1	Front LH shock absorber	\$ BT 2,951.00 ✓
7	1	Front LH lower arm	\$ NEC 1,877.00 ✓
8	1	Front LH knuckle arm	\$ BT 2,578.00 ✓
9	1	Front LH wheel hub	\$ BT 971.00 ✓
10	1	Front LH wheel bearing	\$ NEC 578.00 ✓
11	1	Front LH door	\$ BT 3,895.00 ✓ BT/wrp
12	1	Front LH door weatherstrip	\$ SW 321.00 X
13	1	Rear LH door	\$ R 4,325.00 X 4505N C.P. Dd
14	1	Rear LH door sticker	\$ MA 285.00 ✓ NEC
15	1	Rear LH door weatherstrip	\$ SW 321.00 X
16	1	LH rocker panel spoiler	\$ SW 1,231.00 X
			\$ 30,455.00
Less 10%			\$ 3,045.50
Total :			\$ 27,409.50

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,200.00	✓ 900
2	To putty and spray Spray Paintings charges.	\$ 1,200.00	1000
3	To check wirings and lightings.	\$ 40.00	200
4	To remove, refit front LH under carriages.	\$ 300.00	A 40
5	To conduct computerise wheel alignment test.	\$ 80.00	600
6	To supply and apply anti rust treatment	\$ 90.00	300
Total :		\$ 2,910.00	

Total Parts and Labour : \$ 30,319.50

NOT Authorized

Repair by paint

11 Sep 8, 1.A.1

7 days

LIS = \$ 17,550.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damage parts during resurvey
- Parts price should be without Prejudice basis
- Third party claim should be without Prejudice basis
- No illegal work should be done
- Supplies should be resurveyed and is subject to insurance company

Acknowledged by:

Signature: _____

Date: _____

Business Regn. No. 08102600E

126 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9

SUPPLEMENTARY REPAIR ESTIMATE FOR
PORSCHE PANAMERA - SCL 361 J

1 pc. LH Headlamp Nozzle

CM \$ 250.00 ✓

1 pc. LH Front Upper Arm

R \$ 650.00 ✓

\$ 900.00

Less 10% 90.00

TOTAL \$ 810.00