



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002046/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD

Date : 01-12-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 1730P	Veh. Inspected	SKM 909E
Policy No.	GA449683	Coverage (\$)	0.00
Claim No.	S0M02EM7	Excess (\$)	0.00
Assign From		Assign Date	05/02/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 740i	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAYA62080C994490	Colour	WHITE
Odometer	209088	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/35 R20	MICHELIN	6 mm
L/H Front Tyre	265/35 R20	MICHELIN	6 mm
R/H Rear Tyre	265/35 R20	MICHELIN	6 mm
L/H Rear Tyre	265/35 R20	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/01/2020	Inspection Date	10/02/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------