



Pte Ltd

AIG Singapore
78 Shenton Way
Singapore 079120

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMA INVOICE

Vehicle number	SGU3783K
Make / Model	HONDA / CIVIC
Chassis number	JHMFD45207S200581
Accident date	03 February 2020
Reference	2002-05

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS	
1	REAR BUMPER 733.70 de
2	REAR BUMPER RETAINER 2H-Xm 16.45 32.90 RH-de
1	REAR RH TAILLAMP 452 550.15 am
1	REAR RH TAILLAMP PANEL 165.70 Rx
1	REAR RH FENDER 919.72 Rx
1	BOOTLID 710.00 xRx
2	BOOTLID HINGE 96.00 xnn
1	BOOTLID WEATHERSTRIP 195.00 xnn
1	BOOTLID EMBLEM - HONDA 45.00 xnn
2	BOOTLID LAMP LHx 466.50x RHx RM-cra 233.25.
1	END PANEL 631.00 x? flow Rx
1	END PANEL TOP GARNISH 160.00 x de
1	RER WINDSCREEN MOULDING 40.00x nn.

4745.67

1595.40.

Less 20%

949.13

1296.32.

Subtotal

3796.54

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	REAR BUMPER CLIP 30.00 ne
1 SET	REAR REVERSE SENSOR 400.00x
1	REAR BUMPER LOWER GARNISH 350. 800.00 de
1	JOINT SEALANT 120.00 x
1	WINDSCREEN SEALANT 120.00 x

Subtotal

1470.00

380.

Balance C/F

5266.54

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

5266.54

1	CHECK REAR WIRING AND LIGHTING SYSTEM 60.00 30.
2	REMOVE,REFIT REAR LINING TRIM AND GARNISH 150.00 50.
3	REMOVE AND REFIT REAR WINDSCREEN 120.00x
4	PANEL BEATING ON AFFECTED AREAS 600 1000.00 400. repair
5	SPRAY PAINTING ON AFFECTED AREAS 700 1000.00 500 5 days
6	APPLY ANTI RUST ON AFFECTED AREAS 150.00 30

Subtotal

1410 2480.00

3066.32

41582450

5 days

Grand total

7746.54

Tanfer
97195749
WP' 5/2/20
C/1245
Repair after
5 days
Tanfer
11kants