

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Jia Le

Quotation

DATE : 12.02.2020
VEH NO : SJE8380E
MODEL : Honda Fit
D O A : 13.01.2020
YR REF : SLL2641G

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJE8380E (HONDA FIT)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO</u>	<u>LIST ITEMS</u>		
1	Rear Bumper <i>Dehd</i>	1	474.40 ✓
2	Rear Bumper Clips <i>re</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>re</i>	2	61.00 ✓
4	Rear End Panel <i>Dehd</i>	1	492.90 ✓
5	Rear End Panel Top Garnish <i>Dehd</i>	1	160.40 ✓
6	Tail Lamp - LH & RH <i>lit</i>	2	571.00 ✓
7	Tail Lamp Panel - LH & RH <i>re</i>	2	456.80 ✓
8	Tailgate <i>Dehd</i>	1	771.60 ✓
9	Tailgate Lock <i>Dehd</i>	1	196.30 ✓
10	Tailgate Weatherstripe <i>lit</i>	1	159.20 ✓
11	Tailgate Inner Trim Board <i>Dehd</i>	1	265.20 ✓
12	Tailgate Inner Trim Board Clips <i>re</i>	1 set	30.00 ✓
13	Tailgate Outer Garnish <i>re</i>	1	120.60 ✓
14	Tailgate Glass Moulding <i>re</i>	1	80.30 ✓
15	Honda Logo <i>re</i>	1	25.90 ✓
16	Rear Fender Inner Trim Board <i>LH Dehd</i>	2	544.20 ✓
17	Rear Fender Inner Trim Board Clips <i>re</i>	1 set	60.00 ✓
18	Rear Fender Inner Shield <i>LH Dehd</i>	2	125.00 ✓
19	Rear Fender Inner Shield Clips <i>re</i>	1 set	20.00 ✓
20	Spare Tyre Panel Top Board <i>re</i>	1	282.10 ✓
21	Tools Tray Sponge <i>re</i>	1	279.10 ✓
			5,206.00
Less 20%			(1,041.20)
			\$ 4,164.80

S/NETT ITEMS

1	Reverse Sensor <i>Damaged</i>	1	\$ 280.00 ✓
---	-------------------------------	---	-------------

RE : ESTIMATE FOR ACCIDENT REPAIR SJE8380E (HONDA FIT)

2	Rear End Panel Sealant <i>NA</i>	1	\$	60.00 ✓
3	Tailgate Glass Sealant <i>NA</i>	1	\$	60.00 ✓
4	Rear Camera <i>HE re</i>	1	\$	480.00 x
				\$ 880.00
Total Parts			\$	5,044.80

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 <i>800</i>
2	To putty & spray up paint works	\$	1,200.00 <i>800</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To remove reverse sensor	\$	100.00 <i>50</i>
5	To remove upholstery	\$	150.00 <i>80</i>
6	To transfer tailgate fittings	\$	150.00 <i>80</i>
7	To remove tailgate glass	\$	180.00 <i>120</i>
8	To remove rear camera	\$	100.00 <i>50</i>
Total Labour			\$ 3,130.00
Grand Total			\$ 8,174.80

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 5494.80
C/S: 4 HK.
06 Days

474.4+
30.+
61.+
492.9+
160.4+
571.+
771.6+
196.3+
159.2+
265.2+
30.+
272.1+
30.+
62.5+
20.+
279.1+
80.3+
=
3,956.*

3,956.x
80.%
3,164.8*

0.*

200.+
60.+
60.+
=
320.*

0.*

800.+
800.+
30.+
50.+
80.+
80.+
120.+
50.+
=
2,010.*

0.*

L/s = \$ 4,400

3,164.8+
320.+
2,010.+
=
5,494.8*

5,494.8x
80.%
4,395.84*