

## Case Details

Case Reference Number : TAX/01/20/2138  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHC4325B

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-10306-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : QBE Insurance (International) Ltd  
 Accident Date and Time : 30/01/2020 05:15 PM  
 Vehicle Age(In Months) : 25

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation   |              |         |                 |                                       |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | FENDER SUB-ASSY, FR , RH              | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | EMBLEM, SIDE PANEL ( HYBRID)          | 1   | 52.90                   | 52.90          | 25.00  | 39.67           | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | LINER, FR FENDER, RH                  | 1   | 198.40                  | 198.40         | 25.00  | 148.80          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | PAD, FR WHEEL RH                      | 1   | 57.70                   | 57.70          | 25.00  | 43.28           | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | HOOD SUB-ASSY                         | 1   | 938.40                  | 938.40         | 25.00  | 703.80          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | MIRROR ASSY, OUTER REAR VIEW , RH     | 1   | 1,373.50                | 1,373.50       | 10.00  | 1,236.15        | Replace           | 1                 | 1,236.15                 | Replace        | / CHY.  |
| One Time Key In       | Main         |         |                 | COVER, OUTER MIRROR, RH               | 1   | 89.50                   | 89.50          | 25.00  | 67.13           | Replace           | 1                 | 67.13                    | Replace        | / MRS.  |
| One Time Key In       | Main         |         |                 | MIRROR OUTER GLASS , RH               | 1   | 215.20                  | 215.20         | 25.00  | 161.40          | Replace           | 1                 | 161.40                   | Replace        | / MRS.  |
| One Time Key In       | Main         |         |                 | WHEEL, DISC                           | 1   | 1,555.10                | 1,555.10       | 25.00  | 1,166.32        | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | TYRE                                  | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | MOULDING ASSY, BODY ROCKER PANEL , RH | 1   | 576.00                  | 576.00         | 25.00  | 432.00          | Replace           | 1                 | 0                        | Repair         | X R     |
| Total Spare Part Cost |              |         |                 |                                       |     |                         |                |        | 25,554.74       | Surveyor Total    |                   | 5,421.98                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                                       |     |                         |                |        | 0.00            | Lump Sum Dis (%)  |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                                       |     |                         |                |        | 25,554.74       | Final Sur Total   |                   | 5,421.98                 |                |         |

| SMRT Recommendation   |              |         |                 |                                          |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|------------------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                                | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | PANEL SUB-ASSY, FRONT DOOR RH            | 1   | 1,249.60                | 1,249.60       | 25.00  | 937.20          | Replace           | 1                 | 0                        | Repair         | X R     |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT (DOOR)                | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace           | 1                 | 60.00                    | Replace        | / ME    |
| One Time Key In       | Main         |         |                 | GLASS SUB-ASSY, FRONT DOOR , RH          | 1   | 796.70                  | 796.70         | 25.00  | 597.53          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | GLASS, FRONT DOOR FIX WINDOW , RH        | 1   | 309.90                  | 309.90         | 25.00  | 232.42          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | WEATHERSTRIP, FRONT DOOR FIX WINDOW , RH | 1   | 74.30                   | 74.30          | 25.00  | 55.72           | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | RUN, FRONT DOOR GLASS , RH               | 1   | 141.70                  | 141.70         | 25.00  | 106.27          | Replace           | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | WEATHERSTRIP, FR RH                      | 1   | 126.10                  | 126.10         | 25.00  | 94.57           | Replace           | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | PANEL SUB-ASSY, REAR DOOR , RH           | 1   | 1,243.90                | 1,243.90       | 25.00  | 932.93          | Replace           | 1                 | 0                        | Repair         | X R     |
| One Time Key In       | Main         |         |                 | FILLER, REAR DOOR GLASS CHANNEL          | 1   | 27.20                   | 27.20          | 25.00  | 20.40           | Replace           | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | FILLER, REAR DOOR GLASS CHANNEL          | 1   | 14.30                   | 14.30          | 25.00  | 10.73           | Replace           | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | PANEL SUB-ASSY, FENDER REAR RH           | 1   | 824.80                  | 824.80         | 25.00  | 618.60          | Replace           | 1                 | 0                        | Repair         | X R     |
| One Time Key In       | Main         |         |                 | WHEEL, DISC                              | 1   | 1,555.10                | 1,555.10       | 25.00  | 1,166.32        | Replace           | 1                 | 0                        | Repair         | X R     |
| One Time Key In       | Main         |         |                 | TYRE                                     | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | FENDER SUB-ASSY, FR , LH                 | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | FENDER SUB-ASSY, FR , LH                 | 1   | 933.10                  | 933.10         | 25.00  | 699.83          | Replace           | 1                 | 699.83                   | Replace        | / PP    |
| One Time Key In       | Main         |         |                 | LINER, FR FENDER, LH                     | 1   | 194.30                  | 194.30         | 25.00  | 145.73          | Replace           | 0                 | 0                        | Not Give       | X SVC   |
| Total Spare Part Cost |              |         |                 |                                          |     |                         |                |        | 25,554.74       | Surveyor Total    |                   | 5,421.98                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                                          |     |                         |                |        | 0.00            | Lump Sum Dis (%)  |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                                          |     |                         |                |        | 25,554.74       | Final Sur Total   |                   | 5,421.98                 |                |         |

| SMRT Recommendation   |              |         |                 |                                             |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |              |
|-----------------------|--------------|---------|-----------------|---------------------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|--------------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks      |
| One Time Key In       | Main         |         |                 | PAD, FR WHEEL LH                            | 1   | 57.70                   | 57.70          | 25.00  | 43.28           | Replace           | 0                 | 0                        | Not Give       | X Svc        |
| One Time Key In       | Main         |         |                 | EMBLEM, SIDE PANEL ( HYBRID)                | 1   | 52.90                   | 52.90          | 25.00  | 39.67           | Replace           | 1                 | 39.68<br>39.67           | Replace        | Nec          |
| One Time Key In       | Main         |         |                 | WHEEL, DISC                                 | 1   | 1,555.10                | 1,555.10       | 25.00  | 1,166.32        | Replace           | 0                 | 0                        | Not Give       | X Svc        |
| One Time Key In       | Main         |         |                 | TYRE                                        | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace           | 0                 | 0                        | Not Give       | X Svc        |
| One Time Key In       | Main         |         |                 | MIRROR ASSY, OUTER REAR VIEW , LH           | 1   | 1,283.90                | 1,283.90       | 10.00  | 1,155.51        | Replace           | 1                 | 1,155.51                 | Replace        | Mis.         |
| One Time Key In       | Main         |         |                 | COVER, OUTER MIRROR, LH                     | 1   | 89.50                   | 89.50          | 25.00  | 67.13           | Replace           | 1                 | 67.13                    | Replace        | Mis.         |
| One Time Key In       | Main         |         |                 | MOULDING ASSY, BODY ROCKER PANEL , LH       | 1   | 576.00                  | 576.00         | 25.00  | 432.00          | Replace           | 1                 | 432.00                   | Replace        | X Mis.<br>NN |
| One Time Key In       | Main         |         |                 | PANEL SUB-ASSY, FRONT DOOR LH               | 1   | 1,249.60                | 1,249.50       | 25.00  | 937.20          | Replace           | 1                 | 0                        | Repair         | X R.         |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT (DOOR)                   | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace           | 1                 | 60.00                    | Replace        | Nec          |
| One Time Key In       | Main         |         |                 | DOOR OUTER HANDLE FRONT , LH                | 1   | 378.90                  | 378.90         | 25.00  | 284.17          | Replace           | 1                 | 284.18<br>284.17         | Replace        | SCH          |
| One Time Key In       | Main         |         |                 | COVER SUB-ASSY, FRONT PILLAR , UPR LH       | 1   | 96.90                   | 96.90          | 25.00  | 72.68           | Replace           | 1                 | 72.68                    | Replace        | Mis.         |
| One Time Key In       | Main         |         |                 | GLASS SUB-ASSY, FRONT DOOR , LH             | 1   | 796.70                  | 796.70         | 25.00  | 597.53          | Replace           | 1                 | 597.53                   | Replace        | CNA          |
| One Time Key In       | Main         |         |                 | MOULDING, FRONT DOOR WINDOW FRAME , REAR LH | 1   | 54.70                   | 54.70          | 25.00  | 41.03           | Replace           | 0                 | 0                        | Check          | X Svc        |
| One Time Key In       | Main         |         |                 | GLASS, FRONT DOOR FIX WINDOW , LH           | 1   | 309.90                  | 309.90         | 25.00  | 232.42          | Replace           | 0                 | 0                        | Not Give       | X Svc        |
| One Time Key In       | Main         |         |                 | RUN, FRONT DOOR GLASS , LH                  | 1   | 141.70                  | 141.70         | 25.00  | 106.27          | Replace           | 0                 | 0                        | Check          | X Svc        |
| One Time Key In       | Main         |         |                 | WEATHERSTRIP, FR LH                         | 1   | 126.10                  | 126.10         | 25.00  | 94.57           | Replace           | 0                 | 0                        | Check          | X Svc        |
| Total Spare Part Cost |              |         |                 |                                             |     |                         |                |        | 25,554.74       | Surveyor Total    |                   | 5,421.98                 |                |              |
| Lump Sum Discount (%) |              |         |                 |                                             |     |                         |                |        | 0.00            | Lump Sum Dis (%)  |                   | 0                        |                |              |
| Final Spare Part Cost |              |         |                 |                                             |     |                         |                |        | 25,554.74       | Final Sur Total   |                   | 5,421.98                 |                |              |



| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation                         |     |                         |                |        |                       | Surveyor Approval |                   |                          |                | Remarks  |
|-----------------|--------------|---------|-----------------|---------------------------------------------|-----|-------------------------|----------------|--------|-----------------------|-------------------|-------------------|--------------------------|----------------|----------|
|                 |              |         |                 | Part Name                                   | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$)       | Repair/Replace    | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |          |
| One Time Key In | Main         |         |                 | WEATHERSTRIP, FRONT DOOR FIX WINDOW , LH    | 1   | 74.30                   | 74.30          | 25.00  | 55.72                 | Replace           | 0                 | 0                        | Check          | X SVC    |
| One Time Key In | Main         |         |                 | GLASS SUB-ASSY, REAR DOOR, LH               | 1   | 397.80                  | 397.80         | 25.00  | 298.35                | Replace           | 1                 | 298.35                   | Replace        | ✓ SCH    |
| One Time Key In | Main         |         |                 | PANEL SUB-ASSY, REAR DOOR , LH              | 1   | 1,243.90                | 1,243.90       | 25.00  | 932.93                | Replace           | 1                 | 0                        | Repair         | X R      |
| One Time Key In | Main         |         |                 | DOOR OUTER HANDLE REAR , LH                 | 1   | 93.90                   | 93.90          | 25.00  | 70.43                 | Replace           | 1                 | 70.43                    | Replace        | ✓ SCH    |
| One Time Key In | Main         |         |                 | MOULDING, REAR DOOR WINDOW FRAME , FRONT LH | 1   | 54.70                   | 54.70          | 25.00  | 41.03                 | Replace           | 0                 | 0                        | Check          | X SVC    |
| One Time Key In | Main         |         |                 | GLASS SUB-ASSY, REAR DOOR, LH               | 1   | 397.80                  | 397.80         | 25.00  | 298.35                | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | GLASS , REAR DOOR QUARTER WINDOW , LH       | 1   | 104.60                  | 104.60         | 25.00  | 78.45                 | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | WEATHERSTRIP, REAR DOOR QUARTER WINDOW , LH | 1   | 47.70                   | 47.70          | 25.00  | 35.78                 | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | WEATHERSTRIP, REAR DOOR GLASS, INNER LH     | 1   | 94.80                   | 94.80          | 25.00  | 71.10                 | Replace           | 0                 | 0                        | Check          | X SVC    |
| One Time Key In | Main         |         |                 | PANEL SUB-ASSY, FENDER REAR LH              | 1   | 824.80                  | 824.80         | 25.00  | 618.60                | Replace           | 1                 | 0                        | Repair         | X R      |
| One Time Key In | Main         |         |                 | WHEEL, DISC                                 | 1   | 1,555.10                | 1,555.10       | 25.00  | 1,166.32              | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | TYRE                                        | 1   | 126.74                  | 126.74         | 0.00   | 126.74                | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | LID ASSY, FUEL FILLER OPENING               | 1   | 164.10                  | 164.10         | 25.00  | 123.07                | Replace           | 0                 | 0                        | Not Give       | X SVC    |
| One Time Key In | Main         |         |                 | COVER, FR BUMPER                            | 1   | 495.50                  | 495.50         | 25.00  | 371.63                | Replace           | 1                 | 0                        | Repair         | X R      |
| One Time Key In | Main         |         |                 | SUPPORT, FR BUMPER RH                       | 1   | 76.90                   | 76.90          | 25.00  | 57.68                 | Replace           | 0                 | 0                        | Check          | X SVC    |
| One Time Key In | Main         |         |                 | SUPPORT, FR BUMPER LH                       | 1   | 82.30                   | 82.30          | 25.00  | 61.72                 | Replace           | 0                 | 0                        | Check          | X SVC    |
|                 |              |         |                 |                                             |     |                         |                |        | Total Spare Part Cost | 25,554.74         | Surveyor Total    |                          |                | 5,421.98 |
|                 |              |         |                 |                                             |     |                         |                |        | Lump Sum Discount (%) | 0.00              | Lump Sum Dis (%)  |                          |                | 0        |
|                 |              |         |                 |                                             |     |                         |                |        | Final Spare Part Cost | 25,554.74         | Final Sur Total   |                          |                | 5,421.98 |

| SMRT Recommendation   |              |         |                 |                                     |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-------------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                           | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | COVER, FR BUMPER RH                 | 1   | 28.10                   | 28.10          | 25.00  | 21.08           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | COVER, FR BUMPER LH                 | 1   | 28.10                   | 28.10          | 25.00  | 21.08           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER        | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | RETAINER, FR BUMPER, LH & RH        | 1   | 8.50                    | 8.50           | 25.00  | 6.38            | Replace                  | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | COVER ASSY, ENGINE                  | 1   | 180.10                  | 180.10         | 25.00  | 135.07          | Replace                  | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | COVER ASSY, ENGINE UNDER CENTER SET | 1   | 452.80                  | 452.80         | 25.00  | 339.60          | Replace                  | 0                 | 0                        | Check          | X SVC   |
| One Time Key In       | Main         |         |                 | GRILLE SUB-ASSY                     | 1   | 335.60                  | 335.60         | 25.00  | 251.70          | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | COVER, RR BUMPER ASSY               | 1   | 423.90                  | 423.90         | 25.00  | 317.92          | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | REAR BUMPER REINFORCEMENT           | 1   | 318.80                  | 318.80         | 25.00  | 239.10          | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | SEAL, RR BUMPER ARM, RH & LH        | 1   | 11.00                   | 11.00          | 25.00  | 8.25            | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | PAD, RR BUMPER, RH & LH , 1         | 1   | 3.80                    | 3.80           | 25.00  | 2.85            | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | PAD, RR BUMPER, RH & LH , 2         | 1   | 3.80                    | 3.80           | 25.00  | 2.85            | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | PAD, RR BUMPER, RH & LH , 3         | 1   | 3.80                    | 3.80           | 25.00  | 2.85            | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | RETAINER, RR BUMPER, RH             | 1   | 112.70                  | 112.70         | 25.00  | 84.53           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | RETAINER, RR BUMPER, LH             | 1   | 111.50                  | 111.50         | 25.00  | 83.63           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| One Time Key In       | Main         |         |                 | SEAL, RR BUMPER , RH                | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace                  | 0                 | 0                        | Not Give       | X SVC   |
| Total Spare Part Cost |              |         |                 |                                     |     |                         |                |        | 25,554.74       | Surveyor Total 5,421.98  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                     |     |                         |                |        | 0.00            | Lump Sum Dis (%) 0       |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                     |     |                         |                |        | 25,554.74       | Final Sur Total 5,421.98 |                   |                          |                |         |

| SMRT Recommendation   |              |         |                 |                                         |     |                         |                |        |                 |                  | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-----------------------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                               | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace  | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | SEAL, RR BUMPER , LH                    | 1   | 85.20                   | 85.20          | 25.00  | 63.90           | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | CLIPS PIECE, FRT & RR BUMPER            | 10  | 1.50                    | 15.00          | 25.00  | 11.25           | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | GUARD, RR BUMPER, LOWER                 | 1   | 558.30                  | 558.30         | 25.00  | 418.72          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | FILLER, RR BUMPER , RH                  | 1   | 119.90                  | 119.90         | 25.00  | 89.93           | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | FILLER, RR BUMPER , LH                  | 1   | 119.90                  | 119.90         | 25.00  | 89.93           | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | PIXEL STICKER                           | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace          | 2                 | 120.00                   | Replace        | X Nec.  |
| One Time Key In       | Main         |         |                 | SENSOR REVERSE                          | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | COVER, REAR FLOOR UNDER , RH            | 1   | 169.50                  | 169.50         | 25.00  | 127.13          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | COVER, REAR FLOOR UNDER , LH            | 1   | 234.30                  | 234.30         | 25.00  | 175.73          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | COVER, REAR FLOOR UNDER CENTER          | 1   | 222.60                  | 222.60         | 25.00  | 166.95          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | ANTENNA, ELECTRICAL KEY                 | 1   | 60.30                   | 60.30          | 10.00  | 54.27           | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | LENS & BODY, REAR COMBINATION LAMP , RH | 1   | 438.10                  | 438.10         | 10.00  | 394.29          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | LENS & BODY ASSY , RR BUMPER , RH       | 1   | 486.80                  | 486.80         | 10.00  | 438.12          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| One Time Key In       | Main         |         |                 | LENS & BODY ASSY , RR BUMPER , LH       | 1   | 486.80                  | 486.80         | 10.00  | 438.12          | Replace          | 0                 | 0                        | Not Give       | X Svc   |
| Total Spare Part Cost |              |         |                 |                                         |     |                         |                |        | 25,554.74       | Surveyor Total   |                   | 5,421.98                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                                         |     |                         |                |        | 0.00            | Lump Sum Dis (%) |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                                         |     |                         |                |        | 25,554.74       | Final Sur Total  |                   | 5,421.98                 |                |         |

#### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope            | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR LH PORTION | 676.00                  | 500                     |         |
| Total: |              |                      | 1,183.00                | 700.00                  |         |

| S.No.  | Costing Type | Job Scope            | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|----------------------|----------------------------|----------------------------|---------|
| 2      | Main         | TO REPAIR RH PORTION | 507.00                     | 200                        |         |
| Total: |              |                      | 1,183.00                   | 700.00                     |         |

#### Spray Cost Detail

| S.No.  | Costing Type | Job Scope                            | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|--------------------------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER               | 378.00                     | 200                        |         |
| 2      | Main         | TO RESPRAY FILLER RR BUMPER LH       | 180.00                     | 0                          |         |
| 3      | Main         | TO RESPRAY FILLER RR BUMPER RH       | 180.00                     | 0                          |         |
| 4      | Main         | TO RESPRAY BUMPER BEAM               | 180.00                     | 0                          |         |
| 5      | Main         | TO REPSRAY FRONT BUMPER              | 378.00                     | 200                        |         |
| 6      | Main         | TO RESPRAY FRONT BUMPER LOWER GRILLE | 180.00                     | 0                          |         |
| 7      | Main         | TO RESPRAY REAR FENDER RH            | 378.00                     | 200                        |         |
| 8      | Main         | TO RESPRAY REAR DOOR RH              | 378.00                     | 200                        |         |
| 9      | Main         | TO RESPRAY FRONT DOOR RH             | 378.00                     | 200                        |         |
| 10     | Main         | TO RESPRAY FRONT FENDER RH           | 378.00                     | 0                          |         |
| 11     | Main         | TO RESPRAY FRONT FENDER LH           | 378.00                     | 200                        |         |
| 12     | Main         | TO RESPRAY FRONT DOOR LH             | 378.00                     | 200                        |         |
| 13     | Main         | TO REPSRAY REAR DOOR LH              | 378.00                     | 200                        |         |
| 14     | Main         | TO RESPRAY REAR FENDER LH            | 378.00                     | 200                        |         |
| 15     | Main         | TO RESPRAY RIM                       | 720.00                     | 50                         |         |
| 16     | Main         | RESPRAY MIRROR COVER LH              | 180.00                     | 80                         |         |
| 17     | Main         | RESPRAY MIRROR COVER RH              | 180.00                     | 80                         |         |
| 18     | Main         | TO REPSRAY FRONT HOOD                | 378.00                     | 0                          |         |
| Total: |              |                                      | 5,958.00                   | 2,010.00                   |         |

#### Other Cost Detail

| S.No.  | Costing Type | Job Scope | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|-----------|----------------------------|----------------------------|---------|
| Total: |              |           | 1,741.00                   | 490.00                     |         |



| S.No.  | Costing Type | Job Scope                                         | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks       |
|--------|--------------|---------------------------------------------------|-------------------------|-------------------------|---------------|
| 1      | Main         | TOWING CHARGE                                     | 56.00                   | 0                       | 40            |
| 2      | Main         | TO REMOVE AND REFIX WING MIRROR                   | 120.00                  | 50                      | /             |
| 3      | Main         | TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)   | 120.00                  | 30                      | /             |
| 4      | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA           | 100.00                  | 30                      | /             |
| 5      | Main         | TO REPLACE SUNDRY PARTS                           | 100.00                  | 20                      | /             |
| 6      | Main         | TO CHECK WIRING AND SYSTEM FUNCTION               | 80.00                   | 20                      | /             |
| 7      | Main         | TO WASH AND VACUUM                                | 60.00                   | 0                       |               |
| 8      | Main         | TO TEST AND REFIX REVERSE SENSOR SYSTEM           | 120.00                  | 30                      | /             |
| 9      | Main         | TO TRANSFER DOOR MECHANISM                        | 120.00                  | 0                       |               |
| 10     | Main         | TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET) | 625.00                  | 250                     | 2 pcs (FL,RL) |
| 11     | Main         | TO DO WHEEL ALIGNMENT / TYRE BALANCING            | 120.00                  | 60                      | /             |
| 12     | Main         | TO REMOVE & REFIT REAR QUARTER GLASS LH           | 120.00                  | 0                       |               |
| Total: |              |                                                   | 1,741.00                | 490.00                  |               |
|        |              |                                                   |                         |                         | 42,178.66#    |

## Summary


|                          | Estimator Assesment(\$) | Surveyor Assesment(\$)          |
|--------------------------|-------------------------|---------------------------------|
| Total Spare Part Detail  | 25,554.74               | 5,421.98 /                      |
| Total Labour Cost        | 0.00                    | 700.00 /                        |
| Total Spray Painting     | 0.00                    | 2,010.00 /                      |
| Other                    | 0.00                    | 490.00 /                        |
| Overall Total            | 25,554.74               | 8,621.98 /                      |
| Lump Sum Repair Option   |                         |                                 |
| Lump Sum Total           | 0.00                    | 8,621.98                        |
| Surveyor Approved Amount |                         | 8,621.98                        |
| No of Repair Days*       | 11                      | 7                               |
| Remarks                  |                         | P/P Repair, before spray photo. |
| Surveyor Name            |                         | Sun Pin (LKK)                   |



Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

03/02/2020

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: