

...CLAIM SUBFOLDER...(Pending for Survey Report)































CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2020 11:28		07 Feb 2020 11:36 Edit Adj Rpt	S\$854.00 Edit Estimates	S\$854.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		MUHAMMAD NUR SYAFIQ BIN HARRON, ID: S9813194I [Created by insurer]							
Main Claimant:		SMRT BUSES LTD, Co. Reg. No.: 198202292D							
Vehicle Reg. No.:		SG5826P	Date of Loss:	01/02/2020 11:00 - :59 [29 Months and 10 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / MSC/V/20-000333	Policy/Cover Note No.:	MSD/VMT/20-507192-WTT (Third Party Only) Coverage: 31/01/2020 - 30/01/2021					
Vehicle Reg. No. (Insured):		F8D6851B	Policy No. (Claimant):						
		Excess:							
Repairer:		SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 08/02/2020]							
Driver/Custodian (Insured):		MUHAMMAD NUR SYAFIQ BIN HARRON (), NRIC: S9813194I Email:							
Adj Asg. Remarks:		Direct Survey by LKK.							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SG5826P (MSC/V/20-000333)
[FBD6851B]
TP
SMRT BUSES LTD
Feb 1 2020 11:00AM
[MUHAMMAD NUR SYAFIQ BIN HARRON]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							
						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
11	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
12	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
13	16/03/20 09:43	General View		 Load JPG	<input checked="" type="checkbox"/>		
14	16/03/20 09:43	Odometer Reading		 Load JPG	<input checked="" type="checkbox"/>		
15	16/03/20 09:43	Chassis Number		 Load JPG	<input checked="" type="checkbox"/>		
16	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
17	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
18	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
19	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
20	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
21	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
22	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
23	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
24	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
25	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
26	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
27	16/03/20 09:43	After Repair Photo		 Load JPG	<input checked="" type="checkbox"/>		
Documentation							
						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	07/02/20 11:29	EMAIL FM LKK DS		 Load PDF			
2	07/02/20 11:29	TP GIA		 Load PDF			
3	07/02/20 11:31	OI GIA		 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
----------------------------	--	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20002053/EQD3E2

Date: 31/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VM/20-507192-WTT
 Claimant Vehicle No: SG5826P Insured Vehicle No: FBD6851B
 Date of Loss: 01/02/2020 Nature of Claim: TP Claim No: MSC/V/20-000333

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG5826P**
 Make & Model: MAN A95, 10.5 D (A) Engine No: 50344591974459
 Reg. Date: 22/08/2017 (Man. Year: 2016) Chassis No: WMAA95ZZ3G7003486
 Colour: Multi-colour Odometer: 101572 km
 Engine Capacity: 10518 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,227.00	854.00	373.00	30.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,227.00	854.00	373.00	30.40

INSPECTION

Date of Assignment: 07/02/2020
 Date Inspected: 05/02/2020 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 1.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Mar 2020)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG5826P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	432.00	324.00
Gross Labour Cost (S\$)			1,227.00	854.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >