

000000

/SS, REC. BY:

REF: CS/SMO2 0002064/UGBⁿ²

Special Instruction:

Surveyor

MARUS

ASSIGNMENT (Office)

From (Person):

Grau TRO

of

SMO

Date/Time:

6.2.2020 10:42am

* Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 5D36B

Insured:

FS 5947P

at Workshop m/s

Abhin Service

Tel:

9848 2243

of

NO 17 Kati Bukit Road 4 #01-60 Banting Biz

Policy No:

Claim No:

CMD 2006577/GPI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

"imp"

Date/Time:

6/2/2020 11:01am

Person Contacted:

Shanfah

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 5D36B - KATI/VC 18018304/24 D.O.A - 15/10/2018
	FS 5947P - X
10/2/2020 1:37pm	Vehicle returned to Grau Pau Loop by email.

ASS. REQ. BY: NEW/CLREF: Sno

ASSIGNMENT

From:

Date: 7/1/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 5036Bat Workshop m/s Abwin Serviceof NO 17 Kaki Bukit Rd 4 #01-60

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: After 2pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

SSk.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

MPⁿ LYA 42716

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLD 5036B Yr Regn: 6 / 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Harada vezel C.C. 1496

Colour:

white A/C: Insured / Std / NI / NA

Sp. Reading:

97120 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU11112152

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

6

Rear:

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

5/1/20

D.O.I.

7/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 1/L

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/1/20 1/5 \$2620 confirmed with Sher-feli. (Red to 6233.87, 71%.)

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

☐

Preli. Report

1) 21/2/20 Final☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Welding (\$

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Other:

TOTAL

250

Rep. Form:

Lump Sum / F.P.:

TP2600



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000577/GPL

Date: 10th February 2020

Our Ref: CS/SMO20002064/Uqf3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLD 5036B


We thank you for the instruction on 06/02/2020.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/02/2020 at the premises of M/s ABWIN SERVICE and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 8,833.87</u>
Revised Estimate Amount	: <u>S\$ 3,620.37</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages consistent.

We have NOT authorize repair.

Yours faithfully

Marcus Chua
Licensed Appraiser

Summer Lee (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 6 February, 2020 10:42 AM
To: AbwinM9 - Sharifah; Gnoh, Pau Loong; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD2000577/GPL - LKK/ FS5947P & SLD5036B ACC on 05/02/2020
Attachments: SAS2745736.PDF

Our Reference: CMTD2000577/GPL
Your Reference: SLD5036B

Without Prejudice

EMAIL ONLY

Date: 06/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING FS5947P & SLD5036B ON 05.02.2020

We refer to your email reply of today.

We will appoint LKK Auto to conduct the survey.

Hi LKK AUTO,

Please make the arrangement to survey for **SLD5036B** on a without prejudice and any admission of liability basis.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/
PauLoong.Gnoh@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, **Mr. Pau Loong**.

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Thursday, February 6, 2020 10:25 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: RE: CMTD2000577/GPL - PRI/ FS5947P & SLD5036B ACC on 05/02/2020

WITHOUT PREJUDICE

Hi Grace

Please proceed to appoint LKK for the PRI.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | **F** +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Thursday, 6 February, 2020 9:48 AM
To: AbwinM9 - Sharifah <sharifah@abwinm9.com>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD2000577/GPL - PRI/ FS5947P & SLD5036B ACC on 05/02/2020

Our Reference: CMTD2000577/GPL
Your Reference: SLD5036B

Without Prejudice
EMAIL ONLY

Date: 06/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING FS5947P & SLD5036B ON 05.02.2020

We refer to your Notice of Accident dated 05/02/2020.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 217/ PauLoong.Gnoh@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

	Pre-Repair Survey		
	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Wednesday, February 5, 2020 4:46 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: PRI - Accident Involving SLD5036B & FS5947P on 05/02/2020

WITHOUT PREJUDICE

Dear Sir / Mdm

We have been appointed by **MR YANG WEIHAI**, the registered owner of vehicle no. **SLD5036B** to claim damages against you in connection with a road traffic accident involving SLD5036B & FS5947P on 05/02/2020 at around 0840hrs along CLEMENTI ROAD (SLIP ROAD TOWARDS AYE).

Please arrange for your surveyor to conduct the Pre-repair Inspection **soonest** at our premises (please let us have the available date/timing):

Workshop Location:

Abwin Service Pte Ltd

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809

Please note that if you fail to arrange the pre-repair inspection within the next two (2) working days excluding any intervening Saturday, Sunday and/or Public Holiday, our workshop will commence the repair works without any further notice or reference to you.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | **F** +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 10 February 2020 1:37 PM
To: 'Teo, Grace'; 'Gnoh, Pau Loong'; assignments; SUR
Cc: 'Ye, Yong Kang Melvin'; 'Henry, Irene James'
Subject: RE: CMTD2000577/GPL - LKK/ FS5947P & SLD5036B ACC on 05/02/2020
Attachments: CSSMO20002064Uqf3.pdf

Dear Mr Gnoh,

Enclosed herewith preliminary advice of SLD 5036B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 6 February 2020 11:04 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>
Subject: RE: CMTD2000577/GPL - LKK/ FS5947P & SLD5036B ACC on 05/02/2020

Dear Sir/Madam,

Thank you for the assignment.

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 6 February, 2020 10:42 AM
To: AbwinM9 - Sharifah <sharifah@abwinm9.com>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; 'assignments@lkkauto.com' <assignments@lkkauto.com>; sur@lkkauto.com
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD2000577/GPL - LKK/ FS5947P & SLD5036B ACC on 05/02/2020

Our Reference: CMTD2000577/GPL

ANNOUNCING Carway

as sgCarMart Premium Dealer for the 3rd Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2016 Mercedes-Benz B180 At \$73K.



Low Mileage, Immaculate
Condition, With 1 Year
Warranty.
Direct Owner Status



PRIME MOTOR &

IOHENG YONG CREDIT ENTERPRISES PTE LTD. GR

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted

98 vehicles

vezel

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	vezel	Any	Any	2016	Any	Any	Any
	Honda Vezel Hybrid 1.5A RS Honda Sensing	\$70,800	\$9,630 /yr	30-Dec-2016	1,496 cc	63,000 km	SUV

Fuel Type: Petrol-Electric

RS Model. Only 1 Unit Left. 1 Owner Only. 100% Accident Free. Extremely High Quality Interior. Original Japan Full Kit, Alloy Rim. Different From Others. HID And LED Fog Lamp. View Now! High ARF \$8,843.

Posted: 07-Feb-2020 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X	\$61,800	\$8,750 /yr	02-Aug-2016	1,496 cc	38,000 km	SUV
---------------------------	-----------------	-------------	-------------	----------	-----------	-----

Cheapest In The Market, Non PHVI Full Loan Available, Immediate Transfer For Cash Deal. Extremely Well Taken Care Of By 1 Single Owner, Accident Free Condition, Original Paintwork Since Day 1. View To Believe! Bank And In House Loan Available! In House Loan Int...

Heritage Auto Enterprise Pte Ltd

Posted: 07-Feb-2020 Tags: 2015 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X	\$61,800	\$8,530 /yr	31-Aug-2016	1,496 cc	63,850 km	SUV
---------------------------	-----------------	-------------	-------------	----------	-----------	-----

Don't Miss This Superb Condition Vezel 1.5A, See To Fall In Love On First Sight! 1 Lady Owner, Non Private Hire/Leasing Car. Genuine Low Mileage Done 63850km. Just Done Major Servicing In Sept 19 With Proof. New Paintwork/Dunlop Tyres. 100% Accident Free. Call...

Lake View Credit Pte Ltd

Posted: 06-Feb-2020 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel 1.5A X	\$59,800	\$8,830 /yr	27-Apr-2016	1,496 cc	40,268 km	SUV
---------------------------	-----------------	-------------	-------------	----------	-----------	-----

Low Mileage. 1 Owner! Well Maintained Unit! Selling Cheap! Practical And Fuel Efficient SUV! Spacious And Easy To Maintain! Full Loan And High Trade In Available! Flexible Loan Available With Fast And Easy Loan Approval! Immediate Transfer Of Ownership Upon Collecti...

Benefit Auto Enterprise Pte Ltd

Posted: 06-Feb-2020 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Door Visor

Honda Vezel Door Visor

More info about this product

Honda Vezel 1.5A X	\$60,800	\$9,550 /yr	06-Jan-2016	1,496 cc	51,766 km	SUV
---------------------------	-----------------	-------------	-------------	----------	-----------	-----

ry Silver Vezel With Red Leather Interior And Upgraded Mugen Front Grill Is Definitely Not To Be Missed! Loan Interest Starts 1%, Both Bank And In House Loan Available. Do Call Our Sales Consultant For A Viewing!

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	224H
Vehicle Details	
Vehicle No.:	SLD5036B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	L15B4032157
Chassis No.:	RU11112152
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,982.00
Original Registration Date:	20 Jun 2016
First Registration Date:	20 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$11,375.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jun 2026
PARF Rebate Amount:	\$8,531.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$34,185.00
Total Rebate Amount:	\$42,716.00

The information contained herein is correct as at 07 Feb 2020

OK

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000268**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SLD5036B
MR YANG WEIHAI
 BLK 494B TAMPINES
 AVENUE 9
 #07-460
 SINGAPORE 520494
 CONTACT NO : 82980964

DATE : 07-FEB-2020
 MAKE : HONDA
 MODEL : VEZEL 1.5X CVT
 CHASSIS NO : RU11112152
 ENGINE NO : L15B4032157
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 2

QTY DESCRIPTION REPAIR AMOUNT (SGD) SURVEYOR APP (SGD)

LIST ITEM

1	TAIL GATE	1,155.00	
1	TAIL GATE LOCK	172.70	X
1	REAR BUMPER	510.07	
1	REAR BUMPER SIDE RETAINER LH	19.25	X
1	REAR BUMPER REFLECTOR LH	155.10	X
1	TAIL GATE EMBLEM	20.70	X
1	TAIL GATE EMBLEM "VEZEL"	47.30	
1	REAR END PANEL	453.00	X
1	REAR END PANEL TOP GARNISH	101.50	X
1	TAIL GATE LAMP LH	291.05	X
1	TAIL LAMP LH	485.65	X
1	REAR WINDSCREEN MOULDING	132.00	
1	TAIL GATE LOCK SENSOR	193.05	X
1	TAIL GATE INNER HANDLE	27.50	X
1	TAIL GATE WEATHERSTRIP	101.50	X
1	REAR SMART BUZZER	88.00	
1	REAR EXTENSION PANEL LH	176.00	X
1	REAR CHASSIS BEAM LH	104.50	X

Sub Total**4,233.87****0.00****SPECIAL NETT**

1	REVERSE SENSOR	380.00	200
1	REVERSE CAMERA	480.00	X
10	REAR BUMPER CLIPS	50.00	
1	REAR END PANEL SEALANT	50.00	X
1	REAR WINDSCREEN SEALANT	50.00	40
1	REAR WINDSCREEN INNER SEAL	50.00	30
1	REAR WINDSCREEN PRIMER & CLEANER	50.00	X

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000268**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 07-FEB-2020
 MAKE : HONDA
 MODEL : VEZEL 1.5X CVT
 CHASSIS NO : RU11112152
 ENGINE NO : L15B4032157
 SERVICE ADVISOR : SHARIFAH
 PAGE : 2 OF 2

SLD5036B**MR YANG WEIHAI**

BLK 494B TAMPINES

AVENUE 9

#07-460

SINGAPORE 520494

CONTACT NO : 82980964

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
	Sub Total	1,110.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,200.00	600
1	TO SPRAY PAINT ON AFFECTED AREAS	1,200.00	600
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	50
1	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS	150.00	120
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00	40
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	120.00	40
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	250.00	60
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	150.00	80
1	TO CHECK WIRING	150.00	20
	Sub Total	3,490.00	0.00

I, the undersigned, certify that the above
 is a true and correct estimate of the
 cost of the repair work to be carried out
 on the vehicle described above, and that
 the estimate is based on the information
 provided by the insured and the surveyor.
 I further certify that the estimate is
 valid for a period of 30 days from the
 date of issue, and that it is subject to
 the terms and conditions of the insurance
 policy.

Authorised Signatory
 Signature: _____
 Date: _____

P- 1730.37
 20%
 9-1384.28
 S. + 320.00
 1- 1570.00
 3274.28

SUB-TOTAL	8,833.87	2819	0.00
GST - 7 %	618.37		0.00
TOTAL	9,452.24		0.00

ABWIN SERVICE PTE LTD

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park; Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20002064/Uqf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 21-02-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FS 5947P	Veh. Inspected	SLD 5036B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000577/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11112152	Colour	WHITE
Odometer	97120	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	6 mm
L/H Front Tyre	215/60 R16	FALKEN	6 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/02/2020	Inspection Date	07/02/2020
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 5036B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BADLY DENTED	1,155.00	953.00
1	TAIL GATE LOCK	NOT NECESSARY	172.70	-
1	REAR BUMPER	DENTED	510.07	510.07
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	19.25	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	155.10	-
1	TAIL GATE EMBLEM	NOT NECESSARY	20.70	-
1	TAIL GATE EMBLEM "VEZEL"	NECESSARY	47.30	47.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	453.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	101.50	-
1	TAIL GATE LAMP LH	NOT NECESSARY	291.05	-
1	TAIL LAMP LH	NOT NECESSARY	485.65	-
1	REAR WINDSCREEN MOULDING	NECESSARY	132.00	132.00
1	TAIL GATE LOCK SENSOR	NOT NECESSARY	193.05	-
1	TAIL GATE INNER HANDLE	NOT NECESSARY	27.50	-
1	TAIL GATE WEATHERSTRIP	NOT NECESSARY	101.50	-
1	REAR SMART BUZZER	CRACKED	88.00	88.00
1	REAR EXTENSION PANEL LH	TO REPAIR SEE LABOUR	176.00	-
1	REAR CHASSIS BEAM LH	NOT NECESSARY	104.50	-
	LESS 20% DISCOUNT		-	-346.07
			4,233.87	1,384.30
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (SN)	SHORTED	380.00	200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	30.00
1	REAR WINDSCREEN PRIMER & CLEANER (SN)	NOT NECESSARY	50.00	-
			1,110.00	320.00

Report Ref No. CS/SMO20002064/Uqf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR EXTENSION PANEL LH.		1,200.00	600.00
	TO SPRAY PAINT ON AFFECTED AREAS.		1,200.00	600.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.		150.00	50.00
	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS.		150.00	120.00
	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING. }		120.00	40.00
	TO DISMANTLE,REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING. }		120.00	-
	TO DISMANTLE,REPLACE AND/OR REPAIR TAILGATE COMPONENTS.		250.00	60.00
	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY.		150.00	80.00
	TO CHECK WIRING.		150.00	20.00
			3,490.00	1,570.00
	GRAND TOTAL		8,833.87	3,274.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/SMO20002064/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.