



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

Sompo Insurance Pte. Ltd. 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Maung Maung Zaw ADDRESS : Blk 311 Canberra Road #11-153 Singapore 750311 TEL : 98793178		WIP : 61797 EXCESS : DATE: 4-Feb-20	
VEH NO :	SMP4649P	DATE IN :		CONTACT PERSON :	Eva 63310683
CHASSIS NO :	JM6GL1072K0318793	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	26-Sep-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGSK1-50-221ABB		\$ 1,099.00
2	RETAINER RHS	1	MGJR9-50-2H1		\$ 41.00
3	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
4	COVER UNDER, REAR BUMPER	1	MGSH7-50-C51		\$ 122.20
5	REAR REINFORCEMENT	1	MGHK1-50-260		\$ 538.30
6	RIVET, REAR BUMPER	2	MTK21-50-355		\$ 18.40
7	RIVET, REAR BUMPER	6	MEA01-50-037		\$ 48.00
8	FASTENER, REAR BUMPER	6	MB45A-56-146A		\$ 18.00
9	GROMME, REAR BUMPER	2	M9991-00-501		\$ 6.00
10	GROMME, REAR BUMPER	1	MBHN1-50-0Z1A		\$ 2.70
11	CLIP, REAR BUMPER	4	MC274-50-133		\$ 14.80
12	RUBBER SEAL, REAR BUMPER	2	MGSH7-50-2G1		\$ 27.40
13	RETAINER SIDE, SENSOR	1	MKD47-67-UC5A83		\$ 18.20
14	SENSOR SIDE, ULTRASONIC	1	MKD47-67-UC1 83		\$ 203.60
15	TAPE PROTECTOR, SENSOR	4	MBCKA-50-EM1		\$ 18.80
16	TAILLAMP RHS	1	MGJ4-51-150B		\$ 1,672.70
17	FASTENER, TAILLAMP	1	MKD53-51-146B		\$ 4.10
18	FASTENER, TAILLAMP	1	MGHP9-51-146		\$ 3.50
19	FASTENER, TAILLAMP	1	MGJ6A-51-14Y		\$ 15.70
20	GASKTE LHS, TAILLAMP	1	MGRF5-51-163		\$ 46.00
21	GASKTE RHS, TAILLAMP	1	MGRF5-51-153		\$ 46.00
22	PANEL LWR RHS	1	MGHY1-70-40X		\$ 325.90
23	EXTRACTOR VENT	1	MD350-51-920A		\$ 74.90
24	GUARD STONE RHS	1	MGHP9-50-4P2A		\$ 17.40
TOTAL PARTS					\$ 4,388.00
TOTAL PARTS COST					\$ 4,388.00
Labour Description					

1		TO REPLACE REAR BUMPER, REAR REINFORCEMENT. TO REPAIR PANEL LOWER RH, REAR END PANEL, REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 3,300.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, PANEL LOWER RH, REAR END PANEL, REAR FENDER RH.		\$ 2,520.00
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	NETT	\$ 330.00
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 990.00
5	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00
9		TO SUPPLY BRILA PREMIUM COATING.	NETT	\$ 250.00
10	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 8,690.00
TOTAL PARTS	\$ -	\$ 4,388.00
TOTAL	\$ -	\$ 13,078.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature