

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28332

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0136/2020/NS
Date : 5-Feb-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tok Chun Wei Jeffrey
Address : 311 Ang Mo Kio Avenue 3
#10-2114
Singapore 560311
Telephone : HP +65 98518206
Type of Claim : Own Damage Claims
Policy No. : 1900167022
Vehicle No : **SMP 4729 S**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Sep-19
Engine No : CVK 085982
Chassis No : WAUZZZF4XKA102525
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-20
Place of Accident : SLE Towards BKE Before Turf Club Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 5366 2323 Fax: 6641 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMP 4729 S

S/N Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1. To tow vehicle from scene of accident.	S/N \$ 220.00 ✓	
2. To remove and install front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
3. To remove and renew, aircon condenser, turbo cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
4. To remove and reinstall centre console. Renew both front seat belts and airbag control unit.	S/N \$ 1,800.00 X	
5. To remove and reinstall engine assy with gearbox assy to facilitate cellete bench repairs.	S/N \$ 2,800.00 ✓ <i>plus</i>	
SUB TOTAL LABOUR CHARGES		<u>\$ 6,560.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6356 2323 Fax: 6841 1103

Telefax

Estimated Labour Charges for Accident Vehicle SMP 4729 S

Steve
19/2/21

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	to inspect engine for damages. Renew turbo charger assy and damaged components.	S/N \$ 1,400.00 ? photo	/
7	to remove and reinstall front suspension assy with subframe to facilitate cellete bench repairs. Inspect for damages and renew if necessary.	S/N \$ 2,400.00 ? photo	/
8	To place vehicle on cellete bench.	S/N \$ 1,200.00 ? photo	/
9	To dismantle front bumper, bonnet and both front fenders. Align both front chassis frames to specification of origin. Renew front lock carrier. Renew damaged panels. Re-organise front crash management components. Reinstall all parts removed.	\$ 8,400.00 3000	
10	To dismantle both front door panel trims, remove both wing mirror assy and renew window chrome moldings.	S/N \$ 700.00	/
SUB TOTAL LABOUR CHARGES		\$ 14,100.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMP 4729 S

S/N Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1. To respray front bumper, both front fenders, bonnet, hinges, both A-pillars, engine compartment and both front doors.	\$ 7,600.00	4950
12 To carry out wheel alignment	S/N \$ 240.00	? plus
13 To carry out diagnostic check	S/N \$ 384.00	192
TOTAL LABOUR CHARGES	\$ 28,884.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4729 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>turn</i>	\$	2,068.00	
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$	553.00	
3	FRONT BUMPER GRILLE - CENTRE <i>neu</i>	\$	185.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$	198.00	
5	FRONT BUMPER AIR GUIDE - LH / RH <i>mis</i>	2 \$	118.00	
6	RADIATOR GRILLE <i>neu</i>	\$	1,254.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>mis</i>	2 \$	254.00	
8	FRONT BUMPER FOAM FILLER PIECE <i>X neu</i>	\$	117.00	
9	FRONT BUMPER CARRIER <i>bt</i>	\$	757.00	
10	FRONT BUMPER SUPPORT - LH / RH <i>neu</i>	2 \$	54.00	
11	LOCK CARRIER BRACKET <i>neu</i>	\$	129.00	
12	FRONT BUMPER COVER <i>neu</i>	\$	120.00	
13	BOWDEN CABLE <i>neu</i>	\$	54.00	
14	RELEASE LEVER <i>?</i>	\$	13.00	
15	CAUTION SIGN STICKER <i>neu</i>	NEC \$	13.00	
16	AIRCON STICKER <i>neu</i>	NEC \$	7.00	
17	FRONT BUMPER BRACKET - LH / RH <i>neu</i>	2 \$	428.00	
18	FRONT BUMPER GUIDE SECTION - LH <i>bt</i>	\$	34.00	
19	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	\$	36.00	
20	FRONT FENDER - LH / RH <i>LH-R / RH-bt</i>	21 \$	1,444.00	722
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,836.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

		Damage Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
21	FRONT FENDER ATTACHMENT PARTS ?	5	380.00
22	FRONT FENDER CLOSING ELEMENT LH / RH LH-X / RH-?bt 2	2 \$	94.00
23	FRONT FENDER BRACKET - LH / RH LH-X / RH-? X nm	2 \$	66.00
24	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH X nm	5	92.00
25	FRONT FENDER BRACE - LH / RH LH-X / RH-? X nm	2 \$	224.00
26	FENDER LEDGE COVER - LH / RH nee	2 \$	42.00
27	FENDER LEDGE TOP COVER LH / RH X nm	2 \$	58.00
28	FRONT WHEEL HOUSING LINER - LH X nm	\$	226.00
29	FRONT WHEEL HOUSING LINER - RH X nm	\$	228.00
30	WHEEL HOUSING LINER ATTACHMENT PARTS X nm	2 \$	438.00
31	WHEEL SPOILER - LH / RH X nm	2 \$	138.00
32	STONE CHIP GUARD - LH / RH X nm	2 \$	96.00
33	LED HEADLIGHT - LH / RH br ? short	2 \$	14,642.00
34	MAIN LIGHTS POWER MODULE ? short	2 \$	1,463.00
35	LIGHT CONTROL SYSTEM CONTROL UNIT ? short	2 \$	1,414.00
36	HEADLAMP DRAIN HOSE - LH / RH ?	2 \$	68.00
37	HEADLAMP ASSEMBLY SPACER nee	2 \$	79.00
38	HEADLAMP ASSEMBLY SPACER nee	2 \$	75.00
39	HEADLAMP ASSEMBLY SPACER nee	2 \$	75.00
40	BONNET bree	\$	2,634.00
SUB TOTAL SPARE PARTS CHARGES		: \$ 22,532.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4729 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
41	BONNET IMPACT PROTECTION - LH <i>ne</i> ✓	\$	26.00	
42	BONNET IMPACT PRTECTION - RH <i>ne</i> ✓	\$	26.00	
43	BONNET IMPACT PROTECTION - CENTRE <i>ne</i> ✓	\$	26.00	
44	BONNET ATTACHMENT PARTS <i>X nn</i>	\$	388.00	
45	BONNET LID HINGE - LH / RH <i>?</i>	2 \$	574.00	
46	FENDER LEDGE COVER - LH / RH INNER <i>X nn</i>	2 \$	116.00	
47	BONNET GAS FILLED STRUT <i>X nn</i>	2 \$	224.00	
48	BONNET STRIKER - LH / RH <i>RH-BT / LH-? BT</i> ✓	2 \$	94.00	
49	BONNET LID LOCK <i>BT</i> ✓	2 \$	403.00	
50	FLAT CONNECTOR HOUSING <i>?</i>	2 \$	25.00	
51	BONNET BOWDEN CABLE - CENTRE <i>act</i> ✓	\$	54.00	
52	BONNET LID LOCK CABLE <i>act</i> ✓	\$	69.00	
53	BONNET SOUND ABSORBER <i>de</i> ✓	\$	323.00	
54	LOCK CARRIER <i>ca</i> ✓	\$	956.00	
55	RADIATOR OUTER DUCT - LH <i>ca</i> ✓	\$	27.00	
56	RADIATOR INNER DUCT - LH <i>ca</i> ✓	\$	12.00	
57	RADIATOR OUTER DUCT - RH <i>ca</i> ✓	\$	27.00	
58	RADIATOR INNER DUCT - RH <i>ca</i> ✓	\$	12.00	
59	RADIATOR AIR GUIDE - UPPER <i>ca</i> ✓	\$	15.00	
60	RADIATOR AIR GUIDE - LOWER <i>? MIS</i> ✓	\$	21.00	
SUB TOTAL SPARE PARTS CHARGES		\$	3,418.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4729 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
61	EXTERNAL TEMPERATURE SENSOR BRACKET ? <i>ca</i> ✓	\$	18.00	
62	EXTERNAL TEMPERATURE SENSOR ?	\$	55.00	
63	FRONT PARKING AID SENSOR - INNER / OUTER <i>phant</i> ✓ <i>A2</i>		TBC	
64	FRONT BUMPER WIRING SET <i>cut</i> ✓	\$	480.00	
65	CHARGE AIR COOLER <i>bt</i> ✓	\$	552.00	
66	CHARGE AIR COOLER PRESSURE PIPE - LH <i>X</i> <i>nn</i>	\$	402.00	
67	CHARGE AIR COOLER PRESSURE PIPE - RH ?	\$	336.00	
68	AIRCON CONDENSER <i>bt</i> ✓	\$	586.00	
69	REFRIGERANT LINE PRESSURE SENDER ?	\$	179.00	
70	HIGH PRESSURE SAFETY SWITCH VALVE <i>X</i> <i>nn</i>	\$	49.00	
71	RADIATOR <i>bt</i> ✓	\$	766.00	
72	RADIATOR SLEEVE - UPPER <i>acc</i> ✓	2 \$	16.00	
73	RADIATOR RUBBER BUSH - LOWER <i>acc</i> ✓	2 \$	17.00	
74	RADIATOR LOWER MOUNT <i>acc</i> ✓	2 \$	24.00	
75	RADIATOR FAN RING ? <i>ca</i> ✓	\$	240.00	
76	RADIATOR FAN ? <i>ca</i> ✓	\$	1,877.00	
77	WINDOW SLOT SEAL - LH / RH <i>cut</i> ✓	2 \$	578.00	
78	AIR FILTER <i>cut</i> ✓	\$	362.00	
79	INTAKE AIR DUCT - RH <i>ca</i> ✓	\$	21.00	
80	AIR GUIDE <i>ca</i> ✓	\$	50.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 6,608.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4729 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
81	INTAKE HOSE ? cut ✓	\$	90.00	
82	TURBOCHARGER ca ✓	\$	5,085.00	
83	HOT BOLT PASTE ne ✓	\$	213.00	
84	TIMING COVER ? bt ?	\$	176.00	
85	CAMSHAFT ADJUSTER MAGNET ?	2 \$	335.00	
86	TURN SIGNAL LAMP CONNECTOR ?	4 \$	36.00	
87	TIMING CASE ? bt ✓	\$	264.00	
88	VIBRATION DAMPER ? sc ✓	\$	405.00	
89	BELT TENSION DAMPER ?	\$	137.00	
90	SEPERINE BELT ?	\$	49.00	
91	ALTERNATOR X nn	\$	2,757.00	
92	SEAT BELT - LH / RH X nn	2 \$	2,080.00	
93	SEAT BELT HEIGHT ADJUSTER X nn	2 \$	329.00	
94	AIRBAG CONTROL UNIT X nn	\$	1,986.00	
95	AIRBAG CRASH SENSOR - FRONT X nn	2	TBC	
96	CENTRAL PROTECTION X nn	\$	500.00	
97	COOLANT REGULATOR SUPPORT ✓	2 \$	71.00	
98	FRONT NO PLATE mis ✓ (Owner Supply)	S/N \$	60.00	
99	SUNDRIES ?	\$	2,000.00	

TOTAL SPARE PARTS CHARGES

TOTAL LABOUR CHARGES

GRAND TOTAL

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

: \$ 56,967.00
: \$ 28,884.00
: \$ 85,851.00

98,514

49714

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Lasu - Hp 90010068

06/02/2020 @ 1210

18 days

EXCESS: TBA

REPAIR

Resurvey before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMP 4729 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>turn</i>	\$	2,068.00	
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$	553.00	
3	FRONT BUMPER GRILLE - CENTRE <i>neu</i>	\$	185.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$	198.00	
5	FRONT BUMPER AIR GUIDE - LH / RH <i>mis</i>	2 \$	118.00	
6	RADIATOR GRILLE <i>neu</i>	\$	1,254.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>mis</i>	2 \$	254.00	
8	FRONT BUMPER FOAM FILLER PIECE <i>X</i>	\$	117.00	
9	FRONT BUMPER CARRIER <i>bt</i>	\$	757.00	
10	FRONT BUMPER SUPPORT - LH / RH <i>neu</i>	2 \$	54.00	
11	LOCK CARRIER BRACKET <i>neu</i>	\$	129.00	
12	FRONT BUMPER COVER <i>de</i>	\$	120.00	
13	BOWDEN CABLE <i>act</i>	\$	54.00	
14	RELEASE LEVER <i>?</i>	\$	13.00	
15	CAUTION SIGN STICKER <i>neu</i>	NEC \$	13.00	
16	AIRCON STICKER <i>neu</i>	NEC \$	7.00	
17	FRONT BUMPER BRACKET - LH / RH <i>neu</i>	2 \$	428.00	
18	FRONT BUMPER GUIDE SECTION - LH <i>bt</i>	\$	34.00	
19	FRONT BUMPER GUIDE SECTION - RH <i>?</i> <i>OR</i>	\$	36.00	
20	FRONT FENDER - LH / RH <i>LH-R / RH-bt</i>	2 \$	1,444.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,836.00	

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims | Regn No

Tel: 6841 0055 - Fax: 6256 4315 Model No

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

6-Feb-20

Raymond Ting

1 of 1

SMP 4729 S

Audi A4 SEDAN 2.0 TFSI 8W

Quantity Description

Unit Price

Amount

Labour

1 To dismantled and renew both headlight.

\$ 700.00

\$ 700.00

TOTAL

\$ 700.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims I

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

6-Feb-20

Raymond Ting

1 of 1

SMP 4729 S

Audi A4 SEDAN 2.0 TFSI 8W

Quantity Description

Unit Price

Amount

Labour

1 To dismantled and renew both headlight.

\$ 700.00

\$ 700.00

TOTAL

\$ 700.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

14-Feb-20

Glory Tan

1 of 1

SMP 4729 S

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Shock absorber mounting LHS <i>bl</i>	\$ 59.00	46.72
2	Shock absorber mounting RHS <i>bl</i>	\$ 59.00	46.72
3	Front bumper securing strips <i>ms</i>	\$ 67.00	53.96
4	Lift cylinder RHS <i>cr</i>	\$ 198.00	158
5	Bracket for lift cylinder RHS <i>Xnn</i>	\$ 12.00	
6	Lift cylinder hose <i>cut</i>	\$ 88.00	69.68
7	Ready mix-coolant -25"c <i>ne</i>	\$ 169.00	134.72
8	Air mass meter <i>cr</i>	\$ 546.00	436.40
9	Coolant pipe - return <i>cut</i>	\$ 91.00	72.24
10	Silicone sealant <i>nee</i>	\$ 116.00	92.16
11	Tube for oil dipstick <i>cut</i>	\$ 106.00	84.40
12	Engine mounting RHS <i>cr</i>	\$ 397.00	317.60
13	Hexagon head bolt (combi) <i>na</i>	\$ 46.00	36.16
14	Single wire seal lead with 1 contact in the bag -1500MM <i>cut</i>	\$ 465.00	372
15	1 set single wires each with 2 silver-plated contacts <i>cut</i>	\$ 251.00	200.80
16	Cable guide for headlamps <i>ms</i>	\$ 19.00	14.48

Labours

1	To cut out and weld both front shock absorber mountings.	\$ 1,050.00	500 x
---	--	-------------	-------

Labours total	\$ 1,050.00
Parts total	\$ 2,689.00
TOTAL	\$ 3,739.00

For Premium Automobiles Pte Ltd

Authorised Signature

Rasul

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 18/2/20, 4.00pm

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0136/2020/NS

14-Feb-20

Glory Tan

1 of 1

SMP 4729 S

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Engine mounting LHS / BR	\$ 397.00	317.60
2	Hexagon head bolt (combi) / MC	\$ 46.00	X
3	Gearbox mounting (Rear) / BR	\$ 199.00	159.60
4	Gearbox support (Rear) / MC	\$ 77.00	61.20
5	Stop (Rear) / BR	\$ 61.00	48.64
6	Transmission oil sump / BR	\$ 323.00	258.40
7	Hex socket head bolt (combi) / MC	\$ 65.00	52
8	Coolant hose feed/return / ?	\$ 25.00	19.60
9	Potential distributor fuse / Short (Battery cable)	\$ 500.00	400
10	Guard plate RHS / DD	\$ 30.00	23.92
11	Dual clutch transmission fluid atf 1.0 Ltr / MC	\$ 847.00	677.60
12	Retainer for exhaust pipe / ?	\$ 33.00	26.16
13	Hexagon bolt / MC	\$ 70.00	55.68

Labours

1	To renew engine mounting, gearbox mounting, transmission oil sump and potential distributor fuse.	S/N \$ 600.00 / ✓
---	---	-------------------

Labours total	\$ 600.00
Parts total	\$ 2,673.00
TOTAL	\$ 3,273.00

For Premium Automobiles Pte Ltd

add
chassis member LH (To repair)

repair day (TBA)

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 19/2/20

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

19-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Coolant pipe / TN	\$ 67.00	53.44
2	Exhaust pipe with front silencer / DO	\$ 863.00	690.40
3	Seal / APC	\$ 11.00	8.48
4	Heat shield for bulkhead / TN	\$ 106.00	84.80

Labours

- 1 To remove and renew exhaust pipe with front silencer. Align to position.

S/N \$ 480.00 ✓

TOTAL

\$ 1,527.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

24-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
Parts			
1	Subframe cross member <i>cm /</i>	\$ 602.00	481.60
2	Socket head bolt with inner multipoint head <i>na /</i>	\$ 22.00	19.96

TOTAL

\$ 624.00

For Premium Automobiles Pte Ltd

Authorised Signature

Pam
25/02/2020
add ~~extra~~ xtra
4 days

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia-Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

25-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

- | | | | |
|---|------------------------|-----|------------------------------|
| 1 | Lhs front tyre | TBC | <i>✓ TN 3 X inconsistent</i> |
| 2 | Tyre monitoring system | TBC | <i>✓ m</i> |

Labours

- | | | | |
|---|---|-------------|--|
| 1 | To repair and respray front lhs chassis member. | \$ 2,800.00 | <i>1550 X</i>
<i>check with Rasal</i> |
|---|---|-------------|--|

TOTAL

\$ 2,800.00

For Premium Automobiles Pte Ltd

Authorised Signature

Steve
26/2/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

27-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Engine support bearing RHS <i>bl</i>	\$ 64.00	<i>50.88</i>

TOTAL

\$ 64.00

For Premium Automobiles Pte Ltd

Rare
27/02/2020

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

3-Mar-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Lift cylinder LHS ? see photo CM ✓	\$ 198.00	158

TOTAL

\$ 198.00

For Premium Automobiles Pte Ltd

Authorised Signature

Stene
3/3/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0136/2020/NS

Date

3-Mar-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMP 4729 S

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Noise insulation rear <i>hu</i> ✓	\$ 371.00	296.40
2	Noise insulation front <i>hu</i> ✓	\$ 537.00	429.60

TOTAL

\$ 908.00

For Premium Automobiles Pte Ltd



Authorised Signature