



Kh

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Page 1 / 2

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HAI HOCK DONALD
BLK 113 RIVERVALE WALK #14-43
SINGAPORE 540113

Attention : THE OWNER
Contact : 97281488

Not Notion
11 Lmp @ 3750k
Pruning After Rain
4 day

Estimate : ES006917

Date : 05/02/2020
Vehicle Num. : SJN4452K
Make/Model : NISSAN TEANA 2.0-2009
Chassis/Eng# : JN1BDUJ32Z0000572/MR20678938A
Accident Date : 04/02/2020
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

		NETT ITEMS :		
1.	1	BONNET		B ₁ 1,050.00 —
2.	1	BONNET LOCK		R 325.00 X
3.	1	RADIATOR GRILLE	452.80	na 642.00 —
4.	1	HEADLAMP L/H	586.10	cm 830.00 —
5.	1	HEADLAMP BRACKET L/H	676.10	R 186.00 X
6.	1	FRONT BUMPER		Bul/cm 955.00 —
7.	1	FRONT BUMPER REINFORCEMENT		R 683.00 X
8.	1	FRONT BUMPER SPONGE		in 176.00 X
9.	1	FOG LAMP L/H	320.70	mg/cm 460.00 —
10.	1	FRONT BUMPER LOWER COVER GARNISH L/H	107.50	DI 288.00 —
		Nett Total S\$:		5,595.00
		10.00% Discount S\$:		559.50
				5,035.50

		SPECIAL NETT ITEMS :		
1.	1	RADIATOR GRILLE LOGO		na 63.00 —
2.	2	HEADLAMP CLIP L/H		5.50 na 11.00 —
3.	6	FRONT BUMPER CLIP		5.00 na 30.00 —
4.	2	FRONT BUMPER CHROME MOULDING	@ 121.20	na 232.00 464.00 —
5.	2	FRONT BUMPER BRACKET		211.00 R 422.00 X
6.	1	FOG LAMP GARNISH L/H		in 163.00 X
7.	1	FRONT NUMBER PLATE		in 25.00 X
8.	1	FRONT NUMBER PLATE GARNISH		na 184.00 —
9.	1	FRONT NUMBER PLATE HOLDER		na 33.00 —
		Special Nett Total S\$:		1,395.00
		LABOUR :		20/
		CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION		90.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HAI HOCK DONALD
BLK 113 RIVERVALE WALK #14-43
SINGAPORE 540113

Attention : THE OWNER
Contact : 97281488

Estimate : ES006917

Date : 05/02/2020
Vehicle Num. : SJN4452K
Make/Model : NISSAN TEANA 2.0-2009
Chassis/Eng# : JN1BDUJ32Z0000572/MR20678938A
Accident Date : 04/02/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		RUST PROOFING TREATMENT		
		SPRAY PAINT DAMAGED AREA AFFECTED		
		TO KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND CHANGE		
		ALL NECESSARY PARTS		
		Labour Total S\$:		

Handwritten notes on the right side of the table:
301
450/ 100.00
900.00
500/ 980.00
2,070.00

SingDollars : Eight Thousand Five Hundred & Cents Fifty Only

Total S\$: 8,500.50
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD *The Premier One-Stop Vehicle Accident Claims Centre*
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HAI HOCK DONALD
BLK 113 RIVERVALE WALK #14-43
SINGAPORE 540113

Attention : THE OWNER

Contact : 97281488

Supplementary Estimate : ES006919

Date : 07/02/2020
Vehicle Num. : SJN4452K
Make/Model : NISSAN TEANA 2.0-2009
Chassis/Eng# : JN1BDUJ32Z0000572/MR20678938A
Accident Date : 04/02/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS : FRONT BUMPER TOP BEAM		286.20 ✓
		Nett Total S\$:		286.20
		10.00% Discount S\$:		28.62
				257.58

SingDollars : Two Hundred Fifty-Seven & Cents Fifty-Eight Only

Total S\$: 257.58
=====


COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun