



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

IMMIGRATION & CHECKPOINTS AUTHORITY
SINGAPORE

Ref : CS/ICA20002096/Gvd3s2

Date : 08-04-2020



Code : ICA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.		Veh. Inspected	FBK 2239J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MUHHAAMAD HAKIMULLAH	Assign Date	06/02/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. F800GS	c.c	798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WB10B0506EZ303335	Colour	BLACK / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/90-21	MICHELIN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70 R17	MICHELIN	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2017	Inspection Date	06/02/2020
Survey held at	TRAXX MOTOR-9 TAGORE LANE #04-02		
Repairer	-		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**