

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5670S**AAD2002-009***Not Authorised**Resurvey B4 paint**\$ 967.95*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

05 FEB 2020**SHD 5670S**

JTDKB3FU803079222

TOYOTA

PRIUS

1.2.2020

III

17/1/2019

| | PART |
|---|---------------------------------|
| 1 | REAR BUMPER |
| 1 | REAR BUMPER RE-INFORCEMENT |
| 1 | REAR BUMPER TOWING COVER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | REAR BUMPER SIDE RETAINER LH |
| 1 | REAR BUMPER SIDE RETAINER RH |
| 1 | REAR TAILGATE |
| 1 | REAR TAILGATE OUTER GARNISH |
| 1 | REAR TAILGATE WEATHERSTRIP |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK |
| 1 | TAILLAMP LOWER RH |
| 1 | TAILLAMP UPPER RH |
| 1 | REAR BUMPER SIDE RH |
| 1 | REAR BUMPER SIDE LH |
| 1 | TAILLAMP LOWER LH |
| 1 | TAILLAMP UPPER LH |
| 1 | COVER, DECK TRIM, REAR |
| 1 | COVER, FLOOR UNDER, NO 1 |
| 1 | COVER, FLOOR UNDER, NO 2 |
| 1 | COVER, REAR FLOOR |

| | LIST |
|--------------|-------------------------|
| \$ | <i>nd / lw</i> 442.60 — |
| \$ | <i>R</i> 332.70 X |
| \$ | <i>sn</i> 15.40 X |
| \$ | <i>sn</i> 576.30 |
| \$ | <i>sn</i> 116.50 |
| \$ | <i>sn</i> 117.70 |
| \$ | <i>R</i> 1,147.80 |
| \$ | <i>sn</i> 925.60 |
| \$ | <i>sn</i> 372.30 |
| \$ | <i>R</i> 650.30 |
| \$ | <i>sn</i> 502.00 |
| \$ | <i>sn</i> 451.80 |
| \$ | <i>sn</i> 123.70 |
| \$ | <i>sn</i> 123.70 |
| \$ | <i>sn</i> 502.00 |
| \$ | <i>sn</i> 443.30 |
| \$ | <i>sn</i> 126.70 |
| \$ | <i>sn</i> 175.10 |
| \$ | <i>sn</i> 241.90 |
| \$ | <i>sn</i> 229.90 |
| TOTAL | \$ 7,617.30 |
| 25% | \$ 1,904.33 |
| | \$ 5,712.98 |

Special Nett

1SET PARKING AID

\$ *sn* 700.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5670S**AAD2002-009**

| | | | | | |
|--------------|-----------------------------------|-----------|-----------|-----------------|-------------|
| 1SET | REAR BUMPER CLIP | \$ | <i>nn</i> | 66.00 | — |
| 1 | REAR TAILGATE TOYOTA LOGO | \$ | <i>nn</i> | 47.00 | X |
| 1 | REAR TAILGATE WORDING 'PRIUS' | \$ | <i>nn</i> | 52.90 | X |
| 1 | REAR TAILGATE WORDING 'HYBRID' | \$ | <i>nn</i> | 53.50 | X |
| 1 | REAR TAILGATE STICKER 'TRANS-CAB' | \$ | <i>nn</i> | 80.00 | X |
| 1 | REAR TAILGATE STICKER '6555-3333' | \$ | <i>nn</i> | 80.00 | X |
| 1 | REAR BUMPER PROTECTOR | \$ | <i>nn</i> | 100.00 | <i>3000</i> |
| 1 | REAR WHEEL RIM | \$ | <i>nn</i> | 1,879.40 | X |
| 1 | REAR TYRE 195/65/15 | \$ | <i>nn</i> | 350.00 | X |
| 1 | REAR WHEEL RIM COVER | \$ | <i>nn</i> | 211.50 | X |
| 1 | REAR RH BUMPER RETAINER CLIP | \$ | <i>nn</i> | 35.00 | X |
| 1 | REAR LH BUMPER RETAINER CLIP | \$ | <i>nn</i> | 35.00 | X |
| TOTAL | | \$ | | 3,690.30 | |

TOTAL PARTS \$ 9,403.28**LABOUR**

| | | | | |
|---|----|-----------|----------|-------------|
| To transfer of Tailgate fittings, attachments and perform water seepage test. | \$ | <i>nn</i> | 170.00 | X |
| To transfer of Rear Bumper fittings, attachments and perform water seepage test. | \$ | <i>nn</i> | 170.00 | X |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | <i>nn</i> | 170.00 | X |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | <i>nn</i> | 380.00 | X |
| To check steering geometry and computer wheel alignment | \$ | <i>nn</i> | 220.00 | X |
| Putty And Spray Painting Of The Affected Portion. | \$ | <i>nn</i> | 6,000.00 | <i>2800</i> |
| To Rust-Proofing Of The Affected Areas. | \$ | <i>nn</i> | 170.00 | X |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report the accident to the nearest police station as soon as possible.

2. The insurance company will only pay for the damage to the insured vehicle.

3. The insurance company will not pay for the damage to the other vehicle.

4. The insurance company will not pay for the damage to the property.

5. The insurance company will not pay for the damage to the person.

6. The insurance company will not pay for the damage to the vehicle.

7. The insurance company will not pay for the damage to the property.

8. The insurance company will not pay for the damage to the person.

9. The insurance company will not pay for the damage to the vehicle.

10. The insurance company will not pay for the damage to the property.

Trans-cab Auto Services Pte Ltd

AAD2002-009

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5670S

To reinstall rear bumper parking sensor. \$ 170.00 *501*

To transfer of tire, rim and on wheel balancing. \$ 170.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. \$ 380.00 *X*

To Check Electrical Lighting Concerned. \$ 170.00 *101*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *2001*

TOTAL \$ 14,170.00

Over All Total \$ 23,573.28

(PART-BY-PART) Repair Days

20 Days

2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Driver

NRIC No

Date Of Birth

Occupation

Date Of Driving Pass

Driving Experience

Gender

Mobile Number

Fax Number

Contact Number

Email Address