

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002100/ADA3Q2
Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994112
Claimant
Vehicle No : SGR7888G **Insured Vehicle No :** GBG1357D
 Date of Loss: 31/01/2020 Nature of Claim: TP Claim No: 2440126570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR7888G**
 Make & Model: BMW 523I, 2.5 (A) Engine No: 07587395N52B25AF
 Reg. Date: 31/05/2010 (Man. Year: 2010) Chassis No: WBAFP320X0C544036
 Colour: Black Odometer: 187218 km
 Engine Capacity: 2497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,260.04	3,848.26	3,411.78	46.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,660.00	940.00	36.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,860.04	5,508.26	4,351.78	44.14
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	9,860.04	4,400.00	5,460.04	55.38
+ Loss of Use (8.0 x S\$120.00/day) (S\$)		960.00		
		(S\$) 5,360.00		
Liabe Amount (50.00%) (S\$)		2,680.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,687.45		

INSPECTION

Date of Assignment: 05/02/2020
 Date Inspected: 05/02/2020 Inspected At: Zero Gravity (Kaki Bukit)
 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit
 Autohub
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: CHAN JIA LE

Manager: ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER (R/H/R)	Dented	1,101.50 FL	*1,101.50 FL
2	1		*FENDER INNER GARNISH (R/H/R)	Deformed	115.00 FL	*115.00 FL
3	1		*SPORT RIM (R/H/R)	Cut	1,123.80 FL	*1,123.80 FL
4	1		*LOWER ARM (R/H/R)	Not Necessary	375.20 FL	*- FL
5	1		*LOWER LINK (REAR) (R/H) (SHORT)	Not Necessary	112.50 FL	*- FL
6	1		*LOWER LINK (REAR) (R/H) (LONG)	Not Necessary	346.50 FL	*- FL
7	1		*KNUCKLE (REAR) (R/H)	Not Necessary	1,273.20 FL	*- FL
8	1		*WHEEL BEARING (R/H/R)	Not Necessary	203.55 FL	*- FL
9	1		*REAR BUMPER	Deformed	1,560.50 FL	*1,560.50 FL
10	1		*BUMPER SIDE RETAINER (R/H/R)	Cracked	856.40 FL	*120.00 FL
11	1		*SET BUMPER BEAM SCREW /INNER CLIPS	Necessary	90.00 FL	*30.00 FL
12	1		*REAR BUMPER TOP RETAINER	Not Necessary	84.00 FL	*- FL
13	1		*TYRE (R/H/R)	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,622.15	4,050.80
- List Item Discount on L Items 5.00/5.00% (\$)	362.11	202.54
Total Parts (\$)	7,260.04	3,848.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & REPLACING OF THE ABOVE	New	1,000.00	700.00
2	TO PUTTY AND RESPRAY AFECTED PORTION	New	700.00	600.00
3	TO PROVIDE UNDER TURCOAT	New	120.00	80.00
4	TO REMOVE AND REFIT COMPONENTS /FACILITATE THE REPAIR	New	180.00	80.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
6	TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	New	300.00	0.00
7	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	New	150.00	80.00
			Gross Labour Cost (\$\$)	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >