



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 5288887X

QUOTATION

No : QT-000213

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Jimie

Your Ref. : GBG1357D
 Vehicle No. : SGR7888G
 Make & Model : BMW 523I
 Chasis No. : WBAFP320X0C544036
 Engine No. : 07587395N52B25AF
 Accident Date : 31-01-2020
 Policy No. : 2019-V0104470-VDP-R001
 Date : 06-02-2020
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	FENDER (R/H/R) <i>certed</i>	1.0	PCS 1,101.50	✓ 1,101.50
2	FENDER INNER GARNISH (R/H/R) <i>reld</i>	1.0	PCS 115.00	✓ 115.00
3	SPORT RIM (R/H/R) <i>nt</i>	1.0	PCS 1,123.80	✓ 1,123.80
4	LOWER ARM (R/H/R)	1.0	PCS 375.20	+ 375.20
5	LOWER LINK (REAR) (R/H) (SHORT)	1.0	PCS 112.50	+ 112.50
6	LOWER ARM (REAR) (R/H) (LONG)	1.0	PCS 346.50	+ 346.50
7	KNUCKLE (REAR) (R/H)	1.0	PCS 1,273.20	+ 1,273.20
8	WHEEL BEARING (R/H/R)	1.0	PCS 203.55	+ 203.55
9	REAR BUMPER <i>reld</i>	1.0	PCS 1,560.50	✓ 1,560.50
10	BUMPER SIDE RETAINER (R/H/R) <i>could</i>	1.0	PCS 856.40	120 856.40
11	BUMPER BEAM SCREW/INNER CLIPS SET <i>me</i>	1.0	SET 90.00	30 90.00
12	REAR BUMPER TOP RETAINER <i>new</i>	1.0	PCS 84.00	+ 84.00
13	Discount 5 %			-1,810.54
14	SubTotal (L)			5,431.61
15	TYRE (R/H/R) <i>new</i>	1.0	PCS 380.00	+ 380.00
16	SubTotal (S)			380.00
17	PANEL BEATING & REPLACING OF THE ABOVE	1.0	X 1,000.00	700 1,000.00
18	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X 700.00	60 700.00
19	TO PROVIDE UNDER TURF COAT	1.0	X 120.00	80 120.00
20	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X 180.00	80 180.00
21	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	X 150.00	120 150.00
22	TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	1.0	X 300.00	+ 300.00
23	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1.0	X 150.00	80 150.00
24	SubTotal (LABOUR)			2,600.00

405080

389826

1660

*total 550826 Admin 4
 A/S: 4 HK A/S 06 Days*

4 HK

LKK Auto Consultants hence notify the Repairer of the Car with:

- To resurvey & re-attest spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date: