




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20002104/Aba3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-08-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8860P	Veh. Inspected	SLT 6602B	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000811MFSH	Excess (\$)	0.00	
Assign From	VIC	Assign Date	05/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71120469	Colour	WHITE	
Odometer	146194	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	MICHELIN	6 mm	
L/H Front Tyre	195/55 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/02/2020	Inspection Date	05/02/2020	
Survey held at	EUNOS MOTOR SERVICE 1 KAKI BUKIT AVE 6 #01-64 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		