

NO:

TP 1st Cap Vic

Date:

SLT6602B

Tailgate Glass Sealant. New	60(SN) ✓
Honda Logo	38 ✓
Shuttle Emblem	55 ✓
Hybrid Emblem.	80.10 ✓
Rear RH Fender Distorted	1010.90 ✓
Rear RH Fender Air Vent Distorted	38 ✓
Rear RH Fender Glass Moulding. } New	72.40 ✓
Rear RH Fender Glass Sealant. }	40(SN) ✓
Rear Fender Inner Trim Board x02 Deland	455x2=910 ✓
Rear Fender Inner Trim Board Clips New	60 ✓
Rear Fender Inner Shield x02 RH angled	110.50x2=221 110.50
Rear Fender Inner Shield Clips. New	60.20
Spare Tyre Panel Distorted	1180 ✓
Spare Tyre Lower Tow Panel. Distorted	398 ✓
Spare Tyre Compartment Tray Garnish. Deland	420.80 ✓
Spare Tyre Side Top Cover Band x02 RH Deland	122x2=244 122
Spare Tyre Tools Tray Sponge Deland	285 ✓
Spare Tyre Top Cover Deland	58550 ✓
Spare Tyre Zip Cover Inner Deland	586.70 ✓
Rear Hybrid Inverter Blower NE New	540 X.
Rear Hybrid Inverter Blower Air Duct. Angled	138.70 ✓
Rear Hybrid Inverter Top Cover	397.70 X
Rear Hybrid Inverter Tray Garnish } New	28540 X
Rear Hybrid Inverter Unit. }	9850 X.
Rear Exhaust Pipe Bent	745 ✓
Rear Exhaust Gasket New	32.80 ✓
Rear Exhaust Mounting x02 NE New	32x2=64 X
Rear Exhaust Heat Shield Angled	725.20 ✓
Centre Exhaust Pipe. Bent	585.40 ✓
Rear Axle Bent	1080 ✓
Rear Wheel Hub w/ Bearing x02 RH and	321x2=642 321
Rear Shock Absorber x02 RH Bent	330x2=660 330
Rear RH Door Lock NE New	210.80 X
Rear RH Chassis Sub Member. Reps	855 X.

NO:

TP 1st Cap Vic

Date:

SLT6602B.

Honda Shuttle

GP71120469.

Rear Number Plate Best	30(SN) ✓
Rear Number Plate Holder Delivered	30(SN) ✓
Rear Number Plate Lamp x02 LHM	$32.8 \times 2 = 65.60$ +
Rear Bumper Distorted	1150.60 ✓
Rear Bumper Clips. m	50 30
Rear Bumper Side Holder x02 m	$26.5 \times 2 = 53.$ ✓
Rear Bumper Sponge x02 cml	$89.5 \times 2 = 179$ ✓
Rear Bumper Reflector x02 RH cml	$48.2 \times 2 = 96.40$ 48.20
Rear Bumper Reflector Garnish x02 RH Distorted	$45 \times 2 = 90$ 45
Reverse Sensor Dmgd	280(SN) 200(SN)
Rear End Panel Distorted	560.80 ✓
Rear End Panel Top Garnish. Distorted	155.50 ✓
Rear End Panel Antenna Sensor cml	85.40 ✓
Rear End Panel Buzzer Sensor NEM	88.20 x
Taillamp x02 LH cml, RH cml	$520.5 \times 2 = 1041$ ✓
Taillamp Panel x02 RH Distorted	$268 \times 2 = 536$ 268
Taillamp Inner Panel x02 RH Distorted	$210.2 \times 2 = 420.40$ 210.20.
Tailgate Distorted	1193 ✓
Tailgate Lock Jammed	157.10 ✓
Tailgate Weatherstripe. cut	168.50 ✓
Tailgate Inner Trim Board cml	320.40 ✓
Tailgate Inner Trim Board Clips. m	30 ✓
Tailgate Lamp x02 LH LHM, RH cml	$395 \times 2 = 790$ 395
Tailgate Chrome Moulding with garnish cml	383.10 ✓
Tailgate Chrome Moulding Clips. m	20 ✓
Tailgate Inner Pull Handle Delivered	25.50 ✓
Tailgate Damper x02 Best.	$165 \times 2 = 330$ ✓
Tailgate Hinge x02 NEM	$50.2 \times 2 = 100.40$ +
Tailgate Outer Lock Operer Switch NEM	175.50 +.
Tailgate Lock Striker Dmgd	27.50 ✓
Tailgate G/ass Moulding m	120 ✓

SLT 6602B.

Wiper Motor	HEM	490	x
Rear Bumper Under Cover LH	HEM	98.30	x
Rear Bumper Under Cover Clips LH	HEM	10	x
Rear Bumper Under Cover RH	HEM	95.20	✓
Rear Bumper Under Cover Clips RH	HEM	10	✓
Rear Bumper Tow Cover	Dislodged	16.50	✓
Rear Camera	Damaged	480(SN)	380(SN)
Rear RH Tyre	HEM	220(SN)	x
		16449.50	
		13159.60	
		S.N. 740.	

Panel Beating	3800	1800
Spray Painting	1800	1400
Wiring	100	30
To undersell	250	160
To remove reverse sensor	400	50
To remove rear camera	100	50
To remove upholstery and rear seat	380	200
To remove rear fender glasses	200	60
To transfer tailgate fittings	150	80
To remove tailgate glass	180	120
To remove rear and centre exhaust pipes	300	160
To remove fuel tank	150	80
To remove rear Hybrid Inverter and to re-programme	1600	750
Towing Fees	100	60
To remove rear undercarriage	400	300
To perform wheel alignment	150	80

5380

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 19279.60

L/S: 15.4K

12 Days. ✓