

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

DATE: 4. Feb. 2020

VEHICLE NO : SHA8143T

MAKE : HYUNDAI

MODEL : i40

DOA: 3. Feb. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$670.00
1	Side Mirror - RH Br			\$2,256.40
1	Front Door - RH X nv			\$2,201.10
1	Rear Door - RH X(R)			\$2,171.40
1	Rear Fender - RH X(R)			\$107.10
1	Rear Wheel Cover - RH SCm			

SUB TOTAL

\$7,406.00

LESS 20%

\$1,481.20

DISCOUNTED TOTAL

\$5,924.80

~~\$621.00~~

RH Front Door Logo nec  
RH Rear Door Logo nec

1 Advertisement - RHF Door nec

\$100.00 Nett

1 Advertisement - RHR Door nec

\$100.00 Nett

1 Advertisement - RHR Fender nec

\$100.00 Nett

\$300.00

## Labour Charge

1 Panel Beating

\$1,000.00 \$840

1 Spray Painting Charge

\$800.00 \$520

1 Tuff Kote

\$80.00 \$50

1 Wiring Charge

\$80.00 \$50

TOTAL LABOUR

\$1,960.00

ESTIMATE TOTAL

\$8,184.80

8339.80

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Rqm (UKK)  
5/2/2020 \$1310

pana@ukk9010.com  
88622778 (4S)

(4) repair days

**COMFORTDELGRO  
ENGINEERING**

Our Job Ref No : 305378896  
Date : 12. Feb. 2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK Fax :  
Attn : RAM  
Vehicle Reg No : SHA8143T Date of Accident : 3. Feb. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA GBJ4620H
2. The finalized amount shall be:  
(a) Spare Parts after List discount  
(b) Labour Charges  
Total for Part-By-Part Repair Cost  
(c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less:  
Final Lumpsum Repair cost \$2,000.00

3. Estimated normal period for repairs: 4 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature :  
Name : Lally Ng  
Tel : 6214 8316  
Fax : 6546 8156

Signature :  
Name : Ram  
Date : 19/02/2020

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: