

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA8143T

DATE: 4. Feb. 2020

MAKE : HYUNDAI

MODEL : i40

DOA: 3. Feb. 2020

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Side Mirror – RH Br✓			\$670.00
1	Front Door – RH X n✓			\$2,256.40
1	Rear Door – RH X(R)✓			\$2,201.10
1	Rear Fender – RH X(R)✓			\$2,171.40
1	Rear Wheel Cover – RH sc✓			\$107.10
SUB TOTAL				\$7,406.00
LESS 20%				\$1,481.20
DISCOUNTED TOTAL				\$5,924.80
RH front door Logo nec✓				
RH Rear door Logo nec✓				
1	Advertisement – RHF Door nec✓			\$100.00
1	Advertisement – RHR Door nec✓			\$100.00
1	Advertisement – RHR Fender nec✓			\$100.00
				\$300.00
Labour Charge				
1	Panel Beating			\$1,000.00
1	Spray Painting Charge			\$800.00
1	Tuff Kote			\$80.00
1	Wiring Charge			\$80.00
TOTAL LABOUR				\$1,960.00
ESTIMATE TOTAL				\$8,184.80

Nett
Nett
Nett

\$240
\$520
\$50
\$50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ram (UKK)
5/2/2020 \$1310
para@uram@ukk901000
88622778 LIS
4 repair days