## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

5-Feb-20

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6978 D

1 pc	n/s rocker panel garnish X		\$	286.00
1 pc	Front n/s door X (R)		\$	791.00
2 pcs	Front n/s door hinges @ \$33.00 XXX		\$	66.00
1 pc	Rear n/s door x (R)		\$	765.00
2 pcs	Rear n/s door hinges @ \$33.00 ×hh		\$	66.00
1 pc	Rear n/s wheel cover SCV		\$	116.00
2 pcs	Rear bumper n/s & o/s side retainer ×いへ		\$	58.00
1 pc	Rear bumper		\$	696.00
			\$	2,844.00
		Less 10%	\$	284.40
			\$	2,559.60
S/NETT				
1 pc	Rear n/s fender sticker N2C		\$	60.00
1 set	n/s door sticker vec		\$	100.00
1 set	n/s rocker panel garnish clips ⋉⋈✓		\$	28.00
1 set	Rear bumper clips NeC		\$	48.00
I KK Auto C	Sundry		\$	50.00 \$30
	To check for rear n/s wheel alignment		\$	80.00 1666
	To dismantle and refit the front & rear n/s door inner components into new shell door		\$	300.00 ≺ ∩ \
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, etc		\$	750.00\$54 0
	To putty and spray painting on rear bumper, rear n/s fender, rear n/s door, front n/s door, n/s rocker panel garnish,		\$	1,000.00 \$500
	To apply rustproofing on the repaired and replaced panels.		\$	150.00 \$50
	Consultants hence notify		\$	5,125.60
the Repair	er of the following:	- (1	VV	

. To resurvey before/after spray painting

To display damaged part(s) during resulting REPAIR COSTS ARE SUBJECTED TO GST )
 Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis
No illegal modifications AROWE ESTIMATED COST OF REPAIR DO NOT INCLUDE

• Supplementary it ANY NUNEOR EN SERVIND AMAGES. is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
05/2/2020 re45hrs
05/2/2020 re45hrs