

51 AUTOMOTIVE PTE LTD

LRC / Adiani

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

(COR 14200.00)?
+days?

Contact : 83802233 88938908

TP1st Cap
Khanchan

ESTIMATE

Repair Code : CLM16026

Date in : 04/02/2020

Vehicle Num. : SKW2905A

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104538598/1ZRX530250

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT AIRCON CONDENSER warped.	1	1536.00	1,536.00 ✓
FRONT BONNET MECHANISM LOCK new	1	271.85	271.85 +
FRONT BRACE PANEL Bent.	1	182.10	182.10 ✓
FRONT BUMPER Rehd.	1	581.45	581.45 ✓
FRONT BUMPER INNER SPONGE could	1	186.10	186.10 —
FRONT BUMPER LOWER GRILLE new	1	191.40	191.40 +
FRONT BUMPER REINFORCEMENT Bent	1	374.45	374.45 ✓
FRONT BUMPER SIDE RETAINER L/R new	2	132.10	264.20 +
FRONT GRILLE could	1	643.00	643.00 —
FRONT GRILLE 'LOGO' EMBLEM new	1	65.45	65.45 ✓
FRONT GRILLE UPPER COVER Rehd.	1	92.00	92.00 —
FRONT GRILLE UPPER SEAL new	1	81.90	81.90 +
FRONT HEADLAMP L/R could	2	927.60	1,855.20 ✓
FRONT HEADLAMP LOWER BRACKET L/R new	2	132.10	264.20 +
FRONT TOP PANEL Rejo	1	280.00	280.00 +

5515.75
4136.81

*** This is a computer-generated document which requires no signature.***

N51 AUTOMOTIVE PTE LTD

Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 83802233 88938908

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

Repair Code : CLM16026

Date in : 04/02/2020

Vehicle Num. : SKW2905A

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104538598/1ZRX530250

		Subtotal before discount	6,869.30
Percentage discount	25%		1,717.33
		Sub-total 1	5,151.98
FRONT BUMPER CLIPS - SET	1	50.00	50.00 30
FRONT GRILLE UPPER COVER CLIPS - SET	1	30.00	30.00 10
FRONT NUMBER PLATE	1	25.00	25.00
FRONT NUMBER PLATE HOLDER	1	50.00	50.00 30
		Subtotal before discount	155.00
Percentage discount	0%		0.00
		Sub-total 2	155.00
		Parts-total	5,306.98

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

120.00 ✓
~~50.00~~ 30
~~700.00~~ 500
~~600.00~~ 400
50.00 +

1050

1050 → 1,520.00

6,826.98

total 5281.81 Admin Lj
h/s 42K L/S 02/03/20 04 Pmp