



陳林峰峰私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SGF9992M
Date of Accident : 22 October 2020

Mr Ker Eng Ling

Date : 05 February 2020

Estimate To Repair SLS8609A - Honda Grace Hybrid 1.5 LX CVT
Chassis No : GM41109753

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	o/s rear fender <i>scr</i>	\$ 1,134.80 ✓
02	1 pc	o/s rear fender inner cowling <i>xnn</i>	\$ 85.00 x
03	6 ps	o/s rear fender inner cowling @ \$3.50 <i>xnn</i>	\$ 21.00 x
04	1 pc	o/s rear fender air vent ?	\$ 35.70 ?
05	1 pc	rear bumper ?	\$ 463.70 ?
06	1 pc	rear bumper side retainer o/s <i>xnn</i>	\$ 13.90 x
07	10 ps	rear bumper clips @ \$3.50 ?	\$ 35.00 ?
08	1 pc	o/s rear wheel hub cap <i>scr</i>	\$ 75.00 ✓
09	1 pc	o/s rear door <i>DD</i>	\$ 759.60 ✓
			\$ 2,623.70
Less 20 %			\$ 524.74
			\$ 2,098.96
<u>SPECIAL NETT ITEMS</u>			
10	1 pc	o/s rear fender 1/4 glass sealant <i>rec</i>	\$ 100.00 \$70
11	1 pc	rear windscreen sealant <i>rec</i>	\$ 40.00 ✓
			\$ 140.00
<u>LABOUR & MISC. CHARGES</u>			
01		To rust-proofing of the affected areas.	\$ 80.00 \$50
02		To transfer of door fittings and perform water seepage test.	\$ 100.00 \$60
03		To reinstall of rear bumper parking sensor.	\$ 80.00 \$60
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00 \$450
05		Putty and spray painting of the affected portion.	\$ 800.00 \$600
06		To remove and refit rear windscreen glass.	\$ 120.00 \$80
			\$ 1,980.00
			\$ 4,218.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram (LKK)
5/2/2020 1110 hrs
Ramosuram@lkkauto.com
88622778 @refacunday
Dismantle required