

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002121/GBS3Q2
Date: 29/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100020264
Claimant Vehicle No :	SLJ2961T	Insured Vehicle No :	SBN545Y
Date of Loss:	14/01/2020	Nature of Claim:	TP
		Claim No:	4084613516SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2961T	Engine No:	1NZX872695
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305102112
Reg. Date:	19/02/2009 (Man. Year: 2009)	Odometer:	259038 km
Colour:	Beige		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,279.00	410.40	2,868.60	87.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	700.00	900.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,879.00	1,110.40	3,768.60	77.24
Approved Total (Overridden) (S\$)		900.00		

Nett Amount (S\$)	4,879.00	900.00	3,979.00	81.55
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,207.45		
Global Sum Settlement (S\$)		1,200.00		

INSPECTION

Date of Assignment: 06/02/2020

Date Inspected: 06/02/2020

Estimated Period of Repair: 3.0 days

Inspected At:

52 SENANG CRESCENT

Repairer: 6 Speed Autowerkz Pte Ltd (HQ)

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	568.00 FL	*- FL
2	1		*BOOTLID LOCK	Not Necessary	120.00 FL	*- FL
3	1		*BOOTLID LOCK CATCH	Not Necessary	64.00 FL	*- FL
4	2		*BOOTLID RUBBER STOPPER	Not Necessary	64.00 FL	*- FL
5	2		*BOOTLID HINGE	Not Necessary	92.00 FL	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	220.00 FL	*- FL
7	1		*BOOTLID EMBLEM LOGO	Not Necessary	60.00 FL	*- FL
8	1		*BOOTLID EMBLEM VIOS	Not Necessary	55.00 FL	*- FL
9	1		*BOOTLID EMBLEM E	Not Necessary	48.00 FL	*- FL
10	1		*TAILAMP RH	Not Necessary	470.00 FL	*- FL
11	2		*TAILAMP PANEL	Not Necessary	258.00 FL	*- FL
12	2		*TAILAMP SEAL	Not Necessary	64.00 FL	*- FL
13	1		*REAR BUMPER	Deformed	560.00 FL	*415.20 FL
14	1		*REAR BUMPER REFLECTOR	O/S Cracked / N/SNot Necessary	184.00 FL	*92.00 FL
15	2		*REAR BUMPER RETAINER	Not Necessary	128.00 FL	*- FL
16	2		*REAR BUMPER SIDE HOLDER	Not Necessary	90.00 FL	*- FL
17	2		*REAR BUMPER BRACKET	Not Necessary	212.00 FL	*- FL
18	1		*REAR END PANEL	Repair	700.00 FL	*- FL
19	1		*REAR END PANEL GARNISH	Not Necessary	15.00 FL	*- FL
20	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,272.00	537.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	993.00	126.80
Total Parts (\$\$)	3,279.00	410.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	800.00	300.00
2	TO SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	400.00
Gross Labour Cost (\$\$)			1,600.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >