



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GBA 1219 B
TOYOTA DYNA

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	FRONT SIDE TOP WIPER PANEL (RH) <i>x(R)</i>	2	
2	FRONT CENTER GARNISH <i>scr</i>	1	
3	FRONT CENTER PANEL <i>DD</i>	1	
4	FRONT CENTER PANEL LOGO (TOYOTA) <i>na</i>	1	
5	FRONT CENTER PANEL EMBLEM (DYNA) <i>na</i>	1	
6	FRONT SIDE PANEL (RH) <i>BC</i>	2	
7	FRONT GRILLE <i>xnn</i>	1	
8	FRONT GRILLE PANEL <i>xnn</i>	1	
9	HEAD LAMP (L+R) <i>x(R)</i>	2	
10	HEAD LAMP BRACKET (L+R) ?	2	
11	FRONT BUMPER <i>PD</i>	1	
12	FRONT BUMPER RETAINER (L+R) ?	2	
13	FRONT BUMPER REINFORCEMENT BAR <i>DD(R)</i>	1	
14	FRONT SUPPORT PANEL ?	1	
15	WIPER WASHER TANK <i>xnn</i>	1	
16	WIPER WASHER MOTOR <i>xnn</i>	1	
17	FRONT DOOR (RH) <i>BC</i>	1	
18	FRONT DOOR SIDE MIRROR ASSY (RH) <i>scr</i>	1	
19	FRONT DOOR HANDLE (RH) <i>cut</i>	1	
20	FRONT DOOR WINDOW MOULDING (RH) <i>na</i>	1	
21	FRONT DOOR LOCK (RH) <i>xnn</i>	1	
22	FRONT DOOR LOCK CATCH (RH) <i>xnn</i>	1	
23	FRONT DOOR HINGE UPPER & LOWER (RH) <i>xnn</i>	2	
24	FRONT DOOR CHECKER (RH) <i>xnn</i>	1	
25	FRONT DOOR INNER BOARD (RH) <i>xnn</i>	1	
26	FRONT DOOR LAMP (RH) <i>xnn</i>	1	
27	FRONT DOOR POWER WINDOW REGULATOR (RH) <i>xnn</i>	1	
28	FRONT DOOR POWER WINDOW MOTOR (RH) <i>xnn</i>	1	
29	FRONT DOOR WEATHER STRIP (RH) ?	1	
30	FRONT DOOR INNER WEATHER STRIP (RH) ?	1	
31	FRONT STEP PANEL (RH) <i>x(R)</i>	1	
32	FRONT STEP GARNISH (RH) <i>xnn</i>	1	
33	FRONT DOOR PILLAR (RH) <i>DD</i>	1	
34	FRONT DOOR PILLAR EMBLEM (RH) <i>na</i>	1	
35	FRONT ABSORBER (RH) <i>xnn</i>	1	
36	FRONT LOWER ARM (RH) <i>xnn</i>	1	
37	FRONT KNUCKLE (RH) <i>xnn</i>	1	
38	FRONT KNUCKLE BEARING (RH) <i>xnn</i>	1	
39	FRONT BEARING HUB (RH) <i>xnn</i>	1	
40	FRONT CROSSMEMBER ?	1	

41	FRONT STEERING RACK AND PINION ASSY	1	
42	FRONT DRIVE SHAFT (RH)	1	
43	FRONT STABILIZER BAR	1	
44	FRONT STABILIZER LINK (RH) ?	1	
45	FRONT TIE ROD (RH) ?	1	
46	FRONT TIE ROD END (RH) ?	1	
47	SIDE GATE (RH) DD	1	2
48	SIDE GATE HINGE SET (RH) nec	6	10
49	SIDE GATE LOCK CATCH (RH) nec	2	
50	SIDE GATE LOCK (RH) nec	2	
	SUBTOTAL		\$ -
	LESS 25%		\$ -
	PARTS TOTAL		\$ -

	SPECIAL NETT	QTY	PRICE
1	FRONT SIDE TOP WIPER PANEL SEALANT nec	1	\$ 120.00
2	FRONT CENTER GARNISH CLIPS nec	10	\$ 100.00
3	FRONT CENTER PANEL SEALANT nec	1	\$ 120.00
4	FRONT SIDE PANEL SEALANT nec	1	\$ 120.00
5	FRONT DOOR STICKER (COMPANY REG) nec	1	\$ 1,200.00
6	FRONT DOOR INNER BOARD CLIPS xnn	1	\$ 100.00
7	FRONT STEP PANEL SEALANT nec	1	\$ 120.00
8	FRONT TYRE SET xnn	2	\$ 1,600.00
9	FRONT RIM SET xnn	2	\$ 3,600.00
10	SIDE GATE TOP HANDLE (L+R) xnn DD	2	\$ 6,000.00
	SPECIAL NETT TOTAL		\$ 13,080.00

	LABOUR	QTY	PRICE
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1	\$ 3,300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 2,700.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 250.00
4	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS (FRONT CABIN)	1	\$ 400.00
5	TO RNR DOOR MECHANISM	1	\$ 800.00
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	\$ 150.00
11	TO RNR UNDERCARRIAGE SYSTEM	1	\$ 250.00
12	TO CHECK WHEEL ALIGNMENT	1	\$ 250.00
13	TO RNR TYRE AND WHEEL BALANCING	1	\$ 250.00
15	TO DO WATER LEAK TEST .	1	\$ 100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer


Signature:

Date:

TOTAL \$ 1,700.00

GRAND TOTAL COST \$ 14,780.00

Ram (LKK)
6/2/2020 1645
Parasuram@LKKauto.com
88622778 (LTS) 7 repair days
Disassemble Required



Rico 60 Auto Services Pte Ltd . B1K 8 , KAKI BUKIT AVENUE 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GBA 1219 B
TOYOTA DYNA

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	FRONT SIDE TOP WIPER PANEL (RH) x(R)	1	\$ 526.70
	2	FRONT CENTER GARNISH DD ^{scr} \$ 305	1	\$ 642.50
X	3	FRONT CENTER PANEL DD xnn	1	\$ 1071.20
X	4	FRONT CENTER PANEL LOGO (TOYOTA) DD xnn	1	\$ 90.00
X	5	FRONT CENTER PANEL EMBLEM (DYNA) DD xnn	1	\$ 88.50
	6	FRONT SIDE PANEL (RH) BC \$ 255	1	\$ 820.20
	7	FRONT GRILLE xnn	1	\$ 579.90
	8	FRONT GRILLE PANEL xnn	1	\$ 1169.10
	9	HEAD LAMP (L+R) x(R)	2	\$ 1670.80
	10	HEAD LAMP BRACKET (L+R) ? xnn	2	\$ 394.20
X	11	FRONT BUMPER DD xnn	1	\$ 697.50
	12	FRONT BUMPER RETAINER (L+R) ? xnn	2	NIL
	13	FRONT BUMPER REINFORCEMENT BAR DD (R)	1	\$ 562.70
	14	FRONT SUPPORT PANEL ? xnn	1	\$ 1071.10
	15	WIPER WASHER TANK xnn	1	\$ 275.20
	16	WIPER WASHER MOTOR xnn	1	\$ 421.90
	17	FRONT DOOR (RH) BC \$ 850	1	\$ 1743.20
	18	FRONT DOOR SIDE MIRROR ASSY (RH) scr \$ 196	1	\$ 509.00
	19	FRONT DOOR HANDLE (RH) cut \$ 185	1	\$ 271.20
	20	FRONT DOOR WINDOW MOULDING (RH) rel \$ 160	1	\$ 239.60
	21	FRONT DOOR LOCK (RH) xnn	1	\$ 421.10
	22	FRONT DOOR LOCK CATCH (RH) xnn	1	\$ 121.50
	23	FRONT DOOR HINGE UPPER & LOWER (RH) xnn	2	\$ 376.20
	24	FRONT DOOR CHECKER (RH) xnn	1	\$ 181.20
	25	FRONT DOOR INNER BOARD (RH) xnn	1	\$ 649.90
	26	FRONT DOOR LAMP (RH) xnn	1	\$ 219.50
	27	FRONT DOOR POWER WINDOW REGULATOR (RH) xnn	1	\$ 630.10
	28	FRONT DOOR POWER WINDOW MOTOR (RH) xnn	1	\$ 654.30
	29	FRONT DOOR WEATHER STRIP (RH) ? xnn	1	\$ 319.50
	30	FRONT DOOR INNER WEATHER STRIP (RH) ? xnn	1	\$ 321.10
	31	FRONT STEP PANEL (RH) x(R)	1	\$ 572.70
	32	FRONT STEP GARNISH (RH) xnn	1	\$ 939.20
	33	FRONT DOOR PILLAR (RH) DD \$ 742	1	\$ 742.00
	34	FRONT DOOR PILLAR EMBLEM (RH) rel \$ 53	1	\$ 79.50
	35	FRONT ABSORBER (RH) xnn	1	\$ 329.20
	36	FRONT LOWER ARM (RH) xnn	1	\$ 571.40
	37	FRONT KNUCKLE (RH) xnn	1	\$ 421.00
	38	FRONT KNUCKLE BEARING (RH) xnn	1	\$ 459.40
	39	FRONT BEARING HUB (RH) xnn	1	\$ 540.10
	40	FRONT CROSSMEMBER ? xnn	1	\$ 3641.20

