



Rico 60 Auto Services Pte Ltd. BIK 8, KAJI BUKIT AVENUE 4, #01-27
Premier @ Kajal Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

GBA 1219 B
TOYOTA DYNA

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	FRONT SIDE TOP WIPER PANEL (RH) x(R)	1	\$ 526.70
	2	FRONT CENTER GARNISH scr DP	1	\$ 642.50
X	3	FRONT CENTER PANEL DP xnn	1	\$ 1071.20
X	4	FRONT CENTER PANEL LOGO (TOYOTA) scr xnn	1	\$ 90.00
X	5	FRONT CENTER PANEL EMBLEM (DYNA) scr xnn	1	\$ 88.50
X	6	FRONT SIDE PANEL (RH) BU	1	\$ 820.20
	7	FRONT GRILLE xnn	1	\$ 579.90
	8	FRONT GRILLE PANEL xnn	1	\$ 1169.10
	9	HEAD LAMP (L+R) x(R)	2	\$ 1670.80
	10	HEAD LAMP BRACKET (L+R) ? xnn	2	\$ 394.20
X	11	FRONT BUMPER DP xnn	1	\$ 697.50
	12	FRONT BUMPER RETAINER (L+R) P xnn	2	NIL
	13	FRONT BUMPER REINFORCEMENT BAR DP (R)	1	\$ 562.70
	14	FRONT SUPPORT PANEL ? xnn	1	\$ 1271.10
	15	WIPER WASHER TANK xnn	1	\$ 275.20
	16	WIPER WASHER MOTOR xnn	1	\$ 421.90
	17	FRONT DOOR (RH) BU	1	\$ 1243.20
	18	FRONT DOOR SIDE MIRROR ASSY (RH) scr	1	\$ 509.00
	19	FRONT DOOR HANDLE (RH) cut	1	\$ 271.20
	20	FRONT DOOR WINDOW MOULDING (RH) scr	1	\$ 239.60
	21	FRONT DOOR LOCK (RH) xnn	1	\$ 421.10
	22	FRONT DOOR LOCK CATCH (RH) xnn	1	\$ 121.50
	23	FRONT DOOR HINGE UPPER & LOWER (RH) xnn	2	\$ 376.20
	24	FRONT DOOR CHECKER (RH) xnn	1	\$ 161.20
	25	FRONT DOOR INNER BOARD (RH) xnn	1	\$ 649.90
	26	FRONT DOOR LAMP (RH) xnn	1	\$ 219.50
	27	FRONT DOOR POWER WINDOW REGULATOR (RH) xnn	1	\$ 630.10
	28	FRONT DOOR POWER WINDOW MOTOR (RH) xnn	1	\$ 654.30
	29	FRONT DOOR WEATHER STRIP (RH) ? xnn	1	\$ 319.50
	30	FRONT DOOR INNER WEATHER STRIP (RH) ? xnn	1	\$ 321.10
	31	FRONT STEP PANEL (RH) x(R)	1	\$ 572.70
	32	FRONT STEP GARNISH (RH) xnn	1	\$ 139.20
	33	FRONT DOOR PILLAR (RH) DO	1	\$ 742.00
	34	FRONT DOOR PILLAR EMBLEM (RH) scr	1	\$ 79.50
	35	FRONT ABSORBER (RH) xnn	1	\$ 329.20
	36	FRONT LOWER ARM (RH) xnn	1	\$ 571.40
	37	FRONT KNUCKLE (RH) xnn	1	\$ 421.00
	38	FRONT KNUCKLE BEARING (RH) xnn	1	\$ 459.40
	39	FRONT BEARING HUB (RH) xnn	1	\$ 540.10
	40	FRONT CROSSMEMBER ? xnn	1	\$ 3641.20

41	FRONT STEERING RACK AND PINION ASSY Xnn		1	\$ 3908.60	
42	FRONT DRIVE SHAFT (RH) Xnn		1	\$ 1037.10	
43	FRONT STABILIZER BAR Xnn		1	\$ 597.20	
44	FRONT STABILIZER LINK (RH) Xnn		1	\$ 291.10	
45	FRONT TIE ROD (RH) Xnn		1	\$ 419.40	
46	FRONT TIE ROD END (RH) Xnn		1	\$ 205.50	
47	SIDE GATE (RH) DD	\$1476	1	\$ 1476.10	
48	SIDE GATE HINGE SET (RH) nec	\$179	6	\$ 1410.00	
49	SIDE GATE LOCK CATCH (RH) nec	\$149	2	\$ 269.80	
50	SIDE GATE LOCK (RH) nec	\$210	2	\$ 409.20	
SUBTOTAL				\$ -	
3565.5 LESS 25%				\$ -	
PARTS TOTAL				\$ -	
SPECIAL NETT					
		QTY	PRICE		
1	FRONT SIDE TOP WIPER PANEL SEALANT nec	\$50	1	\$ 120.00	
2	FRONT CENTER GARNISH CLIPS nec Xnn		10	\$ 100.00	
3	FRONT CENTER PANEL SEALANT nec Xnn		1	\$ 120.00	
4	FRONT SIDE PANEL SEALANT nec	\$50	1	\$ 120.00	
5	FRONT DOOR STICKER (COMPANY REG) nec	\$100	1	\$ 1,200.00	
6	FRONT DOOR INNER BOARD CLIPS Xnn Xnn		1	\$ 100.00	
7	FRONT STEP PANEL SEALANT nec	\$50	1	\$ 120.00	
8	FRONT TYRE SET Xnn		2	\$ 1,600.00	
9	FRONT RIM SET Xnn		2	\$ 3,600.00	
10	SIDE GATE TOP HANDLE (L+R) Xnn DD	\$200	2	\$ 6,000.00	
\$550					
SPECIAL NETT TOTAL				\$ 13,080.00	
LABOUR					
		QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	\$1000	1	\$ 3,300.00	\$22
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	\$600	1	\$ 2,700.00	\$11
3	TO RUST PROOF ACCIDENT AFFECTED AREA	\$100	1	\$ 250.00	\$15
4	TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS (FRONT CABIN) Xnn		1	\$ 400.00	\$15
5	TO RNR DOOR MECHANISM	\$80	1	\$ 800.00	\$12
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	Xnn	1	\$ 150.00	\$8
11	TO RNR UNDERCARRIAGE SYSTEM	Xnn	1	\$ 250.00	\$21
12	TO CHECK WHEEL ALIGNMENT	Xnn	1	\$ 250.00	\$8
13	TO RNR TYRE AND WHEEL BALANCING	Xnn	1	\$ 250.00	\$12
15	TO DO WATER LEAK TEST	Xnn	1	\$ 100.00	\$5
\$170					
TOTAL				\$ 1,700.00	
GRAND TOTAL COST				\$ 14,780.00	

List Item: \$3565.50

Net Item: \$550

Labour: \$1780

Total: \$5895.50

\$4700/-
45 days

Ram (LKK)
6/2/2020 1645
Parasuram@LKKauto.com
88622778 (LTS) Repair days
Dismantle required

45