

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 98176547

TP FWD
 Xiao Tony

ESTIMATE

Repair Code : CLM16027

Date in : 05/02/2020

Vehicle Num. : SLD7294J

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104553095/1ZRX581383

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Buckled</i>	1	781.10	✓ 781.10
REAR BOOTLID 'ALTIS' EMBLEM <i>3</i>	1	54.10	✓ 54.10
REAR BOOTLID 'COROLLA' EMBLEM <i>1</i>	1	50.20	✓ 50.20
REAR BOOTLID 'LOGO' EMBLEM <i>1</i>	1	58.50	✓ 58.50
REAR BOOTLID HINGES L/R <i>new</i>	2	79.60	+ 159.20
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	17.00	+ 34.00
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	181.85	+ 181.85
REAR BOOTLID LOCK STRIKER <i>not new</i>	1	85.00	+ 85.00
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	379.20	✓ 379.20
REAR BOOTLID WEATHER STRIP <i>new</i>	1	271.45	✓ 271.45
REAR BUMPER <i>Defect</i>	1	581.90	✓ 581.90
REAR BUMPER REFLECTOR L/R <i>new</i>	2	141.45	+ 282.90
REAR BUMPER REINFORCEMENT <i>Defect</i>	1	398.70	✓ 398.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Defect</i>	2	165.00	✓ 330.00
REAR BUMPER REVERSE SENSOR <i>Defect</i>	2	189.50	379.00 379.00 ✓
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	2	121.10	+ 242.20
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	715.20	+ 715.20
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	65.00	✓ 130.00

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 98176547

ESTIMATE

Repair Code : CLM16027

Date in : 05/02/2020

Vehicle Num. : SLD7294J

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104553095/1ZRX581383

REAR END PANEL <i>Devised</i>	1	781.90	✓	781.90
REAR END PANEL INNER TOP GARNISH <i>Devised</i>	1	185.99	✓	185.99
REAR FENDER INNER TRIM L/R <i>New</i>	2	338.00	+	676.00
REAR FLOOR PANEL TOP BOARD COVER <i>torn</i>	2	338.00	292	676.00
REAR TAILLAMP LOWER BRACKET L/R <i>cancel</i>	2	88.70	✓	177.40
Subtotal before discount				7,611.79
Percentage discount 25%				1,902.95
Sub-total 1				5,708.84
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET <i>New</i>	1	50.00	+	50.00
REAR BUMPER CLIPS - SET <i>New</i>	1	80.00	30	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>New</i>	1	30.00	10	30.00
REAR FENDER INNER TRIM CLIPS L/R - SET <i>New</i>	2	50.00	+	100.00
Subtotal before discount				310.00
Percentage discount 0%				0.00
Sub-total 2				310.00
Parts-total				6,018.84

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 98176547

ESTIMATE

Repair Code : CLM16027

Date in : 05/02/2020

Vehicle Num. : SLD7294J

Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Chassis/Eng# : MR053REH104553095/1ZRX581383

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

80 100.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 140.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

800 1,000.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

800 1,000.00

To apply anti-rust chemical on repaired and replaced panel.

60 120.00

To transfer rear bootlid mechanism lock outer handle reflector

80 80.00

Labour Total

2,440.00

Parts & Labour Total

8,458.84

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Admin L
L/s 24/02/20

06 Days

Total: 5478.58

L/s : A.31C