

PANG SCOOTER SERVICE

Bik 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO: FB J5956H

DATE ACCIDENT: 19.01.2020

MAKE / MODEL: HONDA / CB400X

S/No	DESCRIPTION	AMOUNT
1	HANDLE BAR	\$ <i>bl</i> ✓ 185.00
2	WINDSHIELD	\$ <i>cut</i> ✓ 285.00
3	WINDSHIELD BRACKET	\$ <i>x x nn</i> 185.00
4	TOP CLAMP	\$ <i>* * bl</i> - 250.00
5	STEERING CON	\$ <i>* ? NN</i> 120.00
6	UNDER BRACKET	\$ <i>* ? NN</i> 395.00
7	BRAKE DISC	\$ <i>H</i> ✓ 285.00
8	BRAKE LEVER	\$ <i>* * on</i> 50.00
9	RIGHT HAND FRONT FOOT REST	\$ <i>cut</i> ✓ 85.00
10	RIGHT HAND FRONT FOOT BRACKET	\$ <i>bl</i> ✓ 185.00
11	BRAKE PEDAL	\$ <i>bl</i> ✓ 75.00
12	MUFFLER ASSY	\$ <i>del</i> ✓ 980.00
13	MUFFLER JOINT GASKET	\$ <i>rec</i> ✓ 48.00
14	REAR WHEEL RIM	\$ <i>bl</i> ✓ 795.00
15	REAR BOX	\$ <i>del</i> ✓ 485.00
16	CRASH BAR	\$ <i>bl</i> ✓ 385.00
17	RIGHT HAND MIRROR	\$ <i>cut</i> ✓ 95.00
	<i>Handguard RH cut x NN 1888</i>	
	TOTAL	4138
	SUB-TOTAL	\$ <i>4503</i> - 365 4,888.00
	TRANSPORT	\$ <i>60</i> ✓ 80.00
	LABOUR	\$ <i>300</i> ✓ 500.00 360
	<i>Temples 97495749</i>	
	<i>WP</i>	
	<i>1/2/20 @ 250 per</i>	
	<i>non psan</i>	
	<i>Recovery after repair</i>	
	<i>Temples @ 1k and .com.</i>	
	<i>4 days.</i>	
	Total	\$ 5,468.00

LK Auto Consultants hereby notify the Register of the following:

- To resurvey, before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No legal liability is accepted
- Supplementary item(s) must be returned and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

4503 (PARTS + SUPPLEMENTARY)

15% = 4052.70

360 (LABOUR)

TOTAL 4412.70 04 days

L/S \$3500*

L/S \$3,500.00 (04 DAYS)

30 x 29 2 x 5 5 cm 318 gm

