

# PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

## ESTIMATE REPAIR

BIKE NO.: FBH 5956H

DATE ACCIDENT : 19.01.2020

MAKE / MODEL : HONDA / CB400X

S/No	DESCRIPTION	AMOUNT
1	HANDLE BAR	\$ ? 185.00
2	WINDSHIELD	\$ x 285.00
3	WINDSHIELD BRACKET	\$ x 185.00
4	TOP CLAMP	\$ ? 250.00
5	STEERING CON	\$ ? 120.00
6	UNDER BRACKET	\$ ? 395.00
7	BRAKE DISC	\$ ? 285.00
8	BRAKE LEVER	\$ + 50.00
9	RIGHT HAND FRONT FOOT REST	\$ cut ✓ 85.00
10	RIGHT HAND FRONT FOOT BRACKET	\$ bt ✓ 185.00
11	BRAKE PEDAL	\$ bt ✓ 75.00
12	MUFFLER ASSY	\$ dt ✓ 980.00
13	MUFFLER JOINT GASKET	\$ new ✓ 48.00
14	REAR WHEEL RIM	\$ ? 795.00
15	REAR BOX	\$ dd ✓ 485.00
16	CRASH BAR	\$ bt ✓ 385.00
17	RIGHT HAND MIRROR	\$ cut ✓ 95.00
	Handguard RH - cut ✓	
	<b>SUB-TOTAL</b>	\$ <b>4,888.00</b>
	TRANSPORT	\$ 60. 80.00
	LABOUR	\$ 300 500.00
	Tanfildin 97495749	
	WP'	
	7/2/20 @ 250 pm	
	Luck psun	
	Resurvey after repair	
	tanfildin @ lkkauto.com	
	4 days.	
	<b>Total</b>	\$ <b>5,468.00</b>

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: