



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004238
INV Date 02/06/2020
Reference CC6/CTI20002130/Db3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 2611Z
Insured Veh. SBZ 1177G
Claim No. SNM20D200455
Policy No. DMPCSN3077341901
Accident Date 20/01/2020
Inspection Date 31/01/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20002130/Db3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-06-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBZ 1177G	Veh. Inspected	SHA 2611Z
Policy No.	DMPCSN3077341901	Coverage (\$)	0.00
Claim No.	SNM20D200455	Excess (\$)	0.00
Assign From		Assign Date	31/01/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU068788	Colour	BLUE
Odometer	723986	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/01/2020	Inspection Date	31/01/2020
Survey held at	BIFROST SIN MING		
Repairer	BIFROST AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2611Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	MOUNTING CRACKED	1,106.00	553.00
1	REAR BUMPER CLIP	NECESSARY	19.00	19.00
1	TAIL LAMP (RH)	NOT NECESSARY	697.80	-
1	REAR FENDER	TO REPAIR SEE LABOUR	2,171.40	-
1	REAR FENDER AIR-DUCT	NOT NECESSARY	51.60	-
1	REAR FENDER MUDFLAP (RH)	NOT NECESSARY	13.50	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	51.80	-
1	REAR DOOR (RH)	BUCKLED	2,201.10	2,201.10
1	REAR DOOR RUBBER (RH)	NOT NECESSARY	105.40	-
1	REAR DOOR 1/4 GLASS (RH)	NOT NECESSARY	91.20	-
1	REAR DOOR INNER MOULDING (RH)	NOT NECESSARY	127.00	-
1	REAR DOOR GEAR/REGULATOR (RH)	NOT NECESSARY	260.90	-
1	REAR DOOR LOCK ASSY	NOT NECESSARY	268.20	-
1	REAR DOOR 1/4 GLASS RUBBER (RH)	NOT NECESSARY	46.70	-
1	REAR DOOR HINGE UPPER (RH)	NOT NECESSARY	44.50	-
1	REAR DOOR HINGE LOWER (RH)	NOT NECESSARY	44.50	-
1	REAR DOOR CHECK (RH)	NOT NECESSARY	62.90	-
1	REAR DOOR TRIM BOARD (RH)	NOT NECESSARY	743.80	-
1	ROCKER PANEL INNER (RH)	NOT NECESSARY	351.70	-
1	ROCKER PANEL OUTER GARNISH (RH)	CUT / DISTORTED	682.80	341.40
1	ROCKER INNER SIDE PANEL (RH)	NOT NECESSARY	98.00	-
1	REAR TYRE (RH)	NOT NECESSARY	216.00	-
1	REAR TYRE WHEEL CAP	CUT	214.20	107.10
1	REAR WHEEL BEARING ING & HUB	DAMAGED	724.00	401.40
1	REAR TRAILING ARM (RH)	DISTORTED	384.00	192.00
1	REAR ASSIST (RH)	DISTORTED	219.40	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	552.60	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	162.60	-
1	REAR CROSS MEMBER	NOT NECESSARY	1,021.50	-

Report Ref No. CC6/CTI20002130/Db3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
1	FRONT FENDER (RH)	NOT NECESSARY	566.30	-
1	FRONT FENDER SHIELD (RH)	NOT NECESSARY	174.90	-
1	FRONT FENDER MUDFLAP (RH)	NOT NECESSARY	13.50	-
1	FRONT FENDER RETAINER	NOT NECESSARY	3.00	-
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR (RH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	NOT NECESSARY	96.00	-
1	FRONT DOOR GEAR/REGULATOR (RH)	NOT NECESSARY	176.80	-
1	FRONT DOOR HINGE UPPER (RH)	NOT NECESSARY	44.50	-
1	FRONT DOOR HINGE LOWER (RH)	NOT NECESSARY	44.50	-
1	FRONT DOOR CHECK (RH)	NOT NECESSARY	91.80	-
1	FRONT DOOR INNER LOCK (RH)	NOT NECESSARY	290.80	-
1	FRONT DOOR MIRROR (RH)	NOT NECESSARY	670.00	-
1	FRONT DOOR POWER MOTOR	NOT NECESSARY	442.10	-
1	FRONT DOOR TRIM BOARD (RH)	NOT NECESSARY	997.40	-
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	REAR TYRE RIM (RH)	DISTORTED	650.60	325.30
	LESS 20% DISCOUNT		-4,705.23	-2,116.33
			18,820.92	8,465.32
	SPECIAL NETT ITEMS			
1	FRONT DOOR COLOURED COMFORT LOGO (SN)	NECESSARY	66.00	66.00
1	FRONT DOOR ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	FRONT FENDER ADVERTISEMENT LOGO (SN)	NOT NECESSARY	100.00	-
1	ROCKER PANEL ADVERTISEMENT (SN)	NECESSARY	150.00	150.00
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORT STICKER (RH)(SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR FENDER COMFORT STICKER (RH)(SN)	NOT FITTED	10.00	-

Report Ref No. CC6/CTI20002130/Db3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT/I40 PLATE (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			872.00	716.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,800.00	1,000.00
	SPRAY PAINTING CHARGE.		1,600.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	80.00	-
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		400.00	150.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT.		80.00	60.00
	TRANSFER OF DOOR MECHANISM REAR.		80.00	60.00
	REMOVE/REFIX REAR AXLE.	NOT NECESSARY	280.00	-
	FRONT/FOUR WHEEL ALIGNMENT.		120.00	60.00
			5,190.00	2,450.00
GRAND TOTAL			24,882.92	11,631.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,300.00

Report Ref No. CC6/CTI20002130/Db3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2611Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2611Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2611Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

