BIFROST AUTO PTE LTD

REPAIR ESTIMATE

INSURANCE:

_			
\Box	۸	т	
\cup	М		

21-Jan-20

MODEL:

HYUNDAI 140

VEHICLE NO.: SHA2611Z

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER Caper mounty crock	1- 1-	/	AMOUNT
REAR BUMPER CLIP Has see hu	1 7	\$1,106.00	
TAIL LAMP (RH) NAL		\$19.00	\$19.00
REAR FENDER 12	1 X	\$697.80	\$697.80
REAR FENDER AIR-DUCT NA	1 ×	\$2,171.40	\$2,171.40
REAR FENDER MUDFLAP (RH) 시니	1 ×	\$51.60	\$51.60
REAR WINDSCREEN MOULDING HA	1 X	\$13.50	\$13.50
REAR DOOR (RH) Buc	11	\$51.80	\$51.80
REAR DOOR RUBBER (RH) NH	1 ×	\$2,201.10	\$2,201.10
REAR DOOR 1/4 GLASS (RH)	1 ×	\$105.40	\$105.40
REAR DOOR INNER MOULDING (RH)	1 X	\$91.20	\$91.20
REAR DOOR GEAR/REGULATOR (RH)	1 ×	\$127.00	\$127.00
REAR DOOR LOCK ASSY HA		\$260.90	\$260.90
REAR DOOR 1/4 GLASS RUBBER (RH)	1 X	\$268.20	\$268.20
REAR DOOR HINGE UPPER (RH) HL		\$46.70	\$46.70
REAR DOOR HINGE LOWER (RH)	1 ×	\$44.50	\$44.50
REAR DOOR CHECK (RH)	1 ×	\$44.50	\$44.50
REAR DOOR TRIM BOARD (RH)	1 ×	\$62.90	\$62.90
ROCKER PANEL INNER (RH)	1 1	\$743.80	\$743.80
ROCKER PANEL OUTER GARNISH (RH) Cut dustuck l	1	\$351.70	\$351.70
ROCKER INNER SIDE PANEL (RH)	1 ×	\$682.80	\$682.80
REAR TYRE (RH)	1 ×	\$98.00	\$98.00
REAR TYRE RIM (RH) GOT TO Chishand	Physir	\$216.00	\$216.00
REAR TYRE WHEEL CAP HE CL	1 🛠	\$650.60	\$650.60
REAR WHEEL BEARING ING & HUB Z Dow	1 7	\$214.20 \$724.00	\$214.20
REAR TRAILING ARM (RH) Zaustur	12	\$384.00	\$724.00
REAR ASSIST (RH) 2 dustrous	124	\$219.40	\$384.00
REAR SHOCK ABSORBER (RH) a distribution	171		\$219.40
REAR SHOCK ABSORBER MOUNTING (RH)	1 X	\$552.60	\$552.60
REAR CROSS MEMBER HL	1 🗡	\$162.60	\$162.60
STABILIZER BAR	V	\$1,021.50	\$1,021.50
	1 ^	\$199.60	\$199.60

1 ×	\$85.90	\$85.90
1 %	\$335.75	\$335.75
1 2		\$353.80
		\$545.60
11	4000.00	\$566.30
1		\$174.90
	\$13.50	\$13.50
	\$3.00	\$3.00
1 X	\$225.00	\$225.00
1 1	\$2,256.40	\$2,256.40
1 X	\$96.00	\$96.00
1 X		\$176.80
V		\$44.50
-		\$44.50
_		\$91.80
1	\$290.80	\$290.80
	\$670.00	\$670.00
1 X	\$442.10	\$442.10
1 ×	\$997.40	\$997.40
1 V	\$2,527.80	\$2,527.80
		A00 500 45
		\$23,526.15
		\$4,705.23 \$18,820.92
		\$10,020.92
N 1 1	\$66.00	\$66.00
N 1 1	\$100.00	\$100.00
	\$100.00	\$100.00
	\$150.00	\$150.00
	\$100.00	\$100.00
		\$100.00
		\$100.00
1 4		\$10.00
		\$50.00
		\$50.00
	\$40.00	\$46.00
		\$872.00
		\$672.00
		275
	1	\$335.75 1 \$353.80 1 \$545.60 1 \$566.30 1 \$174.90 1 \$13.50 1 \$3.00 1 \$225.00 1 \$2,256.40 1 \$96.00 1 \$176.80 1 \$91.80 1 \$91.80 1 \$91.80 1 \$997.40 1 \$997.40 1 \$997.40 1 \$997.40 1 \$100.00 N 1 \$50.00 N 1 \$50.00 N 1 \$50.00

Labour Charge				
Panel Beating	10001-	4	21.222.22	
Spray Painting Charge	10001	1	\$1,800.00	\$1,800.0
Wiring Charge		1	\$1,600.00	\$1,600.00
Tuff Kote	HL	1	\$80.00	\$80.00
Towing Charge	40 - Het	1	\$150.00	\$150.00
Remove/Refix Cushion & Upholstery Rear	MM	1	\$50.00	\$50.00
Remove/Refix Rear Windscreen Glass	80 -	1	\$150.00	\$150.00
Remove/Refix Reverse Sensor	HH	1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)	HL	1	\$120.00	\$120.00
Remove/Refix Fuel Tank	150/	1	\$400.00	\$400.00
Remove/Refix Exhaust Pipe	エア	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	HL	1	\$80.00-	\$80.00
Transfer of Door Mechanism FRONT	60 -	1	\$80.00	\$80.00
Remove/Refix Rear Axle	601-	1	\$80.00	\$80.00
	HH	1	\$280.00	\$280.00
Front/Four Wheel Alignment	60/-	1	\$120.00	\$120.00
TOTAL LABOUR				
				\$ 5,190.00
ESTIMATE TOTAL				
				\$ 24,882.92

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

31/01/2021 e 1630 mm 2/sum 9 days

you

LEK AAN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: