

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 06.02.20

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLF8293U**
MODEL : **TOYOTA COROLLA AXIO**
DATE OF ACCIDENT : 05.02.20
TIME OF ACCIDENT : 19:55HRS

Cecilia

NRE1610008929

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 947.50	\$ 947.50
2	BOOT LID INSULATOR <i>new</i>	1	\$ 205.00	\$ 205.00
3	BOOT LID HINGE <i>Best</i>	2	\$ 75.00	\$ 150.00
4	BOOT LID LOCK <i>Damaged</i>	1	\$ 105.00	\$ 105.00
5	BOOT LID LOWER CATCH <i>new</i>	1	\$ 42.00	\$ 42.00
6	BOOT LID LOGO <i>2</i>	1	\$ 58.00	\$ 58.00
7	BOOT LID EMBLEM "AXIO" <i>1</i>	1	\$ 58.00	\$ 58.00
8	BOOT LD EMBLEM "COROLLA"	1	\$ 50.00	\$ 50.00
9	BOOT LID WEATHER STRIP <i>lit</i>	1	\$ 189.70	\$ 189.70
10	BOOTLID OUTER MOULDING <i>Dented</i>	1	\$ 394.60	\$ 394.60
11	BOOT LID KEY LOCK <i>new</i>	1	\$ 138.10	\$ 138.10
12	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 75.10	\$ 150.20
13	REAR BUMPER <i>Del Distorted</i>	1	\$ 1,249.60	\$ <u>1,249.60</u>
14	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 74.60	\$ 149.20
15	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 105.40	\$ 210.80
16	REAR BUMPER BRACKET <i>Best</i>	2	\$ 85.20	\$ 170.40
17	TAIL LAMP <i>could</i>	2	\$ 579.40	\$ <u>1,158.80</u>
18	TAIL LAMP LOWER BRACKET <i>could</i>	2	\$ 98.00	\$ 196.00
19	TAIL LAMP PANEL <i>RH Dented</i>	2	\$ 245.80	\$ 491.60
20	REAR DOOR LOCK RH <i>new</i>	1	\$ 356.70	\$ 356.70
21	REAR DOOR LOCK CATCHER RH <i>2</i>	1	\$ 25.10	\$ 25.10
22	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 137.20	\$ 137.20
23	REAR DOOR INNER TRIM RH	1	\$ 469.70	\$ 469.70
24	REAR FENDER <i>RH Buckled</i>	2	\$ 974.30	\$ 1,948.60
25	REAR FENDER INNER COWLING <i>new</i>	2	\$ 147.60	\$ 295.20
26	REAR FENDER INNER TRIM <i>torn</i>	2	\$ 395.80	\$ 791.60
27	REAR WINDSCREEN GLASS <i>wt</i>	1	\$ 1,283.60	\$ 1,283.60
28	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 147.30	\$ 147.30
29	REAR END PANEL <i>Distorted</i>	1	\$ 697.20	\$ 697.20

✓

+

✓

✓

✓

✓

✓

✓

+

+

+

✓

✓

✓

✓

+

+

+

✓

✓

✓

✓

✓

798

245.80

974.30

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF8293U
 MODEL : TOYOTA COROLLA AXIO
 DATE OF ACCIDENT : 05.02.20
 TIME OF ACCIDENT : 19:55HRS

30	REAR END PANEL TOP GARNISH <i>Reid</i>	1	\$ 229.40	\$ 229.40	✓
31	REAR FLOOR PANEL <i>Distorted</i>	1	\$ 986.00	\$ 986.00	✓
32	REAR FLOOR PANEL TOP BOARD <i>Reid</i>	1	\$ 560.00	\$ 560.00	✓
33	REAR TOOLS SPONGE <i>Cooled</i>	1	\$ 479.20	\$ 479.20	-
34	REAR CHASSIS MEMBER RH <i>Ryis</i>	1	\$ 255.00	\$ 255.00	+
35	REAR EXHAUST PIPE <i>2</i>	1	\$ 940.00	\$ 940.00	+
36	REAR EXHAUST INSULATOR <i>MP</i>	1	\$ 245.70	\$ 245.70	+
37	REAR EXHAUST MOUNTING <i>M</i>	4	\$ 58.00	\$ 232.00	+
38	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+

10881.20
 8160.90

TOTAL PRICE \$ 16,254.00
 LESS 25% \$ 4,063.50
SUB TOTAL PRICE \$ 12,190.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Reu</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>Reu</i>	1	\$ 60.00	\$ 60.00	30
3	BOOT LID SEALANT <i>Reu</i>	1	\$ 150.00	\$ 150.00	+
4	BOOTLID OUTER MOULDING CLIP (SET) <i>Reu</i>	1	\$ 30.00	\$ 30.00	20
5	BOOT LID INSULATOR CLIP (SET) <i>Reu</i>	1	\$ 50.00	\$ 50.00	+
6	TAILLAMP CLIP (SET) <i>Reu</i>	1	\$ 30.00	\$ 30.00	20
7	TAIL LAMP PANEL SEALANT <i>Reu</i>	2	\$ 80.00	\$ 160.00	+
8	REAR DOOR INNER TRIM CLIP RH (SET) <i>MP</i>	1	\$ 80.00	\$ 80.00	+
9	REAR FENDER SEALANT <i>Reu</i>	2	\$ 150.00	\$ 300.00	+
10	REAR FENDER COWLING CLIPS (SET) <i>Reu</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER INNER TRIM CLIPS (SET) <i>Reu</i>	1	\$ 80.00	\$ 80.00	60
12	REAR WINDSCREEN SOLAR FILM <i>Reu</i>	1	\$ 550.00	\$ 550.00	200
13	REAR WINDSCREEN SEALANT <i>Reu</i>	1	\$ 80.00	\$ 80.00	30
14	REAR WINDSCREEN INNER SEAL <i>Reu</i>	1	\$ 60.00	\$ 60.00	30
15	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 30.00	\$ 30.00	10
16	REAR END PANEL INSULATION SEAL <i>Reu</i>	1	\$ 180.00	\$ 180.00	60
17	REAR FLOOR PANEL INSULATION SEAL <i>Reu</i>	1	\$ 350.00	\$ 350.00	60
18	REVERSE CAMERA <i>Reu</i>	1	\$ 450.00	\$ 450.00	+

520

TOTAL \$ 2,770.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	1600

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF8293U
 MODEL : TOYOTA COROLLA AXIO
 DATE OF ACCIDENT : 05.02.20
 TIME OF ACCIDENT : 19:55HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1400
3	TUFF COAT	\$ 250.00	120
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	80
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	60
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	TRANFER BOOTLID MECHANISM	\$ 80.00	80
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	✓
12	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
13	REMOVE AND REFIX REAR DOOR MECHANISM	\$ 80.00	X
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

3570

TOTAL \$ 6,010.00

TOTAL PARTS COST : \$ 14,960.50
 TOTAL LABOUR COST : \$ 6,010.00
 TOTAL REPAIR COST : \$ 20,970.50

Adrian L
 H/S 07/02/20

11 Days

LKK Auto Consultants hence notify

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.
 • Third party survey is on a "No Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental repairs must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: **ABBY**

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

total: 12250.00
 H/S: 9.8K

9.8K