

INS. CASE OWNER:

ANG Yvonne
6568804461

CC4/ASM20002133/ H ga3

LKK:
IDAC: 159403

Surveyor:

Lee Hock Ann

DOI:

ASSIGNMENT

7/7/2020

Date / Time: 06/02/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SML 5258Z

Name of Insured : YEO KIM CHUEN

Insured Tel No. : HP: +65-96655781

Excess Sec II : S\$ D.O.A: 01/02/2020 10:30

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. : (V/L: YES / NO)

Claim No. : S0M02F79

Policy No. : GA470638

Make / Model : HONDA FREED HYBRID-1.5 (A)

Place of Accident : MARINE PARADE FOOD MARKET CARPARK

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLA 1110L

INSRS:
WSP: Tony Automotive

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

INSRS:
WSP:

Tel :

Liability :

RMKS:

Date/ Time	SLA 1110L - X	SML 5258Z - X	STAGE	DATE / PIC	
14/2 3:44pm	called & re response call done.		Non-Reporting ltr (1st):		
20/2 2:16pm	called & still on pole up the line - passed sent letter.		Non-Reporting ltr (2nd):		
			Non-Reporting ltr (Final):		
			Notification ltr (if non-pickup):		
			Call OI:	7/2/2 Jc	
			After call ltr to OI:		
27/2	LOP M, TO seek mandate.		Documentation Check List:	Handler Typist	
28/2	Pending mandate approval ✓		Notification ltr (if non-pickup)	☒	☐
28/2	off site (pending acceptance).		After call ltr to OI:	☒	☐
	sent to GIC & DV send. (pending DV).		Authorisation To Act:	☒	☐
	DV M, FR pass M to GIC.		Release Voucher:	☒	☐
			Final Repair Bill:	☒	☐
			Car Rental Invoice:	☒	☐
			Towing Invoice	☒	☐
			LTA / GIA :	☒	☐
			Medical Bill:	☒	☐
			PIR:	☒	☐
			Mandate/Reject Instruction:	☒	☐
			LOD	☒	☐
			Payment Breakdown Form:	☒	☐
PRELIMINARY ADVICE	Date/Time:	Sent By:	Post-Repair Photos:	☒	☐
			Others:	☒	☐

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: 115	S\$ 6390.00	4 days) Reduction: \$872.21 % 58	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 22	If NO or B 28, Ass. Lia :
Repair Cost:	S\$ 6390.00		01 M passed TP.
Loss of Rental (LOR):	S\$ 642.00	6 days) x \$107	
Loss of Use (LOU):	S\$ -	(5 x days)	
Loss of Income (LOI):	S\$ -	(5 x days)	
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]	
GIA/LTA Search	S\$ 29.00		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/Independent)	
Legal Cost	S\$ -		
Total:	S\$ 7001.00	Global Sum S\$: 7000.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ 7000.00	Name 1: Tony Automotive Pte Ltd	
Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
Payee 3: (Strike if N.A.)	S\$ -	Name 3:	

X GIA

ASSIGNMENT

From:

Date:

7/21/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 1110 L

at Workshop m/s

Tony Automotive

of

2 Kari Bukit Ave 4 #04-07 Premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Amar 10 am

A735 6016 Tony

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

my

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 11102

Regn:

19/05/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi

cc

1595

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

72526

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W00 2050 402 R15 7598

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50/R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/2/20

D.O.I.

7/2/20

Survey held at

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

46 #6350/- (Red: #8777.21/581.) * SLA 11102 To Jan
by Estimate call

MV - 93000

9687.84

PV - 62111

1266.38

NV - 30800

* 4 repair days + 12 hr + 1 PRS = 6 days 11:20

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 - PRS - ST

Photos:

Other:

TOTAL

Report Format:

Lump Sum / F.E.C.:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$



: Assess end (\$



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Model: MERCEDES BENZ C180

Veh No: SLA1110L

FRONT

Qty	List Items	Amount S\$
1	FRONT BUMPER ✓ CNA	1606.37 1510.40 ✓
1	FRONT BUMPER SIDE RETAINER L/H ✓ CNA	153.5 132.40 ✓
1	FRONT BUMPER BOTTOM COVER L/H X (SVC)	120.5
1	FRONT BUMPER TOP SEAL X (SVC)	25.59
1	MOUNTING FOR FRONT BUMPER L/H ✓ CNA	182.4 132.80 ✓
1	FRONT GRILLE ASSY ✓ CNA	1080.6 680.80 ✓
1	FRONT HEAD LAMP L/H ✓ CNA	3626.25 2487.170 ✓
1	FRONT FENDER L/H ✓ CNA	1081.86 780.70 ✓
1	FRONT FENDER LOWER MOULDING L/H ✓ CNA	95
1	FRONT MUDGUARD L/H ✓ CNA	160.38 ✓
1	FRONT LOWER ARM L/H X (SVC)	537
1	FRONT KNUCKLE ARM L/H X (SVC)	790
1	FRONT KNUCKLE ARM BEARING L/H ✓ CNA	166 ✓
1	FRONT SHOCK ABSORBER L/H X (SVC)	697
Sub Total		10322.45
Less 10%		1032.25
		<u>9290.21</u>

Special Nett Items

Qty	List Items	Amount S\$
1	FRONT SPORT RIM L/H ✓ CNA	1817 750 ✓
1 SET	FRONT BUMPER CLIPS ✓ CNA	85 40 ✓
1 SET	FRONT SENSOR 4/H ✓ short only	380 450 ✓
Sub Total		2282

Labour charges

CHECK FRONT ELECTRICAL WIRING ✓	150	30	✓
CHECK WHEEL ALIGNMENT ✓ <i>report</i>	150	60	✓
RESPRAY UNDERCOATING ✓	200	50	✓
RESPRAY PAINTING ✓	1500	480	✓
PANEL BEATING, REMOVE AND REPLACE ABOVE PARTS ETC ✓	1500	500	✓
Sub Total	3500		

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

15072.21

L/S report 7/2/20 12.30pm
 4 day
 without pre-judge.
 Respray after paint
 Hoch 800
 Hoch 3
 85714883
 14000 BMW 11/14/2019



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Model: MERCEDES BENZ C180

Veh No: SLA1110L

SUPPLEMENTARY

Labour charges

DISMANTLE AND ASSEMBLE UNDER CARRIAGE FRONT L/H

Sub Total

250

250

Resurveyed
10/12/20
11.50 AM
H. ANN
H. ANN
Rong Ate Part B

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

parts	6051.18
parts less	10%
	5446.06
spe net	1240
labour	1270
	7956.06
L/s less	20%
	6364.84
	↓
total L/s less	\$ 6350.11

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: R002230
Date 7.2.20 13:00

SLA 1110 L
before

Mercedes-Benz : 205 (C Class 2014-) : without 4MATIC : with Code 485 (Standard Suspension) Sedan/Estate (W/S)

Front : Left

Actual	Before	Specified Range
-1°31'	-1°31'	
8°13'	8°13'	
0°14'	0°13'	0°04' 0°15'
6°57'	6°56'	
5°26'	5°26'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°11'	0°12'	
8°03'	8°03'	
0°13'	0°13'	0°04' 0°15'
6°22'	6°22'	
6°33'	6°33'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-1°42'	-1°42'	-0°24' 0°24'
0°10'	0°10'	-0°30' 0°30'
0°35'	0°35'	
0°27'	0°27'	0°09' 0°29'

Rear : Left

Actual	Before	Specified Range
-1°52'	-1°52'	
-0°01'	-0°01'	0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°00'	-2°00'	
0°09'	0°09'	0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°08'	0°08'	-0°24' 0°24'
0°07'	0°07'	0°11' 0°25'
-0°05'	-0°05'	-0°08' 0°08'

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: R002248
Date 11.2.20 11:52

(SLA 11102)
23/02/2020

Mercedes-Benz : 205 (C Class 2014-) : without 4MATIC : with Code 485 (Standard Suspension) Sedan/Estate (W/S)

Front : Left

Actual	Before	Specified Range
-0°12'	-0°23'	
8°09'	8°09'	
0°07'	0°10'	0°04' 0°15'
7°19'	7°29'	
7°07'	7°07'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°41'	-0°49'	
8°21'	8°21'	
0°16'	0°27'	0°04' 0°15'
14°10'	14°18'	
13°30'	13°30'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°29'	0°26'	-0°24' 0°24'
-0°12'	-0°12'	-0°30' 0°30'
-6°52'	-6°49'	
0°23'	0°37'	0°09' 0°29'

Rear : Left

Actual	Before	Specified Range
-1°45'	-1°59'	
0°12'	0°01'	0°02' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°51'	-1°51'	
0°08'	0°14'	0°02' 0°16'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°06'	-0°08'	-0°24' 0°24'
0°20'	0°15'	0°11' 0°25'
0°02'	-0°06'	-0°08' 0°08'

9

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Wednesday, 26 February, 2020 6:55 PM
To: Tony Ng
Cc: Cecilia Chong (LKK Auto)
Subject: RE: SLA 1110L FINALIZED

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear tony,

Good day, o.k will be process base on finalized total amount COR \$ 6350 L/SUMP REPAIR and DOR 4 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to lkk incharge person (CeciliaChong@lkkauto.com)

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tony Ng [<mailto:tony07auto@gmail.com>]

Sent: Tuesday, 25 February, 2020 11:47 AM

To: Hock Ann (LKK Auto)

Cc: Cecilia Chong (LKK Auto)

Subject: Re: SLA 1110L FINALIZED

Dear Hock Ann

We accept

COR - \$ 6350

DOR – 4 DAYS

Thanks.

On Tue, Feb 25, 2020 at 11:19 AM Hock Ann (LKK Auto) <HockAnn@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear tony ,

Good day , Kindly attached refer SLA 1110L MERCEDES BENZ C180 finalized updated calculate adjustment on 25.2.2020

COR - \$ 6350

DOR – 4 DAYS

Please refer adjustment updated total L/SUMP amount \$ 6350 if agree total L/SUMP amount and repair days, will be to close case.

Please update soon asap

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--

Warm regards



mercedes-benz c180

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » CSH Motors (S) Pte Ltd » Mercedes-Benz C-Class C180 Avantgarde

Mercedes-Benz C-Class C180 Avantgarde

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$112,800		
Depreciation ⓘ	\$13,730 /yr View models with similar depre	Reg Date	23-Dec-2016 (6yrs 10mths 12days COE left)
Mileage	54,000 km (17.2k /yr)	Manufactured ⓘ	2016
Road Tax ⓘ	\$740 /yr	Transmission	Auto
Dereg Value ⓘ	\$64,100 as of today (change)	OMV ⓘ	\$35,663
COE ⓘ	\$53,001	ARF ⓘ	\$36,929
Engine Cap	1,595 cc	Power	115.0 kW (154 bhp)
Curb Weight ⓘ	1,425 kg	No. of Owners ⓘ	1
Type of Vehicle	Luxury Sedan		



Location Map

Features

1.6L 4 Cylinder Inline Turbocharged Engine, 154Bhp, 7G-Tronic With Paddle Shifter, Keyless Go, LED Auto Headlights, DRL, Rain Sensors, Park Assist, View specs of the Mercedes-Benz C-Class Saloon (2014-2018)

Accessories

Factory Fitted Audio, Bluetooth, Reverse Camera, Collision Prevention Assist Plus, Electric Tailgate.

Description

Promo 1.98% Bank Loan Interest Rate. 1 Owner Only. Fully Serviced By C&C. Flawless Condition, Trade In Available. Hurry Call Or Visit Us Now For Further Details.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 09-Feb-2020 | 1 view | Modified on: 09-Feb-2020


Upf Compare

View more Financial info

https://www.sgcarMart.com/used_cars/info.php?ID=868518&DL=3210

Price Chart

Summary



Click on the point to view the vehicle.

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

CSH Motors (S) Pte Ltd

17 vehicles for sale. 27 sold in past 3 mths

210 Turf Club Road Lot A43

Enquire Road Tax Expiry Date

Review Details

Vehicle No.
SLA1110L

Vehicle Make/Model
MERCEDES BENZ / C180 EXCLUSIVE (R17 LED)

Road Tax Expiry Date :
18 May 2020

The information contained herein is correct as at 07 Feb 2020 / 10:01.

Save as PDF

OK →

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	158D
Vehicle Details	
Vehicle No.:	SLA1110L
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 EXCLUSIVE (R17 LED)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	27491030584271
Chassis No.:	WDD2050402R159598
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,589.00
Original Registration Date:	19 May 2016
First Registration Date:	19 May 2016
Transfer Count:	0
Actual ARF Paid:	\$36,825.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2026
PARF Rebate Amount:	\$27,618.00
Intended COE Rebate Details	
COE Expiry Date:	18 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$34,493.00
Total Rebate Amount:	\$62,111.00

The information contained herein is correct as at 10 Feb 2020

OK



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763271

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Link Auto Consultants hence notify the insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Model: MERCEDES BENZ C180

Veh No: SLA1110L

Acknowledged by Repairer

Signature:

Date:

FRONT

Qty	List Items	Amount S\$
1	FRONT BUMPER ✓ <i>CRU</i>	1606.37
1	FRONT BUMPER SIDE RETAINER L/H ✓ <i>new</i>	153.5
1	FRONT BUMPER BOTTOM COVER L/H X (svc)	120.5
1	FRONT BUMPER TOP SEAL X (svc)	25.59
1	MOUNTING FOR FRONT BUMPER L/H ✓ <i>new</i>	182.4
1	FRONT GRILLE ASSY ?	1080.6
1	FRONT HEAD LAMP L/H ✓ <i>CRU</i>	3626.25
1	FRONT FENDER L/H ✓ <i>BF</i>	1081.86
1	FRONT FENDER LOWER MOULDING L/H ✓ <i>new</i>	95
1	FRONT MUDGUARD L/H ?	160.38
1	FRONT LOWER ARM L/H X (svc)	537
1	FRONT KNUCKLE ARM L/H X (svc)	790
1	FRONT KNUCKLE ARM BEARING L/H ?	166
1	FRONT SHOCK ABSORBER L/H X (svc)	697
Sub Total		10322.45
Less 10%		1032.25
		9290.21

Special Nett Items

Qty	List Items	Amount S\$
1	FRONT SPORT RIM L/H ✓ <i>set</i>	1817
1 SET	FRONT BUMPER CLIPS ✓ <i>new</i>	85
1 SET	FRONT SENSOR 4/H ✓ <i>short</i>	380
Sub Total		2282

Labour charges

CHECK FRONT ELECTRICAL WIRING ✓	150	30
CHECK WHEEL ALIGNMENT ? <i>report</i>	150	60
RESPRAY UNDERCOATING ✓	200	50
RESPRAY PAINTING ✓	1500	480
PANEL BEATING, REMOVE AND REPLACE ABOVE PARTS ETC ✓	1500	500
Sub Total		3500

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

15072.21

L/S report 7/2/20 12.30pm
4 day
without prejudice
Resurvey when paint
Hoche BAW
11/11/20
85711283
Hoche BAW @ 11/11/20



Service Request Details

Claim

S0M02F79

Reference

None

Loss Date

February 1, 2020

Report Date

Feb 6, 2020 11:58:00 AM

Request Date

February 6, 2020

Due Date

February 13, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Tony
T: 1:58pm 6/2/2020
V: Out
E. ✓

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SLA1110L

MODEL

C180

Service Address

...

Primary Contact/Insured

YEO KIM CHUEN

BLK 138 RIVERVALE STREET, #14-756, 540138, Singapore

96655781

Claim Handler

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Additional Instructions

11

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

VISHNU BATHAM Shekhar

From: Tony Ng <tony07auto@gmail.com>
Sent: Thursday, February 06, 2020 10:55 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Pre-Repair Survey SLA1110L
Attachments: Pre-repair survey - AXA SLA1110L.pdf

Categories: SHEKHAR

Attention - Person in charge

Dear Sir / Madam

Kindly arrange for a pre-repair survey for our customer's vehicle number SLA1110L.

Attached is the document for your necessary action.

--

Warm regards

Tony

Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07

Premier@KB Singapore 415875

Mobile: 9735 6016

Tel: 6976 3261

Fax: 6976 3271



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 2/3/2020

Survey Details:

Date of loss	1-Feb-2020
Date of appointment	6-Feb-2020
Date of survey	7-Feb-2020
Location of survey	Tony Automotive Pte Ltd - Kaki Bukit

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLA1110L
Make and Model	MERCEDES BENZ C180 EXCLUSIVE (R17 LED)
Date of registration	19/5/2016
Parf Rebate	
Market Value	\$ 93,000.00
Parf Rebate	\$ 62,171.00
Nett Loss	\$ 30,829.00

Repair details:

Initial Estimate	\$ 15,072.21
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,686.06
Check items (estimate)	\$ -
Labour	\$ 1,240.00
Total	\$ 7,926.06
Lump Sum(if applicable)	\$ 6,350.00

Number of days for repair	4
---------------------------	---



Remarks:

4 REPAIR DAYS + 1SUNDAY + 1PRS = 6DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	6,350.00
Loss of use	\$	-
Loss of rental (W/GST)	\$	642.00 6days x \$107
Loss of income	\$	-
LTA search fees	\$	29.00
Others	\$	-
Proposed Total	\$	7,021.00

 **<MANDATE IA> - SOM02F79 {ACCIDENT INVOLVING
SML 5258Z (OI) & SLA 1110L (TP) ON 01/02/2020}**

Type

 Question

Message

LIABILITY: 100% BOLA S22 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$7021 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 02/03/2020

[Reply](#)



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875
Tel: 69763261 Fax: 69763271
Email: tony07auto@gmail.com
Co Reg No. 201906614W

INVOICE

27/2/2020

SLA1110L/02/20

BILL TO

AXA INSURANCE PTE LTD
8 Shenton Way, AXA TOWER
#24-01 Singapore 068811

Vehicle No: SLA1110L
Make/Model: Mercedes Benz C180
Term: Cash/Cheque

ITEM	DESCRIPTION	QTY	UNIT PRICE	TOTAL
1	Being Lump Sum Repair for vehicle SLA1110L Your Reference SML5258Z		S\$ 6350.00	S\$ 6350.00

All cheques should be crossed and made payable to "Tony Automotive Pte Ltd"

Total Amount Due \$ 6,350.00

for Tony Automotive Pte Ltd



◀ Re:<MANDATE IA> - S0M02F79 {ACCIDENT INVOLVING
SML 5258Z (OI) & SLA 1110L (TP) ON 01/02/2020}

Type

🔗 Question

Message

Please proceed

Reply



Tony Automotive Pte Ltd

8 Kaki Bukit Ave 4 #04-07 Premier @ KB Singapore 415875

Tel: 69763261 Fax: 69763261

Email: tony07auto@gmail.com

Co. Reg No.: 201939168R

Your Ref No: SML5258Z

Our Ref No: SLA1110L/02/20

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01, AXA Tower, Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam,

ACCIDENT INVOLVING: SLA1110L and SML5258Z on 01/02/2020

Please refer to the above-mentioned accident.

We are writing on behalf of Zhang Wen Mei, the owner of motor vehicle SLA1110L which was involved in the above accident.

We are instructed that the above accident was caused solely and completely by the negligence of your insured's vehicle SML5258Z.

As a result of the said collision, our client has suffered loss and damage which are set out hereunder as follows (for Property Damage Claim only) :

1. COST OF REPAIR	\$	6,350.00
2. GIA SEARCH	\$	29.00
3. CAR RENTAL(6 DAYS X \$120)	\$	770.40
TOTAL AMOUNT	\$	7,149.40

We enclosed the following support documents for your reference:

- Authorization Letter
- Driver's ID and Driving License
- GIA Search
- Car Rental Invoice and Agreement
- Certificate of Insurance

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Yours Faithfully,


Tony Automotive Pte Ltd


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002133/Hga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:YVONNE

Date : 10-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SML 5258Z	Veh. Inspected	SLA 1110L
Policy No.	GA470638	Coverage (\$)	0.00
Claim No.	S0M02F79	Excess (\$)	0.00
Assign From		Assign Date	06/02/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050402R159598	Colour	BLUE
Odometer	92526	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	MICHELIN	7 mm
L/H Front Tyre	225/50 R17	MICHELIN	7 mm
R/H Rear Tyre	225/50 R17	MICHELIN	7 mm
L/H Rear Tyre	225/50 R17	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/02/2020	Inspection Date	07/02/2020
Survey held at	TONY AUTOMOTIVE PTE. LTD 8 KAKI BUKIT AVENUE 4 #04-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1110L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	CRUMPLED	1,606.37	1,510.40
1	FRONT BUMPER SIDE RETAINER L/H (CONSISTENT)	NECESSARY	153.50	132.40
1	FRONT BUMPER BOTTOM COVER L/H (CONSISTENT)	SERVICEABLE	120.50	-
1	FRONT BUMPER TOP SEAL (CONSISTENT)	SERVICEABLE	25.59	-
1	MOUNTING FOR FRONT BUMPER L/H (CONSISTENT)	NECESSARY	182.40	132.80
1	FRONT GRILLE ASSY (CONSISTENT)	CRACKED	1,080.60	680.80
1	FRONT HEAD LAMP L/H (CONSISTENT)	CRACKED	3,626.25	2,487.70
1	FRONT FENDER L/H (CONSISTENT)	BENT	1,081.86	780.70
1	FRONT FENDER LOWER MOULDING L/H (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT MUDGUARD L/H (CONSISTENT)	CRACKED	160.38	160.38
1	FRONT LOWER ARM L/H (CONSISTENT)	SERVICEABLE	537.00	-
1	FRONT KNUCKLE ARM L/H (CONSISTENT)	SERVICEABLE	790.00	-
1	FRONT KNUCKLE ARM BEARING L/H (CONSISTENT)	CRUMPLED	166.00	166.00
1	FRONT SHOCK ABSORBER L/H (CONSISTENT)	SERVICEABLE	697.00	-
	LESS 10% DISCOUNT		-1,032.25	-605.12
			9,290.20	5,446.06
SPECIAL NETT ITEMS				
1	FRONT SPORT RIM L/H (SN) (CONSISTENT)	SCRATCHED	1,817.00	750.00
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	85.00	40.00
1	SET FRONT SPORT L/H (SN) (CONSISTENT)	SHORTED	450.00	450.00
			2,352.00	1,240.00
LABOUR				
	CHECK FRONT ELECTRICAL WIRING .		150.00	30.00
	CHECK WHEEL ALIGNMENT.		150.00	60.00
	RESPRAY UNDERCOATING.		200.00	50.00
	RESPRAY PAINTING.		1,500.00	480.00
	PANEL BEATING ,REMOVE AND REPLACE ABOVE PARTS ETC.		1,500.00	500.00

Report Ref No. CC4/ASM20002133/Hga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	DISMANTLE AND ASSEMBLE UNDER CARRIAGE FRONT L/H. (ADDITIONAL)		250.00	120.00
			3,750.00	1,240.00
GRAND TOTAL			15,392.20	7,926.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,350.00

Report Ref No. CC4/ASM20002133/Hga3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

⏪ Service Request Details

Claim	SOM02F79	Vehicle Information	
Reference	CC4/AGM00002133/Hga3a2 📄	Incident Vehicle Registration #	SLA1110L
Loss Date	1 February 2020	Make	TPKD MERCEDES-BENZ
Report Date	6 Feb 2020 11:58:00 AM	Model	C180
Request Date	6 February 2020	Service Address	
Due Date		...	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TPH)	Primary Contact/Insured	
Type of Loss	Third Party Vehicle Damage	YEO KIM CHUEN BLK 138 RIVERVALE STREET, #14-756, 340138, Singapore 96655781	
Services	Pending verification • Direct Settlement	Claim Handler	
		ANG Yvonne 6568804461 yvonne.ang@axa.com.sg	

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

📄 Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Reports & Statement				Meriment

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 PAIR CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 LOO AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
MANDATE IA DO 02032020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
RENTAL AGREEMENT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2020
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2020
Service appointment in Vendor Portal claim SOMQ2F79 for vehicle SLA1110L.html	(igetDocumentType_AutItem.documentType.pdf)			6 February 2020
SURVEYOR APPOINTED.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shelhar	6 February 2020
EMAIL TP REQ.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shelhar	6 February 2020
LIST OF SURVEYOR SENT.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shelhar	6 February 2020
GA070638 Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shelhar	6 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 EMAIL TP REG.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shelkar	6 February 2020
 GIA 5M1525BZ INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shelkar	6 February 2020
 GIA SLA111DL TP.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shelkar	6 February 2020
 GA470638-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shelkar	6 February 2020
 LIST OF SURVEYOR SENT.msg	Letters and Correspondence	Workshop	VISHNU BATHAM Shelkar	6 February 2020