

NEW ZEN WERKZ PTE LTD

BLOCK 3 KAKI BUKIT ROAD 1 #03-04 EUNOS TECHNOLINK
SINGAPORE 415935

Tel : (65) 67428117 HP: 92712214 Fax: (65) 67428117

06th FEBRUARY 2020

HOCK LIAN SENG INFRASTRUCTION - SEMBCORP

Blk 3 Kaki Bukit Road 1
03 - 04 Eunoss Technolink
Singapore 415935

TP 1st Cap.
Khanchana

JTFST229100030712

Accident date: 04th FEBRUARY 2020 PC
Estimated repair cost for vehicle no: PA5765M Toyota Hiace HIGH ROOF '17

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid <i>Dented</i>		\$2,500.40 2290
2	1	Rear boot lid HIACE logo		\$74.10 ✓
3	1	Rear boot lid Emble logo		\$61.00 ✓
4	1	Rear boot lid 70Km/h logo		\$20.00 10(SW)
5	1	Rear boot lid center moulding <i>NE new</i>		\$209.10 X
6	2	Rear boot lid hinges <i>NE new</i>	\$131.20	\$262.40 X
7	1	Rear boot lid inner lock <i>Damaged</i>		\$358.20 ✓
8	1	Rear boot lid inner trim board <i>NE new</i>		\$485.00 X
9	10	Rear boot lid inner clips <i>NE new</i>		\$129.00 X
10	1	Rear boot lid inner rubber <i>NE new</i>	\$12.90	\$329.10 X
11	2	Rear boot lid number plate lamp <i>NE new</i>		\$166.40 X
12	1	Rear boot lid number plate	\$83.20	\$50.00 X
13	2	Rear tail lamp <i>RH cracked</i>	\$321.20	\$642.40 321.20
14	2	tail lamp <i>lower Apron RH cracked</i>	\$182.20	\$364.40 90
15	2	Rear tail lamp lower garnish bracket <i>NE new</i>	\$131.75	\$263.50 X
16	1	Rear bumper <i>Distorted</i>		\$582.10 ✓
17	2	Rear bumper <i>lower bracket Bent</i>	\$121.25	\$242.50 60
18	1	Rear bumper reverse sensor <i>Damaged</i>		\$350.00 200(SW)
19	2	rear bumper side retainer <i>NE new</i>	\$155.20	\$310.40 ✓
20	6	Rear bumper clips <i>NE new</i>	\$12.90	\$77.40 30
21	1	Rear end panel (out) <i>Dented</i>		\$580.15 ✓
22	1	Rear end panel (in) <i>Ryis</i>		\$568.10 X
23	1	air duct <i>Dented</i>		\$155.00 83
24	1	Rear floor panel top carpet <i>NE new</i>		\$580.55 X
25	1	Rear spare tire bracket		\$288.20 X
26	1	Rear exhaust <i>NE new</i>		\$1,020.10 X
Subtotal :-				<u>\$10,669.20</u>

484015 S.N: 220 210

360761

Labour charges

To remove & re-fix rear windscreen

Gum

To remove & re-fix rear reverse sensor

To remove & re-fix rear exhaust

To remove & re-fix rear cushion

Tuff kote

To check wiring system

Panel beating

Spray painting

\$120.00 ✓

\$50.00 ✓

~~\$100.00~~ 50

~~\$180.00~~ x

~~\$150.00~~ 60

~~\$120.00~~ 60

~~\$80.00~~ 30

~~\$1,200.00~~ 1000

~~\$1,200.00~~ 1000

Subtotal :-

\$3,200.00

Total :-

\$13,869.20

2370

total: 6207.61

h/8: 4950

07 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: