



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20002163/Esf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 16-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 8773G	Veh. Inspected	SMF 8385B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000595/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/02/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1SJGK85GG081047	Colour	SILVER
Odometer	70097	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/02/2020	Inspection Date	07/02/2020
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------