



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 6451E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	AXLE WHEEL	BENT	58.00	58.00
1	BAR HANDLE ZETA (BLUE)	BENT	180.00	180.00
1	BEARING STEERING CONE LOWER	NECESSARY	64.00	64.00
1	SET BOX SIDE TOURATECH ZEGA PRO 2 31L	SCRATCHED	1,860.00	1,860.00
1	BRACKET, HANDLE 4	CRUMPLED	6.00	6.00
1	COVER HANDLE RH	SCRATCHED	22.00	22.00
1	CRASH BAR TOURATECH SILVER	NOT NECESSARY	650.00	-
1	CROWN, HANDLE	NOT NECESSARY	106.00	-
1	FRONT FORK ASSY (L.H)	BENT	1,374.00	1,374.00
1	FRONT FORK ASSY (R.H)	BENT	1,374.00	1,374.00
1	FRONT MUDGUARD	SCRATCHED	117.00	117.00
1	GRIP (DOMINO) ROAD-RACING BLACK/BLUE	NECESSARY	38.00	38.00
2	HOLDER DAMPER @\$9.60	NOT NECESSARY	19.20	-
1	LEVER BRAKE	SERVICEABLE	81.00	81.00
1	MIRROR RH	SCRATCHED	69.00	69.00
1	PANEL 2	SCRATCHED	154.00	154.00
2	PLATE DISC BRAKE FRONT @\$270.00	NOT NECESSARY	540.00	-
1	RIM (2.50-19)	BENT	529.00	529.00
1	SPOKE SET FRONT	NECESSARY	91.00	91.00
1	UNDER BRACKET COMP	NECESSARY	645.00	645.00
1	VALVE RIM	NECESSARY	9.00	9.00
1	EMBLEM (ADDITIONAL)	NECESSARY	17.00	17.00
1	MOLD, FUEL TANK (ADDITIONAL)	TWISTED	17.00	17.00
2	MOLD, FUEL TANK @\$17.00 (ADDITIONAL)	TWISTED	34.00	34.00
1	SET POWDER COAT CRASH BAR (ADDITIONAL)	NOT NECESSARY	185.00	-
1	SKID PLATE (ADDITIONAL)	BENT	278.00	278.00
	LESS 10% DISCOUNT		-	-701.70
			8,517.20	6,315.30
<u>SPECIAL NETT ITEMS</u>				
1	TYRE 110/80-19 (BRIDGESTONE) BATTLEX A41 (SN) (60%)(ADDITIONAL)	WARPED	170.00	102.00

Report Ref No. CS/AGI20002180/Htf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR		170.00	102.00
	LABOUR - FOR DISMANTLING & ASSEMBLING OF PARTS QUOTED.		540.00	480.00
	SPRAY PAINT FUEL TANK. (ADDITIONAL)		150.00	150.00
			690.00	630.00
	GRAND TOTAL		9,377.20	7,047.30

RECOMMENDED COST OF REPAIRS			7,047.30
LESS EXCESS			-300.00
NETT LIABILITY			6,747.30

Report Ref No. CS/AGI20002180/Htf3e2

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.