



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2101127
3 ANSON ROAD #16-00	INV Date	22/02/2021
SPRINGLEAF TOWER	Reference	CC6/CTI20002181/Uga3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	GBH 8699R
Insured Veh.	GBJ 2060L
Claim No.	SNM20D200773
Policy No.	DMCVSNW00003142000
Accident Date	07/02/2020
Inspection Date	07/02/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI20002181/Uga3q2 Date: 22/02/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 2060L	Veh. Inspected	GBH 8699R
Policy No.	DMCVSNW00003142000	Coverage (\$)	0.00
Claim No.	SNM20D200773	Excess (\$)	0.00
Assign From		Assign Date	07/02/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFAT35Y80K211597	Colour	WHITE
Odometer	16022 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm
L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/02/2020	Inspection Date	07/02/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8699R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	TAILLAMPS @\$350.00	CRACKED	700.00	634.00
2	TAILLAMP HOUSING PANELS @\$185.00	O/S BENT	370.00	135.00
1	REAR LICENCE PLATE BRACKET	BENT	221.10	188.50
1	REAR EXHAUST	TO REPAIR SEE LABOUR	657.50	-
1	REAR SPARE TYRE BRACKET & CHAIN	SERVICEABLE	485.10	-
1	REAR END PANEL	DENTED / BENT	785.10	645.20
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,800.00	-
1	FRONT BUMPER	DENTED/ DEFORMED	866.01	727.10
2	FRONT BUMPER BRACKETS @\$399.00	BENT	798.00	798.00
1	FRONT GRILLE	CRACKED	1,205.10	573.21
1	FRONT GRILLE LOGO	SCRATCHED	145.00	95.00
2	HEADLAMPS @\$2500.00	CRACKED	5,000.00	2,291.60
1	FRONT PANEL	BADLY DENTED	1,688.10	1,144.00
1	FRONT PANEL 'DYNA' EMBLEM	NECESSARY	168.50	86.50
1	FRONT WIPER PANEL GARNISH	DENTED	850.10	620.50
2	FRONT NOZZLES @\$145.00	NOT NECESSARY	290.00	-
2	FRONT WIPER ARMS @\$188.00	NOT NECESSARY	376.00	-
2	FRONT CORNER PANELS @\$450.10	TO REPAIR SEE LABOUR	900.20	-
1	FRONT VIEW MIRROR BRACKET N/S	TO REPAIR SEE LABOUR	625.10	-
1	FRONT VIEW MIRROR ROUND N/S	BROKEN / MISSING	250.00	185.00
1	FRONT CROSS MEMBER	TO REPAIR SEE LABOUR	899.20	-
1	DASHBOARD	DEFORMED / TORN	1,488.20	923.60
1	DASHBOARD BRACKET	NOT NECESSARY	695.30	-
1	AIR CON BLOWER	CRACKED	1,450.00	1,345.32
1	AIR CON HEATER UNIT	CRACKED	2,250.00	2,033.25
1	FRONT WINDSCREEN RUBBER	NECESSARY	322.20	266.50

Report Ref No. CC6/CTI20002181/Uga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-3,173.07
			26,285.81	9,519.21
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT LICENCE PLATE (SN)	SERVICEABLE	20.00	-
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR CARGO BOX BACK DOOR LH (SN)	DENTED / BENT	1,800.00	1,100.00
1	REAR CARGO BOX BACK DOOR LOCK BAR LH (SN)	BENT	680.00	380.00
1	REAR CARGO BOX BACK DOOR LOCK CATCH LH (SN)	DENTED	100.00	80.00
1	REAR CARGO BOX BACK DOOR INNER CHECKER PLATE LH (SN)	BENT	600.00	200.00
1	REAR 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	REAR CARGO BOX BACK DOOR RH (SN)	DENTED / BENT	1,800.00	1,100.00
1	REAR CARGO BOX BACK DOOR LOCK BAR RH (SN)	BENT	680.00	380.00
1	REAR CARGO BOX BACK DOOR LOCK CATCH RH (SN)	DENTED	100.00	80.00
1	REAR CARGO BOX BACK DOOR INNER CHECKER PLATE RH (SN)	BENT	600.00	200.00
1	REAR CARGO BOX BACK DOOR HINGE RH (SN)	NOT NECESSARY	280.00	-
1	REAR LICENCE PLATE (SN)	BENT	20.00	15.00
1	REAR CARGO BOX LOWER SAFETY BAR (SN)	CRACKED / BENT	1,200.00	1,000.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR CARGO BOX RIVET (SN)	NECESSARY	50.00	50.00
1	REAR CARGO BOX PILLAR RH (SN)	TO REPAIR SEE LABOUR	850.00	-
1	REAR CARGO BOX FLOOR TOP CHECKER PLATE (SN)	BUCKLED	2,800.00	1,500.00
			11,930.00	6,345.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REAR CARGO BOX .	NOT NECESSARY	600.00	-
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO DISMANTLE & REPLACING FRONT DASHBOARD .		300.00	200.00

Report Ref No. CC6/CTI20002181/Uga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX FRONT WINDSCREEN .		100.00	80.00
	TO REFILL AIR CON GAS.		150.00	100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,REAR FLOOR PANEL,FRONT CORNER PANELS,FRONT VIEW MIRROR BRACKET N/S,FRONT CROSS MEMBER AND REAR CARGO BOX PILLAR RH.		2,500.00	2,200.00
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,480.00
			6,010.00	4,220.00
	<b>GRAND TOTAL</b>		<b>44,225.81</b>	<b>20,084.21</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>16,000.00</b>
---	--	--	--	------------------

Report Ref No. CC6/CTI20002181/Uga3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBH 8699R

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 8699R

RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBH 8699R

## RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. GBH 8699R

## RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

