

not allowed
d/m
7/1/20
2/5 @ 16,000 /
12 days.

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO:GBH 8699R

QTY	PARTICULAR			
1 PCS	TAILLAMPS @\$350.00	317. x 2 = 634.00	CNA	\$700.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$185.00	135.00	o/sent	\$370.00 1PC
1 PCS	REAR LICENCE PLATE BRACKET	188.50	sent	\$221.10 ✓
1 PCS	REAR EXHAUST		n	\$657.50 X
1 PCS	REAR SPARE TYRE BRACKET & CHAIN		SVC	\$485.10 X
1 PCS	REAR END PANEL	645.20	no/sent	\$785.10 ✓
1 PCS	REAR FLOOR PANEL		n	\$2,800.00 X
1 PCS	FRONT BUMPER	727.10	no/sent	\$866.01 ✓
2 PCS	FRONT BUMPER BRACKETS @\$399.00		sent	\$798.00 ✓
1 PCS	FRONT GRILLE	573.21	CNA	\$1,205.10 ✓
1 PCS	FRONT GRILLE LOGO	95.00	SVC	\$145.00 ✓
2 PCS	HEADLAMPS @\$2500.00	1145.80 x 2 = 2291.60	CNA	\$5,000.00 ✓
1 PCS	FRONT PANEL	1144.00	Body	\$1,688.10 ✓
1 PCS	FRONT PANEL 'DYNA' EMBLEM	85.50	n	\$168.50 ✓
1 PCS	FRONT WIPER PANEL GARNISH	620.50	n	\$850.10 ✓
2 PCS	FRONT NOZZLES @\$145.00		11	\$290.00 X
2 PCS	FRONT WIPER ARMS @\$188.00		11	\$376.00 X
2 PCS	FRONT CORNER PANELS @\$450.10		n	\$900.20 X
1 PCS	FRONT VIEW MIRROR BRACKET N/S		n	\$625.10 X
1 PCS	FRONT VIEW MIRROR ROUND N/S	185.00	HW/mis	\$250.00 ✓
1 PCS	FRONT CROSS MEMBER		n	\$899.20 X
1 PCS	DASHBOARD	923.60	no/sent	\$1,488.20 ✓
1 PCS	DASHBOARD BRACKET		n	\$695.30 X
1 PCS	AIR CON BLOWER	1345.32	CNA	\$1,450.00 ✓
1 PCS	AIR CON HEATER UNIT	2033.25	CNA	\$2,250.00 ✓
1 PCS	FRONT WINDSCREEN RUBBER	266.50	n	\$322.20 ✓
				\$26,285.81
	S.NETT			
1 PCS	FRONT LICENCE PLATE		SVC	\$20.00 X
1 SET	FRONT GRILLE CLIPS		n	\$50.00 ✓
1 PCS	REAR CARGO BOX BACK DOOR LH		no/sent	\$1,800.00 1100
1 PCS	REAR CARGO BOX BACK DOOR LOCK BAR LH		sent	\$680.00 300
1 PCS	REAR CARGO BOX BACK DOOR LOCK CATCH LH		n	\$100.00 80
1 PCS	REAR CARGO BOX BACK DOOR INNER CHECKER PLATE LH		sent	\$600.00 200
1 PCS	REAR 70 KM/H STICKER		n	\$20.00 10
1 PCS	REAR CARGO BOX BACK DOOR RH		no/sent	\$1,800.00 1100
1 PCS	REAR CARGO BOX BACK DOOR LOCK BAR RH		sent	\$680.00 300
1 PCS	REAR CARGO BOX BACK DOOR LOCK CATCH RH		n	\$100.00 80
1 PCS	REAR CARGO BOX BACK DOOR INNER CHECKER PLATE RH		sent	\$600.00 200
1 PCS	REAR CARGO BOX BACK DOOR HINGE RH		n	\$280.00 X
1 PCS	REAR LICENCE PLATE		sent	\$20.00 15
1 PCS	REAR CARGO BOX LOWER SAFETY BAR		CNA/sent	\$1,200.00 1000
1 SET	REAR REVERSE SENSOR		shuld	\$280.00 200
1 SET	REAR CARGO BOX RIVET		n	\$50.00 ✓
1 PCS	REAR CARGO BOX PILLAR RH		n	\$850.00 X

257

1 PCS	REAR CARGO BOX FLOOR TOP CHECKER PLATE	Buc	\$2,800.00	1500
	LABOUR CHARGES			
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00	50
	TO DISMANTLE & REFIX REAR EXHAUST	1A	\$80.00	X
	TO DISMANTLE & REFIX REAR CARGO BOX	11	\$600.00	X
	TO SPRAY RUST PROOFING		\$120.00	80
	TO DISMANTLE & REPLACING FRONT DASHBOARD		\$300.00	200
	TO DISMANTLE & REFIX FRONT WINDSCREEN		\$100.00	80
	TO REFILL AIR CON GAS		\$150.00	100
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$2,500.00	2200
	TO PUTTY & SPRAY PAINTING		\$2,000.00	1480
	TOTAL		\$43,725.81	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-12692.28
 252
 P-9519.21
 S.N-6345.00
 L-4220.00
 2008.21
 203
 16267