

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2075M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID GLASS (WCP)	SCRATCHED	937.66	937.66
4	BOOT LID GLASS SCREW @ \$2.00 (WCP)		8.00	8.00
1	BOOT LID GLASS EMBLEM (WCP)	NECESSARY	59.35	59.35
1	BOOT LID GLASS LOGO (WCP)	NECESSARY	30.41	30.41
1	REAR BUMPER ASSY (WCP)	DEFORMED	823.08	823.08
10	REAR BUMPER SCREW @ \$2.00 (WCP)	NECESSARY	20.00	20.00
1	REAR BUMPER REFLECTOR LH (WCP)	MISSING	47.92	47.92
1	REAR BUMPER REFLECTOR RH (WCP)	MISSING	47.92	47.92
1	REAR BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	79.46	-
1	REAR BUMPER REINFORCEMENT BRACKET (WCP)	NOT NECESSARY	10.83	-
1	REAR BUMPER REINFORCEMENT BRACKET (WCP)	NOT NECESSARY	10.83	-
1	NUMBER PLATE LAMP LH (WCP)	NOT NECESSARY	42.00	-
1	NUMBER PLATE LAMP RH (WCP)	NOT NECESSARY	38.48	-
1	REAR RH FENDER COVER (WCP)	DEFORMED	188.00	188.00
	COST PLUS 15%		351.59	324.35
			2,695.53	2,486.69
	SPECIAL NETT ITEMS			
1	STICKER (BLUESG) (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE W/CASING (SN)	CRACKED	45.00	45.00
1	FRONT NUMBER PLATE W/CASING (SN)	CRACKED	45.00	45.00
			140.00	140.00
	<u>LABOUR</u>			
	TO REPAIR, REPLACE REAR GLASS, REAR BUMPER, REFLECTOR, NUMBER PLATE, STICKERS AND AFFECTED AREA.		100.00	300.00
	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED AREA.	NOT NECESSARY	300.00	-
	TO APPLY TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
			650.00	330.00

Report Ref No. CC6/EQI20002184/Gpa3s2



Page No.:2 of 2

GRAND TOTAL	3,485.53	2,956.69
PECOMMENDED COST OF PEDAIRS		2 956 69

Report Ref No. CC6/EQI20002184/Gpa3s2

XING GUO QIANG

M.MATAI, AMSAE-A
Automotive Assessor

mont

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.