



No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISIO Tel: (65) 382 2736 FAX: (65) 6382 2817

### ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SLV2075M

Type of Claim : TP

Vehicle No. : SLV2075M

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. VL4BCEB4RHT003092

Ins Company : EQ INSURANCE COMPANY LIMITED

Excess :

Date of Accident : 9/1/2020

Engine No. : 921955Q15R310844118

Policy No. :

Time of Accident : 20:05

Suggested Days of Repair : 4

Case Owner BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : GBH806B

#### Repair Estimates

Parts (a) Cost / List Price Items \$ 2,155.95

Plus/Less— 20.0% \$ 431.19

Total of Cost / List \$ 2,587.14

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 140.00

Total Parts Cost (Appendix A) \$ 2,727.14

Labour (Appendix B) \$ 1,550.00

Total Repair Cost \$ 4,277.14

The above total will be subjected to 7% G.S.T.

Name of Surveyor :

Company :

Survey conducted on :  at

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair :  day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor :  Date:



VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**ESTIMATED REPAIR COST DETAILS**

Vehicle No : SLV2075M Case Owner : BLUECAR EAST ASIA  
 Make & Model : BLUECAR Year Manufacture : PTE LTD  
 Chassis No : VL4BCEB4RHT003092 Engine No : 2017  
 Date & Time : \_\_\_\_\_ Supplier : 921955Q15R310844118  
 Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	BOOT LID GLASS	1	\$ 937.66	\$ 937.66			
2	BOOT LID GLASS SCREW	4	\$ 2.00	\$ 8.00			
3	BOOT LID GLASS EMBLEM	1	\$ 59.35	\$ 59.35			
4	BOOT LID GLASS LOGO	1	\$ 30.41	\$ 30.41			
5	STICKER (BLUESG)	1					\$ 50.00
6	REAR BUMPER ASSY	1	\$ 823.08	\$ 823.08			
7	REAR BUMPER SCREW	10	\$ 2.00	\$ 20.00			
8	REAR BUMPER REFLECTOR LH	1	\$ 47.92	\$ 47.92			
9	REAR BUMPER REFLECTOR RH	1	\$ 47.92	\$ 47.92			
10	REAR BUMPER REINFORCEMENT	1	\$ 79.46	\$ 79.46			
11	REAR BUMPER REINFORCEMENT BRACKET	1	\$ 10.83	\$ 10.83			
12	REAR BUMPER REINFORCEMENT BRACKET	1	\$ 10.83	\$ 10.83			
13	REAR NUMBER PLATE W CASING	1					\$ 45.00
14	NUMBER PLATE LAMP LH	1	\$ 42.00	\$ 42.00			
15	NUMBER PLATE LAMP RH	1	\$ 38.48	\$ 38.48			
16	FRONT NUMBER PLATE W CASING	1					\$ 45.00
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL** \$ 2,131.95 \$ 2,155.95 \$ - \$ - \$ 140.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR  
EAST ASIA  
PTE LTD

Case Owner

Year of Manufacture

2017

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*