

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ESTIMATED REPAIR COST DETAILS

BLUECAR EAST ASIA : PTE LTD **Vehicle No** : SLV2075M Case Owner Make & Model : BLUECAR : 2017 Year Manufacture : 921955Q15R310844118 Chassis No : VL4BCEB4RHT003092 **Engine No** Date & Time Supplier : <u>TP</u> Order By Type of Claim

S/No	Part Description	αту	Cost Price				List	Nett	S/N
S/NO				Unit	Sub	-Total	Price	Price	J
1	BOOT LID GLASS COP	1	\$	937.66	\$	937.66			
2	BOOT LID GLASS SCREW / (4	\$	2.00	\$	8.00			
3	BOOT LID GLASS EMBLEM	1	\$	59.35	\$	59.35			
4	BOOT LID GLASS LOGO	1	\$	30.41	\$	30.41			
5	STICKER (BLUESG)	1							\$ 50.00
6	REAR BUMPER ASSY / DL	1	\$	823.08	\$	823.08			
7	REAR BUMPER SCREW / NCC .	10	\$	2.00	\$	20.00			
8	REAR BUMPER REFLECTOR LH	1	\$	47.92	\$	47.92			
9	REAR BUMPER REFLECTOR RH	1	\$	47.92	\$	47.92			
10	REAR BUMPER REINFORCEMENT X NN	a^1	\$	79.46	\$	79.46			
11	REAR BUMPER REINFORCEMENT BRACKET		ij	10.83	\$	10.83			
12	REAR BUMPER REINFORCEMENT BRACKET	St L	Ŗ	10.83	\$	10.83			
13	REAR NUMBER PLATE W CASING / CALL	, 1							\$ 45.00
14	NUMBER PLATE LAMP LH 🕺 NN	1	\$	42.00	\$	42.00			
15	NUMBER PLATE LAMP RH 🗘 NN	1	\$	38.48	\$	38.48			
16	FRONT NUMBER PLATE W CASING /	,1							\$ 45.00
17 (0	0							
18 (pear PH Fonder Cover	0		De		188			
19 (0							
20 0)	0							
21 0		0				216	2.34		
22 0		0					%·2486 6	a	
23 0		0					140		
24 0		0				<u> </u>	110		
25 0		0							
26 0		0			-				+
7 0		0							-
8 0		0	-						
9 0		0			-				
0 0		0		+					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 2,131.95 \$ 2,155.95 \$

\$



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

BLUECAR EAST ASIA : DTE LTD

Vehicle No. :

SLV2075M

Case Owner

Make & Model:

BLUECAR

Year of Manufacture

2017

S/No	Labour Description		Esimated Price	Adjusted Price
1	O REPAIR, REPLACE REAR GLASS, REAR BUMPER, REFLECTOR,		\$1,000.00	300
	NUMBER PLATE, STICKERS AND AFFECTED AREA			
2	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED A	AREA	\$300.00	ŽOO NN
3			2450.00	× NN
	TO APPLY TUFF KOTE		\$150.00	7 1111
4			\$100.00	30
_	TO CHECK WIRING		Anna di Santa Anna di Santa d	
5				
6	Total:2956.69			
7	Hays.			
8				
-				
	LKK Auto Consultants hence notify			
	the Repairer of the following:			+
	To resurvey before/after spray painting To display damaged part(s) during resurvey			
\neg	Parts prices are subject to confirmation			
\dashv	Third party survey is on a "Without Prejudice" basis			
-	▶ No illegal medification(s) iş allowed			
+	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
+	Acknowledged by Repairer			
\top	Signature:			
+	Date:			
+				
				-
T		TOTAL	\$1,550.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.