

ASS. REC. BY:

REF:

CS/CTI 20007144/G v f3/12

Special Instructions:

Survey: 66

ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 02/21/2004.9M

Estimated Cost: Bill for:

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No: SJS 9229E Insured: PC 3354D

at Workshop m/s Premium Tel:

of Ubi

Policy No: Claim No: SNA 200200676

Sum Insured: Excess:

Make of Veh: D.O.A. 06/21/20

(Client's Record)

CA / REV / REP. / REV 24 HRS 10/21/20 @ 3pm owner waiting

Date/Time: H.O.D. Endorsement:

Person Contacted: Vehicle IN/OUT

Date/Time Action/Instruction Vehicle

SJS 9229E - X

PC 3354D - X

27/3/20 Final fig \$ 16,563.20 confirmed by email (Recd 8249.84, 3370)

ASSIGNMENT

From:

Date:

10/7/20

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJS 9229E

at Workshop m/s

Premium

of

Ush

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

3m
owner waitingRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

w/p

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJS 9229E

Yr Regn:

22 Sep 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

c.c.

1395

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

30898

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ F43HA 18249

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

10-02-20

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

3pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2. 27/2 - typist

Report Form:

Merimen

Lump Sum / LBJ: 12

16,563.20

Days Of Repair:

7

Resurvey No. of Trip:

2

Arid Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Final Insp (\$

Survey Fee:

Transportation:

S + RS \$

Fines:

(Other):

Total:

220

Summer Lee (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Friday, 7 February, 2020 4:51 PM
To: Claims Dept
Cc: assignments; Admin A
Subject: RE: OUR REF: SNM20D200676/PC3354D/IRENE - ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with PREMIUM AUTO to conduct survey.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Friday, February 7, 2020 3:35 PM
To: 'Claims' <claims@premiumauto.com.sg>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200676/PC3354D/IRENE - ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear Irene,

Could you let us know who can we arrange survey on next Monday?

Kindly update us by today.

Our client may engage lawyer for injury claim.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.mailto:claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Friday, 7 February 2020 3:18 PM

To: 'Claims Dept'; 'Claims Dept of CTI'; 'Irene Tay'

Cc: 'Claims'

Subject: RE: OUR REF: SNM20D200676/PC3354D/IRENE - ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear all,

Attached is the estimate for your reference.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Friday, 7 February 2020 12:00 PM
To: 'Claims Dept of CTI'; 'Irene Tay'
Cc: 'Claims Dept'
Subject: RE: OUR REF: SNM20D200676/PC3354D/IRENE - ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear Irene,

Kindly let us know who should we arrange survey with?

We have arrange survey on next Monday

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Singapore 408699
p. +65 6366 2323, d. +65 67689911
[e.mailto:claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]
Sent: Friday, 7 February 2020 11:28 AM
To: claims@premiumauto.com.sg; Irene Tay
Cc: Claims Dept of CTI
Subject: OUR REF: SNM20D200676/PC3354D/IRENE - ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear Irene,

Please conduct PRS for SJS9229E.

Note : officer in charge – Irene 63896192.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, February 7, 2020 9:34 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: ACCIDENT BETWEEN SJS 9229 E AND YOUR INSURED PC 3354 D ON 6/2/2020

Dear all,

Kindly assist in the liability clearance for above mentioned case. We propose for a 100% direct settlement in our client's favour

Please advise who is the officer in-charge we shall liaise with. To avoid dispute during finalisation, we propose for LOU/R at \$60/100 per day.

Attached is the GIA report for your reference and we will send you the estimate once it is ready.

Kindly arrange survey on 10/02/2020, 3PM. Owner waiting.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No: 1999402275W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 March 2020 5:15 PM
To: 'Boo seng yak'; claims@premiumauto.com.sg; SUR
Subject: RE: FINAL REVISION - SJS9229E - TP CHINA - SURVEYED 10 FEB 20

Dear Mr Boo,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 27 March 2020 4:52 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: FINAL REVISION - SJS9229E - TP CHINA - SURVEYED 10 FEB 20

Hi Veron,

OK closed.

Rgds - jb

On Fri, Mar 27, 2020 at 9:14 AM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Mr Boo,

WITHOUT PREJUDICE

As agree with Guo Qiang No 4. Labour revised to \$3150.00

Please confirmed amount \$16,563.20 @ 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 26 March 2020 12:10 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: FINAL REVISION - SJS9229E - TP CHINA - SURVEYED 10 FEB 20

Hi Veron

I will review the case later with Adrian.

Best regards jb

On Thu, 26 Mar 2020, 11:54 Veron Chen (LKKAuto), <veronchen@lkkauto.com> wrote:

Dear Mr Boo,

WITHOUT PREJUDICE

No 4. Labour surveyor revised to \$2800 instead of \$3500

Please confirmed amount \$16,213.20 @ 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Wednesday, 25 March 2020 3:33 PM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; Jiayee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SJS9229E - TP CHINA - SURVEYED 10 FEB 20

Hi Guo Qiang and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$16,913.20 @ 7 days exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	051J
Vehicle No.:	SJS9229E
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVN041505
Chassis No.:	WAUZZZF43HA182419
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,096.00
Original Registration Date:	22 Sep 2017
First Registration Date:	22 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$26,935.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2027
PARF Rebate Amount:	\$20,201.00
COE Expiry Date:	21 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$37,308.00
Total Rebate Amount:	\$57,509.00

The information contained herein is correct as at 10 Feb 2020

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28712

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0146/2020/NS
Date : 7-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : PC 3354 D

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Au-Yong Kok Keong Kenneth
Address : 370B Alexandra Road
#03-04
Singapore 159955
Telephone : HP +65 96736454
Type of Claim : Third Party Claim
Policy No. : 1700053943-02
Vehicle No : **SJS 9229 E**
Model Code : A4 1.4 TFSI S
Model / Year : Sep-17
Engine No : CVN 041505
Chassis No : WAUZZZF43HA182419
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Feb-20
Place of Accident : Slip Road To Bishan St 21

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 9229 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness and tail lights.	S/N \$ 280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	✓
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld rear end panelling inner and outer. To repair spare wheel housing. Re-organise rear crash management components. Reinstall all parts removed.	700 \$ 4,550.00	1400 3500 2800 3150
5	To respray rear bumper, rear lid, hinges, spare wheel housing and end panelling. To carry out joint sealer works and stone chip treatment	700 800 ✓ \$ 4,000.00	3000 1500 3000
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,862.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 9229 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / Re	\$ 2,079.00	2079
2	REAR BUMPER FIXING PARTS 7 X NN	\$ 69.00	
3	REAR BUMPER SECURING STRIP / Re	\$ 210.00	210
4	REAR BUMPER SPOILER - LH / RH 7 X NN	\$ 234.00	234
5	REAR LIGHT REFLECTOR - LH / RH X NN	2 \$ 78.00	
6	REAR BUMPER CARRIER 7 BT	\$ 845.00	845.50
7	REAR BUMPER SEAL 7 BT	2 \$ 26.00	26
8	REAR BUMPER GUIDE SECTION - LH 7 X NN	\$ 41.00	
9	REAR BUMPER GUIDE SECTION - RH 7 X NN	\$ 43.00	
10	REAR BUMPER GUIDE SECTION - LH / RH 7 BT	2 \$ 42.00	41.40
11	REAR PARKING AID SENSOR - INNER/ OUTER 1 PC 2 DM 462 TBC	2 \$ 14.00	231
12	REAR PARKING AID SEAL RING / Re	4 \$ 14.00	13.00
13	REAR BUMPER WIRING SET 7 X NN	\$ 633.00	
14	BOOT LID CONTROL UNIT 7 X NN	\$ 392.00	
15	REAR LID / BT	\$ 2,496.00	2496
16	REAR LID HINGE - LH / RH 7 X NN	2 \$ 432.00	
17	REAR LID LOCK 7 X NN	\$ 217.00	
18	LID LOCK PUSH BUTTON X NN	\$ 510.00	
19	REAR LID LOCK STRIKER X NN	\$ 31.00	
20	REAR LID FLAP GASKET / Re	\$ 193.00	193
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,585.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 9229 E

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	PACKING ADHESIVE <i>h</i> ✓ <i>MC</i>	\$	18.00	17.80
22	AUDI EMBLEM <i>-</i>	\$	117.00	116.50
23	A4 INSCRIPTION <i>-</i> <i>h</i> <i>MC</i>	\$	90.00	89.70
24	TFSI INSCRIPTION <i>-</i>	\$	90.00	89.70
25	REAR CROSS PANEL <i>h</i> ✓ <i>MC</i>	\$	245.00	244.50
26	CROSS PANEL REINFORCEMENT <i>h</i> ✓ <i>BT</i>	\$	475.00	475
27	LED TAIL LIGHT - LH INNER <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	959.00	
28	TAIL LIGHT TRIM - LH INNER <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	28.00	
29	LED TAIL LIGHT - RH INNER <i>h</i> ✓ <i>RA</i>	\$	959.00	959
30	TAIL LIGHT TRIM - RH INNER <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	28.00	
31	LED TAIL LIGHT - RH OUTER <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	959.00	
32	TAIL LIGHT TRIM - RH OUTER <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	28.00	
33	REAR CROSS PANEL TRIM <i>h</i> ✓ <i>RE</i>	\$	156.00	156
34	LUGGAGE COMPARTMENT FLOOR <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	669.00	
35	REAR LID TRIM PANEL <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	\$	310.00	
36	LED LICENSE PLATE LIGHT <i>h</i> <i>x</i> <i>h</i> <i>NN</i>	2 \$	195.00	
37	REAR NO PLATE <i>h</i> <i>BT</i>	S/N \$	40.00	40
38	ACRYLIC SEALANT <i>h</i> ✓ <i>h</i> <i>NN</i>	S/N \$	180.00	180
39	CAVITY WAX <i>h</i> ✓ <i>h</i> <i>NN</i>	S/N \$	140.00	140
40	STONE CHIP <i>h</i> ✓ <i>h</i> <i>NN</i>	S/N \$	180.00	180
41	SUNDRIES <i>h</i> ✓ <i>h</i> <i>NN</i>	\$	500.00	44.90

TOTAL SPARE PARTS CHARGES

: \$ 14,951.00

TOTAL LABOUR CHARGES

: \$ 9,862.00

GRAND TOTAL

: \$ 24,813.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

25275

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

7/5 Days.
11/2/2020

Name : *Guo Qiang - 82880282*
Surveyed Date :
Authorised Date : *10/2/2020*
Excess Cost :
Liability :
Remarks : *before paint photos.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28712

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0146/2020/NS
Date : 7-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : PC 3354 D

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Guo Qiang

You recommended 5 days

We took 7 days exclude 1 Sunday

jb 25 Mar 20

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Au-Yong Kok Keong Kenneth
Address : 370B Alexandra Road
#03-04
Singapore 159955
Telephone : HP +65 96736454
Type of Claim : Third Party Claim
Policy No. : 1700053943-02
Vehicle No : **SJS 9229 E**
Model Code : A4 1.4 TFSI S
Model / Year : Sep-17
Engine No : CVN 041505
Chassis No : WAUZZZF43HA182419
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Feb-20
Place of Accident : Slip Road To Bishan St 21

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJS 9229 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system and wire harness and tail lights.	S/N \$ 280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	\$ 480.00
4	To dismantle and renew rear bumper and rear lid. <i>Cut out and reweld rear end panelling inner and outer. To repair spare wheel housing.</i> Re-organise rear crash management components. Reinstall all parts removed. (Added 3 days = \$2100.00)	\$ 4,550.00	\$ 3,500.00
5	To respray rear bumper, rear lid, hinges, <i>rear panel(inner/outer) and spare tyre housing</i> To carry out joint sealer works and stone chip treatment <i>(Added \$800.00 +700.00)</i>	\$ 4,000.00	\$ 3,000.00
6	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 9,862.00	\$ 7,812.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 9229 E

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 2,079.00	\$ 2,079.00
2	REAR BUMPER FIXING PARTS	\$ 69.00	
3	REAR BUMPER SECURING STRIP	\$ 210.00	\$ 210.00
4	REAR BUMPER SPOILER - LH	\$ 234.00	\$ 234.00
5	REAR LIGHT REFLECTOR - LH / RH	2 \$ 78.00	
6	REAR BUMPER CARRIER	\$ 845.00	\$ 844.50
7	REAR BUMPER SEAL	2 \$ 26.00	\$ 26.00
8	REAR BUMPER GUIDE SECTION - LH	\$ 41.00	
9	REAR BUMPER GUIDE SECTION - RH	\$ 43.00	
10	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 42.00	\$ 41.40
11	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 231.00	\$ 231.00
12	REAR PARKING AID SEAL RING	4 \$ 14.00	\$ 13.20
13	REAR BUMPER WIRING SET	\$ 633.00	
14	BOOT LID CONTROL UNIT	\$ 392.00	
15	REAR LID	\$ 2,496.00	\$ 2,496.00
16	REAR LID HINGE - LH / RH	2 \$ 432.00	
17	REAR LID LOCK	\$ 217.00	
18	LID LOCK PUSH BUTTON	\$ 510.00	
19	REAR LID LOCK STRIKER	\$ 31.00	
20	REAR LID FLAP GASKET	\$ 193.00	\$ 193.00
SUB TOTAL SPARE PARTS CHARGES		: \$ 8,816.00	\$ 6,368.10

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1163

Telefax

Material List for Accident Vehicle Regn No. SJS 9229 E

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remarks
		cf		\$ 6,368.10
21	PACKING ADHESIVE		\$ 18.00	\$ 17.80
22	AUDI EMBLEM		\$ 117.00	\$ 116.50
23	A4 INSCRIPTION		\$ 90.00	\$ 89.70
24	TFSI INSCRIPTION		\$ 90.00	\$ 89.70
25	REAR CROSS PANEL		\$ 245.00	\$ 244.50
26	CROSS PANEL REINFORCEMENT		\$ 475.00	\$ 475.00
27	LED TAIL LIGHT - LH INNER		\$ 959.00	
28	TAIL LIGHT TRIM - LH INNER		\$ 28.00	
29	LED TAIL LIGHT - RH INNER		\$ 959.00	\$ 959.00
30	TAIL LIGHT TRIM - RH INNER		\$ 28.00	
31	LED TAIL LIGHT - RH OUTER		\$ 959.00	
32	TAIL LIGHT TRIM - RH OUTER		\$ 28.00	
33	REAR CROSS PANEL TRIM		\$ 156.00	\$ 156.00
34	LUGGAGE COMPARTMENT FLOOR		\$ 669.00	
35	REAR LID TRIM PANEL		\$ 310.00	
36	LED LICENSE PLATE LIGHT	2	\$ 195.00	
37	REAR NO PLATE	S/N	\$ 40.00	\$ 40.00
38	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
39	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
40	STONE CHIP	S/N	\$ 180.00	\$ 180.00
42	SUNDRIES		\$ 500.00	\$ 44.90
TOTAL SPARE PARTS CHARGES			\$ 15,182.00	\$ 9,101.20
TOTAL LABOUR CHARGES			\$ 9,862.00	\$ 7,812.00
GRAND TOTAL			\$ 25,044.00	\$ 16,913.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002194/GVF3N2
Date: 01/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:
Claimant Vehicle No: SJS9229E Insured Vehicle No: PC3354D
Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: SNM20D200676

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS9229E Engine No: CVN041505
Make & Model: AUDI A4, 1.4 (A) Chassis No: WAUZZZF43HA182419
Reg. Date: 22/09/2017 (Man. Year: 2017) Odometer: 30898 km
Colour: White
Engine Capacity: 1395 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,413.00	9,101.20	6,311.80	40.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,862.00	7,462.00	2,400.00	24.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,275.00	16,563.20	8,711.80	34.47
+ GST 7.00/7.00% (S\$)	1,769.25	1,159.42	609.83	34.47
Nett Amount (S\$)	27,044.25	17,722.62	9,321.63	34.47

INSPECTION

Date of Assignment: 07/02/2020
Date Inspected: 10/02/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
Parts:	143	AUDI A4 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS9229E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,079.00 FS	*2,079.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Deformed	210.00 FS	*210.00 FS
4	1		*REAR BUMPER SPOILER	Cut	234.00 FS	*234.00 FS
5	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	78.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Bent	845.00 FS	*844.50 FS
7	2		*REAR BUMPER SEAL	Necessary	26.00 FS	*26.00 FS
8	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	41.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	43.00 FS	*- FS
10	2		*REAR BUMPER GUIDE SECTION-LH/RH	Cut	42.00 FS	*41.40 FS
11	1		*REAR PARKING AID SENSOR-INNER/OUTER (2 Pcs)	Inner Damaged	462.00 FS	*231.00 FS
12	4		*REAR PARKING AID SEAL RING	Necessary	14.00 FS	*13.20 FS
13	1		*REAR BUMPER WIRING SET	Not Necessary	633.00 FS	*- FS
14	1		*BOOT LID CONTROL UNIT	Not Necessary	392.00 FS	*- FS
15	1		*REAR LID	Bent	2,496.00 FS	*2,496.00 FS
16	2		*REAR LID HINGE-LH/RH	Not Necessary	432.00 FS	*- FS
17	1		*REAR LID LOCK	Not Necessary	217.00 FS	*- FS
18	1		*LID LOCK PUSH BUTTON	Not Necessary	510.00 FS	*- FS
19	1		*REAR LID LOCK STRIKER	Not Necessary	31.00 FS	*- FS
20	1		*REAR LID FLAP GASKET	Necessary	193.00 FS	*193.00 FS
21	1		*PACKING ADHESIVE	Necessary	18.00 FS	*17.80 FS
22	1		*AUDI EMBLEM	Necessary	117.00 FS	*116.50 FS
23	1		*A4 INSCRIPTION	Necessary	90.00 FS	*89.70 FS
24	1		*TFSI INSCRIPTION	Necessary	90.00 FS	*89.70 FS
25	1		*REAR CROSS PANEL	Buckled	245.00 FS	*244.50 FS
26	1		*CROSS PANEL REINFORCEMENT	Bent	475.00 FS	*475.00 FS
27	1		*LED TAIL LIGHT-LH INNER	Not Necessary	959.00 FS	*- FS
28	1		*TAIL LIGHT TRIM-LH INNER	Not Necessary	28.00 FS	*- FS
29	1		*LED TAIL LIGHT-RH INNER	Cracked	959.00 FS	*959.00 FS
30	1		*TAIL LIGHT TRIM-RH INNER	Not Necessary	28.00 FS	*- FS
31	1		*LED TAIL LIGHT-RH OUTER	Not Necessary	959.00 FS	*- FS
32	1		*TAIL LIGHT TRIM-RH OUTER	Not Necessary	28.00 FS	*- FS
33	1		*REAR CROSS PANEL TRIM	Deformed	156.00 FS	*156.00 FS
34	1		*LUGGAGE COMPARTMENT FLOOR	Not Necessary	669.00 FS	*- FS
35	1		*REAR LID TRIM PANEL	Not Necessary	310.00 FS	*- FS
36	2		*LED LICENSE PLATE LIGHT	Not Necessary	195.00 FS	*- FS
37	1		*REAR NO PLATE	Bent	40.00 FS	*40.00 FS
38	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
39	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
40	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
41	1		*SUNDRIES	Necessary	500.00 FS	*44.90 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	15,413.00	9,101.20
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AIR AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS AND TAIL LIGHTS	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND REWELD REAR END PANELLING INNER AND OUTER.TO REPAIR SPARE WHEEL HOUSING.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,550.00	3,150.00
5	TO RESPRAY REAR BUMPER,REAR LID,HINGES,SPARE WHEEL HOUSING AND END PANELLING.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	4,000.00	3,000.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			9,862.00	7,462.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >