

INS CASE OWNER:

CC6 / AIG 20002195 / Uds3

LKK:
IDAC:

ASSIGNMENT

Surveyor:

Marcus

DOI:

7/2/2020

Date / Time:

7/2/2020

Registered in Merimen:

7/2/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SLT 4052B Claim No. : _____
 Name of Insured : Muhammad Ridzal Bin Sarwal Policy No. : _____
 Insured Tel No. : _____ HP: _____ Make / Model : _____
 Excess Sec II : \$\$ D.O.A : 6/2/2020 Place of Accident : _____
 Is driver the owner? YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT YES / NO
 Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

GIBB1057X



INSRS:
WSP: city tech
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	GIBB1057X : X ; SLT 4052B : X	
1/2 11:28 am	probe to OL, OI involve 4 vehicle c.c, #1=3rd car. informed TP claim & provide NCD offered. letter sent	
21/2/2020	FILE PPS TO TYPE MANDATE	
15/5/2020	FILE PPS TO LSL TO CLOSE	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$\$ _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: 12/5/2020 Confirm with Winton Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28 If NO or B 28, Ass. Lia : 0%
 Repair Cost: 1w/6M \$S 8025.00 (A URM. C.O.; OI BRO CASE)
 Loss of Rental (LOR): 1w/6M \$S 1070.00 (10 days) x \$100
 Loss of Use (LOU): \$S - (\$ x days)
 Loss of Income (LOI): \$S - (\$ x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

COPY SENT
16/3/2020

GIA/LTA Search \$S 2.00
 Medical: \$S -
 Disbursement: \$S 50.00 (e.g. Tow/ Independent)
 Legal Cost \$S -
 Total: \$S 9147.00 Global Sum \$S:
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: SP
 3) Survey fee: \$320

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 9147.00 Name 1: Stytech Auto Pte Ltd
 Payee 2: (Strike if N.A.) \$S Name 2:
 Payee 3: (Strike if N.A.) \$S Name 3:

A161

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP WS TP RES OD RES EVA INV MV
 To Inspect Vehicle No: GBB1057X
 at Workshop m/s: Slytech
 of: _____
 Insured: SL7405UB
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

 N/S O/S	
N/S	O/S

(Policy Condition) _____
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$ 21k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS C 061H
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: GBB1057X Yr Regn: 7, 08
 Type: M.Car / M.Cycle / Bus / Van / ~~Car~~ / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: Toyota Dyno c.c. 2982
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 248948 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFA735Y303001774
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: C / Rim / STD A/Rim or
 Tyre Size: F: 195 R15 Yokohama
 R: 155 R12
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 5- mm R/Bal. 5/5 mm
 L/Bal. 5- mm L/Bal. 5/5 mm
 D.O.A. 6/2/20 D.O.I. 7/2/20
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S. & M.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 349.52
con 6-7-2023 LRA 610990
net 1000
43- \$7500 (Red \$7699.90 / 512)

Date/Time, File Pass to? : Preli. Report
 1) : Final Report
 Date/Time, File Return to? _____
 2) _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____) _____ \$ + RS _____ \$
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Other
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 TOTAL _____

stytech

Alu

Jigle

Vehicle: GBB1057X

Make & Model: Toyota Dyna

Chassis No: JTFAT35Y303001774

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Wiper Panel			286.40	no /
2	Front Left Side Mirror Garnish			124.70	no X
3	Front Panel			876.10	no /
4	DYNA Plate			62.80	no /
5	Front Left Headlamp		607.50	1156.70	no /
6	Front Grille			506.50	no /
7	Emblem			76.40	no X
8	Number Plate		*	30.00 S.N	set 14 S.N
9	Front Bumper			583.90	no /
10	Front Bumper Reinforcement			177.80	no X
11	Left Door Side Marking Sticker		*	20.00 S.N	no /
12	Left Door Company Sticker		*	20.00 S.N	no / S.N
13	Left Side Gate			1625.80	no /
14	Left Side Gate Fencing railing		*	350.00 S.N	set ✓ 300 S.N
15	Left Side Gate Lock Device latch n/s		184.50	300.40	set /
16	Left Side Gate Aluminum Plate			300.00 S.N	no X
17	Left Side Gate Company Sticker			350.00 S.N	no /
18	Rear Tailgate			1200.80	no /
19	Rear Tailgate Aluminum Plate		*	300.00 S.N	set /
20	Rear Tailgate Company Sticker		*	20.00 S.N	no / 200 S.N
21	70Km & 6 Pax Sticker		*	30.00 S.N	no 20 S.N
22	Rear Floor End Panel		546.10	1077.90	set /
23	Left Rear Floor Panel Side Guide n/s			284.60	set /

24	Left Rear Floor Panel Side Guide Rubber	2	28.50	57.00	MS 7000 KC
25	Rear Taillamp ALS			229.60	✓
26	Rear Taillamp Panel ALS		78.50	145.70	✓
27	Reverse Sencer 1 set		↓	200.00 SW	one 200.00 W
28	Spare Tyre Lock Device			366.60	PM X
29	Rear Canopy		(25)	600.00 SW	R X
				1169.90	
	Labour				
1	Anti Rust Proof			\$ 100.00	80
2	Check Wiring			\$ 100.00	30
3	Panel Beating			\$ 1,500.00	1200
4	Paint Work			\$ 1,800.00	1500
5				3500.00	

Not Approved
 d/h/h
 2/5/20
 7500
 8/2/20
 who? photo attached.

P-7100.60
 25%
 P 5325.45
 S.N-1250
 L-2810
 9389.48

LHK Auto Consultants hence notify the Repairer of the following:

- To recovery cost/other spray painting
- To not pay damaged parts during survey
- Parts prices are subject to confirmation
- This policy survey is on a "Without Prejudice" basis
- No illegal modifications to be allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	061H
Vehicle Details	
Vehicle No.:	GBB1057X
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1KD1807511
Chassis No.:	JTFAT35Y303001774
Maximum Power Output:	-
Open Market Value:	\$24,243.00
Original Registration Date:	07 Jul 2008
First Registration Date:	07 Jul 2008
Transfer Count:	3
Actual ARF Paid:	\$1,213.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$16,100.00
COE Rebate Amount:	\$10,990.00
Total Rebate Amount:	\$10,990.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 07 Feb 2020

OK

[New Cars](#)[Used Cars](#)[Rental Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[Forum](#)

Google Pixel 4 XL

Meet the new Pixel 4 XL, built around the helpful Google software you know & love.

dyna

Price Range

Depreciation

> 10 year(s)

Vehicle Type

[Home](#) » [Used Cars](#) » [Think One Automobile & Trading](#) » [Toyota Dyna 150 3.0M \(COE till 08/2023\)](#)

Toyota Dyna 150 3.0M (COE till 08/2023)

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Think One Automobile**

Price	\$20,800	Lifespan	04-Aug-2028
Depreciation	\$5,960 /yr	Reg Date	05-Aug-2008 (3yrs 5mths 28days COE left)
Mileage	N.A.	Manufactured	2008
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$10,878 as of today (change)	OMV	\$24,243
COE	\$15,582	ARF	\$1,213
Engine Cap	2,982 cc	No. of Owners	4
Curb Weight	1,680 kg		
Type of Vehicle	Truck		

Features

[View specs of the Toyota Dyna 150 \(2014\)](#)

Description

Selling Cheap! Refrigerator Truck 2008 Toyota Dyna 150 With Coe Till 8/2023 High Trade In And In House Loan Available! Call Now To Get The Opportunity Today!

Category

COE Car, Premium Ad Car

Status

Available

Resourc

[Compare](#)[Free](#)https://www.sgcarMart.com/used_cars/info.php?ID=874996&DL=2357[Shortlist](#)[Compare](#)[Report Error](#)[More Action](#)

Seller Information

Think One Automobile & T

132 vehicles for sale. 52 sold in past 30 days

20 Ubi Road 4
Think One Building
Tel: 65553300
[Search cars nearby](#)

Sheila 93%
Wong 96%
Liza 97%



dyna Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » Bell Auto Pte Ltd » Toyota Dyna 150 3.0M (COE till 07/2023)

Toyota Dyna 150 3.0M (COE till 07/2023)

Overview

Financial

Accessories

Similar

Research

Photos

Map



WHOLESALE
EXPERIENCE AT YOUR
CONVENIENCE

Price **\$23,800**

Depreciation **\$6,840 /yr**

Lifespan 07-Aug-2028

Reg Date 08-Aug-2008
(3yrs 5mths 24days COE left)

Mileage N.A.

Manufactured 2008

Road Tax N.A.

Transmission Manual

Dereg Value **\$11,204 as of today (change)**

OMV **\$24,243**

COE **\$16,100**

ARF **\$1,213**

Engine Cap 2,982 cc

No. of Owners **2**

Curb Weight **2,000 kg**

Type of Vehicle Truck



Shortlist

Compare

Report Error

More Action

Seller Information

Bell Auto Pte Ltd

103 vehicles for sale. 72 sold in past 3

8 Tuas Avenue 18 (Level 5 & 7)

Tel: 67457076

Search cars nearby

Eric Lim

910

Features

View specs of the Toyota Dyna 150 (2014)

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Compare

- Free

Market value of your existing car for free. Get started

https://www.sgcarMart.com/used_cars/info.php?ID=878572&DL=3431

Vehicle:

GBB1057X

Make & Model:

Toyota Dyna

Chassis No:

JTFAT35Y303001774

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Wiper Panel				OK / ✓
2	Front Left Side Mirror Garnish				?
3	Front Panel				OK / ✓
4	DYNA Plate				OK / ✓
5	Front Left Headlamp				?
6	Front Grille				OK / ✓
7	Emblem				OK X
8	Number Plate				Set / 14
9	Front Bumper				OK / ✓
10	Front Bumper Reinforcement				?
11	Left Door Side Marking Sticker				OK / ✓
12	Left Door Company Sticker				OK / ✓
13	Left Side				OK / ✓
14	Left Side Gate Fencing <i>rolling</i>				Set ✓
15	Left Side Gate Lock Device <i>latch</i> <i>1/5</i>				Set / ✓
16	Left Side Gate Aluminum Plate				OK X
17	Left Side Gate Company Sticker				OK
18	Rear Tailgate				Body OK / ✓
19	Rear Tailgate Aluminum Plate				Set / ✓
20	Rear Tailgate Company Sticker				OK / ✓
21	70Km & 6 Pax Sticker				OK 20 S. ✓
22	Rear Floor End Panel				Set / ✓
23	Left Rear Floor Panel Side Guide <i>1/5</i>				Set / ✓

24	Left Rear Floor Panel Side Guide Rubber	2			Mc 70114c
25	Rear Taillamp				atc one 1pc
26	Rear Taillamp Panel				atc 2nd 1pc
27	Reverse Sencer				one 2005.1
28	Spare Tyre Lock Device				PMX
29	Rear Canopy				2 x
	Labour				
1	Anti Rust Proof			\$ 100.00	80
2	Check Wiring			\$ 100.00	30
3	Panel Beating			\$ 1,500.00	1200
4	Paint Work			\$ 1,800.00	1500
5					

LIXX Auto Components notice notify
 the Repairer of the following:
 • To receive notification from insurer
 • To receive damaged goods being received
 • Parts prices are subject to variation
 • This policy is on a "Without Insurance" basis
 • No third party liability is allowed
 • Supplementary (if any) must be requested and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Not Authorised
 LIXX
 2/5/20
 8 days.
 7/2/20
 who photo the repair.

View Received Message

This mail is associated with :

***GBB1057X (8966541079SG)**
[SLT4052B]
 TP
 UNITED MACHINERY & TRADING PTE. LTD.
 Feb 6 2020 6:00PM
 [MUHAMMAD RIDZAL BIN SARWAL]

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/03/2020 17:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9147.00) - GBB1057X - Claim Handler: Lee, Ming-Yao

Approved:9147.00:Please fill up workshop detail

DOCUMENTS SUMMARY
 There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Feb 2020 Edit Reg		07 Feb 2020 00:00 Edit Adj Rpt	S\$7,500.00 Edit Estimates	S\$7,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MUHAMMAD RIDZAL BIN SARWAL, ID: S79112022								
Main Claimant:	UNITED MACHINERY & TRADING PTE. LTD.								
Vehicle Reg. No.:	GBB1057X	Date of Loss:	06/02/2020 18:00 - :59 [138 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8966541079SG	Policy/Cover Note No.:	1700076233 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLT4052B	Policy No. (Claimant):							
		Excess:							
Repairer:	Stytech Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 64448125								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (11/03/2020): Alert - Adj Mandate Approved (S\$9147.00) - GBB1057X - Claim Handler: Lee, Ming-Y... AIG_SG_EXPRESS (11/03/2020): Alert - Adj Mandate Approved (S\$9147.00) - GBB1057X - Claim Handler: Lee, Ming-Y... AIG_SG (10/02/2020): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBB1057X (8966541079SG)
 [SLT4052B]
 TP
 UNITED MACHINERY & TRADING PTE. LTD.
 Feb 6 2020 6:00PM
 [MUHAMMAD RIDZAL BIN SARWAL]
 Stytech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	07/02/20 17:40	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	07/02/20 17:40	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
4	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
5	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
6	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
7	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
8	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
9	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
10	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
11	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
12	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
13	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
14	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
15	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
16	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
17	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
18	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
19	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
20	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
21	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
22	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
23	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
24	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
25	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
26	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
27	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
28	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
29	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
30	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
31	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
32	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
33	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
34	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
35	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
36	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
37	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
38	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
39	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	
40	07/02/20 17:41	General View							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
59	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
60	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
61	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
62	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
63	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
64	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
65	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
66	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
67	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
68	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
70	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
71	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
72	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
73	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
74	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
75	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
76	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
77	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
78	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
79	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
80	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
81	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
82	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
83	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
84	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
85	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
86	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
87	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
88	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
89	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
90	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
91	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
92	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
93	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
94	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
95	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
97	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
98	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
99	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
100	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
101	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
102	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
103	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
104	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
105	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
106	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
107	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
108	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
109	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
110	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
111	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
112	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
113	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
114	07/02/20 17:41	General View	 Load JPG	<input checked="" type="checkbox"/>
115	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	17/02/20 08:19	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
134	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
135	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
136	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
137	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
138	17/02/20 08:20	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/02/20 16:53	TP ESTIMATE-MARKED	 Load PDF	
2	10/02/20 16:53	TP GIA REPORT	 Load PDF	
3	11/02/20 11:40	LETTER TO OI	 Load PDF	
4	24/02/20 15:42	LOD	 Load PDF	
5	24/02/20 15:42	RENTAL	 Load PDF	
6	24/02/20 15:42	GIA SEARCH FEE	 Load PDF	
7	24/02/20 15:59	TOWING FEE	 Load PDF	
8	17/03/20 09:21	WORKSHOP INVOICE	 Load PDF	
9	17/03/20 09:21	AUTHORISATION TO ACT FORM	 Load PDF	
10	17/03/20 09:21	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/02/20 14:44	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLT4052B (Insd veh)	Model:	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M)
	GBB1057X (TP veh)		
Date of Accident:	06/02/2020		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		16,263.89
Final Repair Cost	: \$		8,025.00
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		1,070.00 10 days
LTA / GIA Search Fee	: \$		2.00
Others: Towing Fee	: \$		50.00
	: \$		
Final Settlement Sum	: \$		9,147.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Stytech Auto Pte Ltd	: \$	9,147.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

17 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002195/UDS3Q2

Date: 17/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700076233
Claimant
Vehicle No : GBB1057X **Insured Vehicle No :** SLT4052B
Date of Loss: 06/02/2020 **Nature of Claim:** TP **Claim No:** 8966541079SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB1057X
Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) **Engine No:** 1KD1807511
Reg. Date: 07/07/2008 (Man. Year: 2008) **Chassis No:** JTFAT35Y303001774
Colour: White **Odometer:** 248948 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 195 R15 **Rear Tyre Size:** 155 R12 (D)
Front Left Side: Yokohama 5 mm **Rear Left Side:** Yokohama 5/5 mm
Front Right Side: Yokohama 5 mm **Rear Right Side:** Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,699.90	6,579.45	5,120.45	43.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	2,810.00	690.00	19.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,199.90	9,389.45	5,810.45	38.23
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	15,199.90	7,500.00	7,699.90	50.66
+ GST 7.00/7.00% (S\$)	1,063.99	525.00	538.99	50.66
Nett Amount (S\$)	16,263.89	8,025.00	8,238.89	50.66
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		9,147.00		

INSPECTION

Date of Assignment: 07/02/2020
Date Inspected: 07/02/2020 **Inspected At:**
Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WIPER PANEL	Dented	286.40 F	*286.40 FL
2	1		*FRONT LEFT SIDE MIRROR GARNISH	Not Necessary	124.90 F	*- FL
3	1		*FRONT PANEL	Dented / Bent	876.10 F	*876.10 FL
4	1		*DYNA PLATE	Necessary	62.80 F	*62.80 FL
5	1		*FRONT LEFT HEADLAMP	Cracked	1,156.70 F	*607.50 FL
6	1		*FRONT GRILLE	Cracked	506.50 F	*506.50 FL
7	1		*EMBLEM	Not Necessary	76.40 F	*- FL
8	1		*NUMBER PLATE	Bent	30.00 FS	*14.00 FS
9	1		*FRONT BUMPER	Dented / Buckled	583.90 F	*583.90 FL
10	1		*FRONT BUMPER REINFORCEMENT	Repair	179.80 F	*- FL
11	1		*LEFT DOOR SIDE MARKING STICKER	Necessary	20.00 FS	*20.00 FS
12	1		*LEFT DOOR COMPANY STICKER	Necessary	200.00 FS	*200.00 FS
13	1		*LEFT SIDE GATE	Dented / Bent	1,625.80 F	*1,625.80 FL
14	1		*LEFT SIDE GATE FENCING RAILLING	Bent	350.00 FS	*300.00 FS
15	1		*LEFT SIDE GATE LOCK LATCH N/S	Bent	306.40 F	*184.50 FL
16	1		*LEFT SIDE GATE ALUMINIUM PLATE	Not Necessary	300.00 FS	*- FS
17	1		*LEFT SIDE GATE COMPANY STICKER	Not Necessary	250.00 FS	*- FS
18	1		*REAR TAILGATE	Badly Dented	1,200.80 F	*1,200.80 FL
19	1		*REAR TAILGATE ALUMINIUM PLATE	Bent	300.00 FS	*300.00 FS
20	1		*REAR TAILGATE COMPANY STICKER	Necessary	250.00 FS	*200.00 FS
21	1		*70KM & 6 PAX STICKER	Necessary	30.00 FS	*20.00 FS
22	1		*REAR FLOOR END PANEL	Bent	1,079.90 F	*545.10 FL
23	1		*LEFT REAR FLOOR PANEL SIDE GUIDE N/S	Bent	284.60 F	*284.60 FL
24	1		*LEFT REAR FLOOR PANEL SIDE GUIDE RUBBER	N/S Torn	57.00 F	*28.50 FL
25	1		*REAR TAILLAMP N/S	Damaged	229.60 F	*229.60 FL
26	1		*REAR TAILLAMP PANEL N/S	Damaged	165.70 F	*78.50 FL
27	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
28	1		*SPARE TYRE LOCK DEVICE	Not Necessary	366.60 F	*- FL
29	1		*REAR CANOPY	Repair	600.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	11,699.90	8,354.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,775.15
Total Parts (\$\$)	11,699.90	6,579.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI RUST PROOF	New	100.00	80.00
2	CHECK WIRING	New	100.00	30.00
3	PANEL BEATING	New	1,500.00	1,200.00
4	PAINT WORK	New	1,800.00	1,500.00
Gross Labour Cost (S\$)			3,500.00	2,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >