

Vehicle:

GBB1057X

Make &amp; Model:

Toyota Dyna

Chassis No:

JTFAT35Y303001774

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Wiper Panel				✓
2	Front Left Side Mirror Garnish				?
3	Front Panel				✓
4	DYNA Plate				✓
5	Front Left Headlamp				?
6	Front Grille				✓
7	Emblem				X
8	Number Plate				set 14
9	Front Bumper				✓
10	Front Bumper Reinforcement				?
11	Left Door Side Marking Sticker				✓
12	Left Door Company Sticker				✓
13	Left Side				✓
14	Left Side Gate Fencing <i>railling</i>				set ✓
15	Left Side Gate Lock <del>Device</del> <i>latch n/s</i>				set ✓
16	Left Side Gate Aluminum Plate				X
17	Left Side Gate Company Sticker				✓
18	Rear Tailgate				Body ✓
19	Rear Tailgate Aluminum Plate				set ✓
20	Rear Tailgate Company Sticker				✓
21	70Km & 6 Pax Sticker				✓ 205 ✓
22	Rear Floor End Panel				set ✓
23	Left Rear Floor Panel Side Guide <i>n/s</i>				set ✓

24	Left Rear Floor Panel Side Guide Rubber	2				MS 7000 pc
25	Rear Taillamp					MS 1000 1pc
26	Rear Taillamp Panel					MS 1000 1pc
27	Reverse Sencer					one 2005.0
28	Spare Tyre Lock Device					AMX
29	Rear Canopy					2 x
	<b>Labour</b>					
1	Anti Rust Proof			\$ 100.00		80
2	Check Wiring			\$ 100.00		30
3	Panel Beating			\$ 1,500.00		1200
4	Paint Work			\$ 1,800.00		1500
5						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Not Authorised  
LKK  
2/5/20  
8 days.  
7/2/20  
Who photo attached.