

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLQ 2624 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	500.00
3	To respray front bumper and lhs front fender.	\$ 2,000.00	1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	✓
SUB TOTAL LABOUR CHARGES		: <u>\$ 3,952.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 2624 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	\$ 2,010.00	X
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 269.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 198.00	+
4	FRONT BUMPER AIR GUIDE - LH <i>new</i>	\$ 59.00	+
5	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 185.00	+
6	RADIATOR GRILLE <i>new</i>	\$ 1,084.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH ?	\$ 127.00	+
8	FRONT BUMPER GUIDE SECTION - LH } <i>new</i>	\$ 34.00	+
9	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	+
10	FRONT BUMPER CARRIER ? <i>new</i>	\$ 757.00	+
11	LOCK CARRIER BRACKET	\$ 129.00	+
12	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 \$ 54.00	+
13	HORN - LH HIGH TONE <i>new</i>	\$ 38.00	+
14	LIFT CYLINDER - LH ? <i>nn</i>	\$ 198.00	X
15	HEADLIGHT CORRUGATED PIPE <i>new</i>	\$ 88.00	+
16	LED HEADLIGHT - LH <i>new</i>	\$ 7,321.00	+
17	FRONT NO PLATE <i>new</i>	S/N \$ 40.00	+
18	SUNDRIES ? <i>nec</i>	\$ 300.00	✓
TOTAL SPARE PARTS		: \$ 13,008.00	
TOTAL LABOUR CHARGES		: \$ 3,952.00	
GRAND TOTAL		: \$ 16,960.00	

47.52

All charges are not inclusive of GST.


Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 12/02/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days



Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant